

Ergonomics Evaluation Report

Posture Analysis

- Neck Flexion: Red risk (Angle: 164.0836588590314°)
- Shoulder Elevation: Red risk (Angle: 33.571107387542725°)
- Elbow Angle: Red risk (Angle: 139.13964551984202°)
- Wrist Deviation: Red risk (Angle: 158.65536147038247°)
- Pelvic Tilt: Red risk (Angle: 27.9567289352417°)

Workstation Analysis

Risk Summary

Severe ergonomic risks detected: excessive neck flexion (neck strain), elevated shoulders (shoulder and upper back strain), overextended elbows (arm fatigue), significant wrist deviation (wrist strain), and improper pelvic tilt (lower back strain).

Exercise Recommendations

Neck retraction: Gently pull your head straight back, keeping your chin tucked, to align your ears over your shoulders. Hold for 5 seconds, repeat 10 times.

Shoulder rolls: Roll your shoulders up, back, and down in a circular motion. Repeat 10–15 times to relieve tension.


Elbow flexor stretch: Extend your arm in front of you, palm up, and gently pull back on your fingers with your other hand. Hold for 20 seconds each side.

Wrist stretches: Extend your arm with palm facing down, gently pull back on your fingers with your other hand. Hold for 15–20 seconds per wrist.

Seated pelvic tilts: While sitting, gently rock your pelvis forward and backward to find a neutral, comfortable position. Repeat 10–15 times.

Final Advice

Your current posture presents high ergonomic risks according to ISO 9241-5. Immediate corrections to both posture and workstation setup are necessary to prevent musculoskeletal disorders. Implement the recommended adjustments and exercises, and reassess your workstation regularly to maintain optimal ergonomics.



Annotated posture analysis from your uploaded photo