
DI2FK-02

Door lock motor circuit

WIRING DIAGRAM



INSPECTION PROCEDURE

1 | Check[door[lock[motor.[See[page[BE-148]]

NG

Replace the door lock motor.

OK

2 Check wireharness and connector between door lock motor and rear right door ECU.

NG

Repair or replace wireharness or connector.

OK

Proceed to next circuit inspection shown on problem symptoms table. (See page DI-616)