DI1AU-04


DTC	B2797/99	Communication Malfunction No.1
-----	----------	--------------------------------

## **CIRCUIT DESCRIPTION**

This code is detected when although the communication has been performed normally, an error occurs. (Example. Some noise is included in communication line.)


DTC No.	DTC Detecting Condition	Trouble Area
B2797/99	Communication error	Wire Harness Transponder Key Amplifier
B2797/99	Communication end	Engine and ECT ECU

# **WIRING DIAGRAM**



## **INSPECTION PROCEDURE**

1 Noise check



### **PREPARATION:**

Insert the already registered master key in the key cylinder.

#### CHECK:

Using an oscilloscope or LEXUS hand-held tester, check that noise is included in the signals sent to the CODE terminal of ECM.

## Ο<u>Κ:</u>

No noise is detected.

NG

Try to find the cause of the noise and remove it.

ОК

2 Does the system operate normally after replacement of transponder key amplifier?

Yes

Replace transponder key amplifier.

No

Replace ECU.