DI2BB-02

DTC	B1261 / 61	Engine and ECT ECU communication stop
-----	------------	---------------------------------------

CIRCUIT DESCRIPTION

This DTC is output when communication stops between Engine and ECT ECU and Body No.1 ECU.

DTC No.	DTC Detecting Condition	Trouble Area
B1261/61	No communication from Engine and ECT ECU more than 10	• Engine and ECT ECU
	seconds.	Wireharness

WIRING DIAGRAM

SeepageDI-820

INSPECTION PROCEDURE

1 Check Engine and ECT ECU.

CHECK:

Check that the engine starts normally.


HINT:

With this inspection, Engine and ECT ECU CPU can be diagnosed if it works normally or not.

NG Replace the Engine and ECT ECU.

OK

2 Check wireharness



PREPARATION:

Disconnect connector "B5" of body No.1 ECU, "E7"(or "E5") of Engine and ECT ECU and "A13" of A/C ECU.

CHECK:

- (a) Check continuity between terminals MPX1 of body No.1 ECU and MPX1 of Engine and ECT ECU.
- (b) Check continuity between terminals MPX2 of Engine and ECT ECU and MPX+ of A/C ECU.

OK:

There is a continuity in wireharness of both (a) and (b), or either (a) or (b).

HINT:

If there is OPEN in wireharness of either (a) or (b), please repair it

NG

Repair or replace wireharness.

OK

Replace the Engine and ECT ECU.