



The 24.6 mm 2part mismatch is a missing valley tie, not a parameterisation limit

(a) FDM force density q per edge
the target was form-found with a valley tie



(b) FEM baseline – target
no cable in the model: the crease never forms



(c) the stiff line and the mismatch
are the same line

