


Direction 1 | original trial 16


T, channel 7 | final 500 ms before GO | $m = 3$ | $\tau = 16$ ms | 468 points

1-torus: planar band



Normalized 3D set error: 0.2092
Native coverage: 0.902 | nfev: 40
Flags: near optimizer bound

2-torus: donut volume



Normalized 3D set error: 0.0016
Native coverage: 0.874 | nfev: 29
Flags: collapsed hole; active optimizer bound; near optimizer bound

Same observed cloud and scale. Band versus solid-tube containment; not a topology test.
Tube overlay is a parametric sweep, not a volume boundary; thick-tube sweeps can self-intersect.