


Direction 3 | original trial 14


T, channel 7 | final 500 ms before GO | $m = 3$ | $\tau = 16$ ms | 468 points

1-torus: planar band



Normalized 3D set error: 0.2656
Native coverage: 0.910 | nfev: 34
Flags: none

2-torus: donut volume



Normalized 3D set error: 0.0011
Native coverage: 0.897 | nfev: 25
Flags: collapsed hole; near optimizer bound

Same observed cloud and scale. Band versus solid-tube containment; not a topology test.
Tube overlay is a parametric sweep, not a volume boundary; thick-tube sweeps can self-intersect.