

## Full

# **TEST REPORT**

# No. I15D00083-BT

## **For**

Client: Suzhou Mobilead Eletronic Technology

Co.,Ltd

**Production: WCDMA wireless data terminal** 

Model Name: Mobilead M80

FCC ID: 2AFBBM80

Hardware Version: V01

Software Version: M80.01.01.20150526

Issued date: 2015-07-30

#### Note:

The test results in this test report relate only to the devices specified in this report. This report shall not be reproduced except in full without the written approval of ECIT Shanghai.

### **Test Laboratory:**

ECIT Shanghai, East China Institute of Telecommunications

Add: 7-8F, G Area, No.668, Beijing East Road, Huangpu District, Shanghai, P. R. China

Tel: (+86)-021-63843300, E-Mail: welcome@ecit.org.cn



## **Revision Version**

Report No.: I15D00083-BT

Report Number	Revision	Date	Memo
I15D00083-BT	00	2015-07-30	Initial creation of test report

East China Institute of Telecommunications Page Number : 2 of 73 TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



## Report No.: I15D00083-BT

Page Number : 3 of 73 Report Issued Date : Jul, 30, 2015

## **CONTENTS**

1.	TEST LABORATORY 5
1.1.	TESTING LOCATION5
1.2.	TESTING ENVIRONMENT5
1.3.	PROJECT DATA5
1.4.	SIGNATURE5
2.	CLIENT INFORMATION6
2.1.	APPLICANT INFORMATION6
2.2.	MANUFACTURER INFORMATION6
3.	EQUIPMENT UNDER TEST (EUT) AND ANCILLARY EQUIPMENT (AE)
3.1.	ABOUT EUT7
3.2.	INTERNAL IDENTIFICATION OF EUT USED DURING THE TEST7
3.3.	INTERNAL IDENTIFICATION OF AE USED DURING THE TEST7
4.	REFERENCE DOCUMENTS8
4.1.	REFERENCE DOCUMENTS FOR TESTING 8
5.	SUMMARY OF TEST RESULTS9
5.1.	NOTES10
5.2.	STATEMENTS10
6.	TEST RESULT 11
6.1.	PEAK OUTPUT POWER-CONDUCTED 11
6.2.	FREQUENCY BAND EDGES-CONDUCTED16
6.3.	CONDUCTED EMISSION23
6.4.	RADIATED EMISSION
6.5.	TIME OF OCCUPANCY (DWELL TIME)47
6.6.	20DB BANDWIDTH58
6.7.	CARRIER FREQUENCY SEPARATION63



ECI	T	RF Test Report	Report No.: I15D00083-B	šΤ
6.8.	NUMB	ER OF HOPPING CHANNELS	6	6
7.	TEST E	EQUIPMENTS AND ANCILLARIES USED FOR	TESTS7	'1
8.	TEST E	ENVIRONMENT	7	'2
ΔNNFX	΄Δ Ι	DEVIATIONS FROM PRESCRIBED TEST MET	HODS 7	<b>'</b> 3

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 4 of 73 Report Issued Date : Jul, 30, 2015



## 1. Test Laboratory

## 1.1. Testing Location

Company Name:	ECIT Shanghai, East China Institute of Telecommunications	
Address:	7-8F, G Area, No. 668, Beijing East Road, Huangpu District,	
	Shanghai, P. R. China	
Postal Code:	200001	
Telephone:	(+86)-021-63843300	
Fax:	(+86)-021-63843301	

## 1.2. Testing Environment

Normal Temperature:	15-35℃
Extreme Temperature:	-10/+55℃
Relative Humidity:	20-75%

### 1.3. Project data

Project Leader:	Lan Yaqin
Testing Start Date:	2015-06-08
Testing End Date:	2015-07-04

## 1.4. Signature

Wang Daming

(Prepared this test report)

Liu Jianquan

(Reviewed this test report)

Report No.: I15D00083-BT

Zheng Zhongbin
Director of the laboratory
(Approved this test report)

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 5 of 73 Report Issued Date : Jul, 30, 2015



## **RF Test Report** Report No.: I15D00083-BT

### 2. Client Information

## 2.1. Applicant Information

Company Name: Suzhou Mobilead Eletronic Technology Co.,Ltd

Room 1503, building G1, No.88, Dongchang Road, SIP, Suzhou,

Address: PRC

Telephone: 18014912125

Postcode: 215000

### 2.2. Manufacturer Information

Company Name: MOBIWIRE MOBILES (NINGBO) CO.,LTD

Address: No.999, Dacheng East Road, Fenghua City, Zhejiang

Telephone: 0574 59550618

Postcode: 315500

East China Institute of Telecommunications Page Number : 6 of 73
TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



## 3. Equipment Under Test (EUT) and Ancillary Equipment (AE)

Report No.: I15D00083-BT

### 3.1. About EUT

EUT Description	WCDMA wireless data terminal
Model name	Mobilead M80
UMTS Frequency Band	WCDMA BandII and V
GSM Frequency Band	GSM850/900/1800/1900
WLAN Frequency	2412MHz-2472MHz
WLAN Channel	Channel1-Channel13
WLAN type of modulation	802.11b:DSSS
	802.11g/n: OFDM
Extreme Temperature	-10/+55℃
Nominal Voltage	3.9V
Extreme High Voltage	4.35V
Extreme Low Voltage	3.6V

Note: Photographs of EUT are shown in ANNEX A of this test report.

### 3.2. Internal Identification of EUT used during the test

EUT ID*	SN or IMEI	HW Version	SW Version	Date of receipt
N01	867762020000193	V01	M80.01.01.2015	2015-06-09
			0526	

<sup>\*</sup>EUT ID: is used to identify the test sample in the lab internally.

### 3.3. Internal Identification of AE used during the test

AE ID*	Description	SN
AE1	RF cable	
AE2		

<sup>\*</sup>AE ID: is used to identify the test sample in the lab internally.

East China Institute of Telecommunications Page Number : 7 of 73
TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



## 4. Reference Documents

## 4.1. Reference Documents for testing

The following documents listed in this section are referred for testing.

Reference	Title	Version
FCC Part15	FCC CFR 47, Part 15, Subpart C: 15.205 Restricted bands of operation; 15.209 Radiated emission limits, general requirements; 15.247 Operation within the bands 902-928MHz, 2400-2483.5MHz, and 5725-5850MHz.	Oct,2009 Edition
ANSI C63.10	American National Standard of Procedures for Compliance Testing of Unlicensed Wireless Devices	2013

Report No.: I15D00083-BT

East China Institute of Telecommunications Page Number : 8 of 73
TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



## 5. Summary of Test Results

A brief summary of the tests carried out is shown as following.

Measurement Items	Sub-clause of Part15C	Sub-claus e of IC	Verdict
Maximum Peak Output Power	15.247(b)	1	Р
Peak Power Spectral Density	15.247(d)	1	NA
20dB Occupied Bandwidth	15.247(a)	/	Р
Band Edges Compliance	15.247(b)	/	Р
Transmitter Spurious Emission-Conducted	15.247	/	Р
Transmitter Spurious Emission-Radiated	15.247,15.209,	/	Р
AC Powerline Conducted Emission	15.107,15.207	1	Р

Report No.: I15D00083-BT

Please refer to part 5 for detail.

The measurements are according to and ANSI C63.10.

Terms used in Verdict column

Р	Pass, the EUT complies with the essential requirements in the standard.
NP	Not Perform, the test was not performed by ECIT.
NA	Not Applicable, the test was not applicable.
F	Fail, the EUT does not comply with the essential requirements in the standard.

### **Test Conditions**

Tnom	Normal Temperature
Tmin	Low Temperature
Tmax	High Temperature
Vnom	Normal Voltage
Vmin	Low Voltage
Vmax	High Voltage
Hnom	Norm Humidity
Anom	Norm Air Pressure

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 9 of 73 Report Issued Date : Jul, 30, 2015



For this report, all the test case listed above are tested under Normal Temperature and Normal Voltage, and also under norm humidity, the specific conditions as following:

Report No.: I15D00083-BT

: 10 of 73

Temperature	Tnom	<b>22</b> °C
Voltage	Vnom	3.7V
Humidity	Hnom	32%
Air Pressure	Anom	1010hPa

#### Note:

- a. All the test data for each data were verified, but only the worst case was reported.
- b.The GFSK,  $\pi/4$  DQPSK and 8DPSK were set in DH1 for GFSK, 2-DH1 for  $\pi/4$  DQPSK, 3-DH1 for 8DPSK.
- c.The DC and low frequency voltages' measurement uncertainty is ±2%.

#### 5.1. Notes

All reported tests were carried out on a sample equipment to demonstrate limited compliance with section 3.

The test results of this test report relate exclusively to the item(s) tested as specified in section 5.

The following deviation from, additions to, or exclusions from the test specifications have been made. See section 3.

#### 5.2. Statements

The product name Mobilead M80, supporting GSM/GPRS/WCDMA/HSDPA/HSUPA/HSPA+/WLAN/BTBLE//GPS, manufactured by MOBIWIRE MOBILES (NINGBO) CO.,LTD is a new product for testing.

ECIT has verified that the compliance of the tested device specified in section 5 of this test report is successfully evaluated according to the procedure and test methods as defined in type certification requirement listed in section 5 of this test report.

### 6. Test result

#### 6.1. **Peak Output Power-Conducted**

#### **6.1.1 Measurement Limit**

Standard	Limit (dBm)
FCC Part 15.247(b)(1)	< 30

Report No.: I15D00083-BT

: 11 of 73

### 6.1.2 Test Condition:

Hopping Mode	RBW	VBW	Span	Sweeptime
Hopping OFF	3MHz	10MHz	9MHz	Auto

### 6.1.3 Test procedure

The measurement is according to ANSI C63.10 clause 7.8.5.

- 1. The output power of EUT was connected to the spectrum analyzer and CBT32 by cable and divide. The path loss was compensated to the results for each measurement.
- 2. Enable EUT transmitter maximum power continuously.
- 3. Measure the conducted output power and record the results it.

### 6.1.4 Measurement Results:

#### For GFSK

Channel	Ch0 2402 MHz	Ch39 2441 MHz	CH78 2480 MHz	Conclusion
Peak Conducted	2.634	2.848	2.932	Р
Output Power (dBm)	Fig.1	Fig.2	Fig.3	F

#### For π/4 DQPSK

Channel	Ch0 2402 MHz	Ch39 2441 MHz	CH78 2480 MHz	Conclusion
Peak Conducted	1.947	2.161	2,184	P
Output Power (dBm)	Fig.4	Fig.5	Fig.6	Г

#### For 8DPSK

Channal	Ch0 2402	Ch39 2441	CH78 2480	Conclusion
Channel	MHz	MHz	MHz	Conclusion

East China Institute of Telecommunications Page Number TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



Peak Conducted	2.016	2.199	2,191	D
Output Power (dBm)	Fig.7	Fig.8	Fig.9	r

Report No.: I15D00083-BT

Conclusion: PASS
Test graphs an below



Date: 10.JUN.2015 19:37:40

Fig.1 Peak Conducted Output Power CH0, DH1




Date: 10.JUN.2015 19:37:52

Fig.2 Peak Conducted Output Power CH39, DH1

Page Number


: 12 of 73



Report No.: I15D00083-BT

Date: 10.JUN.2015 19:38:05

Fig.3 Peak Conducted Output Power CH78, DH1




Date: 10.JUN.2015 19:38:17

Fig.4 Peak Conducted Output Power CH0, 2DH1

Page Number


: 13 of 73



Report No.: I15D00083-BT

Date: 10.JUN.2015 19:38:29

Fig.5 Peak Conducted Output Power CH39, 2DH1




Date: 10.JUN.2015 19:38:42

Fig.6 Peak Conducted Output Power CH78, 2DH1

Page Number

: 14 of 73



Report No.: I15D00083-BT

Date: 10.JUN.2015 19:38:54

Fig.7 Peak Conducted Output Power CH0, 3DH1




Date: 10.JUN.2015 19:39:06

Fig.8 Peak Conducted Output Power CH39, 3DH1

Page Number

: 15 of 73





Date: 10.JUN.2015 19:39:18

Fig.9 Peak Conducted Output Power CH78, 3DH1

### 6.2. Frequency Band Edges-Conducted

#### 6.2.1 Measurement Limit:

Standard	Limited(dBc)
FCC 47 CFR Part 15.247(d)	>20

### **6.2.2 Test procedure**

The measurement is according to ANSI C63.10 clause 7.8.6.

- 1. Connect the EUT to spectrum analyzer.
- 2. Set RBW=100KHz, VBW=300KHz, span more than 1.5 times channel bandwidth (2MHz).
- 3. Detector =peak, sweep time=auto couple, trace mode=max hold.
- 4. Allow sweep to continue until the trace stabilizes.

#### 6.2.3 Measurement results

### For GFSK

Channel	Hopping	Band Edge Power (dBc)	Conclusion
	Hopping OFF	Fig.10	Р
0	Hopping ON	Fig.11	Р
78	Hopping OFF	Fig.12	Р

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 16 of 73 Report Issued Date : Jul, 30, 2015

Report No.: I15D00083-BT



<b>=</b>		
Hopping ON	Fig.13	Р

Report No.: I15D00083-BT

### For $\pi/4$ DQPSK

Channel	Hopping	Band Edge Power (dBc)	Conclusion
0	Hopping OFF	Fig.14	Р
0	Hopping ON	Fig.15	Р
78	Hopping OFF	Fig.16	Р
	Hopping ON	Fig.17	Р

### For 8DPSK

Channel	Hopping	Band Edge Power (dBc)	Conclusion
0	Hopping OFF	Fig.18	Р
	Hopping ON	Fig.19	Р
78	Hopping OFF	Fig.20	Р
	Hopping ON	Fig.21	Р

Conclusion: PASS
Test graphs an below





Fig.10 Frequency Band Edge: GFSK, Ch0, Hopping OFF

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301


Date: 10.JUN.2015 19:40:25

Page Number : 17 of 73 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 19:42:29

Fig.11 Frequency Band Edge: GFSK, Ch0, Hopping ON



Date: 10.JUN.2015 19:43:04


Fig.12 Frequency Band Edge: GFSK, Ch78, Hopping OFF

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 18 of 73 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 19:45:09


Fig.13 Frequency Band Edge: GFSK, Ch78, Hopping ON



Date: 10.JUN.2015 19:45:44


Fig.14 Frequency Band Edge:  $\pi/4$  DQPSK, Ch0, Hopping OFF

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 19 of 73 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 19:47:48

Fig.15 Frequency Band Edge:  $\pi/4$  DQPSK, Ch0, Hopping ON



Date: 10.JUN.2015 19:48:24

Fig.16 Frequency Band Edge:  $\pi/4$  DQPSK, Ch78, Hopping OFF


East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 20 of 73 Report Issued Date : Jul, 30, 2015

Report No.: I15D00083-BT



Date: 10.JUN.2015 19:50:28


Fig.17 Frequency Band Edge:  $\pi/4$  DQPSK, Ch78, Hopping ON



Date: 10.JUN.2015 19:51:03


Fig.18 Frequency Band Edge: 8DPSK, Ch0, Hopping OFF

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 21 of 73 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 19:53:08

Fig.19 Frequency Band Edge: 8DPSK, Ch0, Hopping ON




Date: 10.JUN.2015 19:53:43

Fig.20 Frequency Band Edge: 8DPSK, Ch78, Hopping OFF

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 22 of 73 Report Issued Date : Jul, 30, 2015





Date: 10.JUN.2015 19:55:48

Fig.21 Frequency Band Edge: 8DPSK, Ch78, Hopping ON

### 6.3. Conducted Emission

#### 6.3.1 Measurement Limit:

Standard	Limit	
FCC 47 CFR Part15.247 (d)	20dB below peak output power in 100KHz	
1 00 47 OF IN Part 13.247 (u)	bandwidth	

### 6.3.2 Test procedures

The measurement is according to ANSI C63.10 clause 7.8.8.

- 1. Connect the EUT to spectrum analyzer.
- 2. Set RBW=100KHz, VBW=300KHz.
- 3. Detector =peak, sweep time=auto couple, trace mode=max hold.

#### 6.3.3 Measurement Results:

### **For GFSK**

Channel	Frequency Range	Test Results	Conclusion
Ch0 2402MHz	Center Freq.	Fig.22	Р
	30MHz~26GHz	Fig.23	Р
Ch39 2441MHz	Center Freq.	Fig.24	Р
	30MHz~26GHz	Fig.25	Р
Ch78 2480MHz	Center Freq.	Fig.26	Р

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 23 of 73 Report Issued Date : Jul, 30, 2015

Report No.: I15D00083-BT



30MHz~26GHz	Fig.27	Р
-------------	--------	---

Report No.: I15D00083-BT

### For $\pi/4$ DQPSK


Channel	Frequency Range	Test Results	Conclusion
Ch0 2402MHz	Center Freq.	Fig.28	Р
	30MHz~26GHz	Fig.29	Р
Ch39 2441MHz	Center Freq.	Fig.30	Р
	30MHz~26GHz	Fig.31	Р
Ch78 2480MHz	Center Freq.	Fig.32	Р
	30MHz~26GHz	Fig.33	Р

### For 8DPSK

Channel	Frequency Range	Test Results	Conclusion
Ch0 2402MHz	Center Freq.	Fig.34	Р
	30MHz~26GHz	Fig.35	Р
Ch39 2441MHz	Center Freq.	Fig.36	Р
	30MHz~26GHz	Fig.37	Р
Ch78 2480MHz	Center Freq.	Fig.38	Р
	30MHz~26GHz	Fig.39	Р


Conclusion: PASS Test graphs as below

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 24 of 73 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 19:56:40

Fig.22 Conducted spurious emission: GFSK, Ch0, 2402MHz




Date: 10.JUN.2015 19:57:03

Fig.23 Conducted spurious emission: GFSK, Ch0, 30MHz~26GHz

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 25 of 73 Report Issued Date : Jul, 30, 2015


Report No.: I15D00083-BT



Report No.: I15D00083-BT

Date: 10.JUN.2015 19:57:29

Fig.24 Conducted spurious emission: GFSK, Ch39, 2441MHz




Date: 10.JUN.2015 19:57:51

Fig.25 Conducted spurious emission: GFSK, Ch39, 30MHz~26GHz


Page Number

: 26 of 73



Date: 10.JUN.2015 19:58:17

Fig.26 Conducted spurious emission: GFSK, Ch78, 2480MHz




Date: 10.JUN.2015 19:58:40

Fig.27 Conducted spurious emission: GFSK, Ch78, 30MHz~26GHz


Page Number

: 27 of 73



Date: 10.JUN.2015 19:59:05

Fig.28 Conducted spurious emission:  $\pi/4$  DQPSK, Ch0, 2402MHz




Date: 10.JUN.2015 19:59:28

Fig.29 Conducted spurious emission:  $\pi/4$  DQPSK, Ch0, 30MHz~26GHz


East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 28 of 73 Report Issued Date : Jul, 30, 2015

Report No.: I15D00083-BT



Date: 10.JUN.2015 19:59:53


Fig.30 Conducted spurious emission:  $\pi/4$  DQPSK, Ch39, 2441MHz



Date: 10.JUN.2015 20:00:16


Fig.31 Conducted spurious emission:  $\pi/4$  DQPSK, Ch39, 30MHz~26GHz

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 29 of 73 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 20:00:42

Fig.32 Conducted spurious emission:  $\pi/4$  DQPSK, Ch78, 2480MHz




Date: 10.JUN.2015 20:01:05

Fig.33 Conducted spurious emission:  $\pi/4$  DQPSK, Ch78, 30MHz~26GHz


East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 30 of 73 Report Issued Date : Jul, 30, 2015

Report No.: I15D00083-BT



Date: 10.JUN.2015 20:01:30


Fig.34 Conducted spurious emission: 8DPSK, Ch0, 2402MHz



Date: 10.JUN.2015 20:01:53


Fig.35 Conducted spurious emission: 8DPSK, Ch0, 30MHz~26GHz

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 31 of 73 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 20:02:18

Fig.36 Conducted spurious emission: 8DPSK, Ch39, 2441MHz




Date: 10.JUN.2015 20:02:41

Fig.37 Conducted spurious emission: 8DPSK, Ch39, 30MHz~26GHz


Page Number

: 32 of 73



Date: 10.JUN.2015 20:03:06

Fig.38 Conducted spurious emission: 8DPSK, Ch78, 2480MHz



Date: 10.JUN.2015 20:03:29

Fig.39 Conducted spurious emission: 8DPSK, Ch78, 30MHz~26GHz

### 6.4. Radiated Emission

#### **6.4.1 Measurement Limit:**

Standard	Limit
FCC 47 CFR Part 15.247, 15.205, 15.209	20dB below peak output power

In addition, radiated emissions which fall in the restricted bands, as defined in 15.205(a),

East China Institute of Telecommunications Page Number TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



Report No.: I15D00083-BT

must also comply with the radiated emission limits specified in 15.209(a) (see 15.205(c)).

#### Limit in restricted band:

Frequency of emission (MHz)	Field strength (uV/m)	Field strength (dBuV/m)
30~88	100	40
88~216	150	43.5
216~960	200	46
Above 960	500	54

#### 6.4.2 Test Method

Portable, small, lightweight, or modular devices that may be handheld, worn on the body, or placed on a table during operation shall be positioned on a non-conducting platform, the top of which is 80 cm above the reference ground plane. The preferred area occupied by the EUT arrangement is 1 m by 1.5 m, but it may be larger or smaller to accommodate various sized EUTs. For testing purposes, ceiling- and wall-mounted devices also shall be positioned on a tabletop (see also ANSI C63.10-2009 section 6.3.4 and 6.3.5). In making any tests involving handheld, body-worn, or ceiling-mounted equipment, it is essential to recognize that the measured levels may be dependent on the orientation (attitude) of the three orthogonal axes of the EUT. Thus, exploratory tests as specified in 8.3.1 shall be carried out for various axes orientations to determine the attitude having maximum or near-maximum emission level.

The EUT was placed on a non-conductive table. The measurement antenna was placed at a distance of 3 meters from the EUT. During the tests, the antenna height and the EUT azimuth were varied in order to identify the maximum level of emissions from the EUT. This maximization process was repeated with the EUT positioned in each of its three orthogonal orientations.

Frequency of emission (MHz)	RBW/VBW	Sweep Time (s)
30~1000	100KHz/300KHz	5
1000~4000	1MHz/1MHz	15
4000~18000	1MHz/1MHz	40
18000~26500	1MHz/1MHz	20

#### 6.4.3 Measurement Results:

A "reference path loss" is established and  $A_{Rpi}$  is the attenuation of "reference path loss", and including the gain of receive antenna, the gain of the preamplifier, the cable loss. The measurement results are obtained as described below:

A<sub>Rpi</sub> = Cable loss + Antenna Gain-Preamplifier gain

East China Institute of Telecommunications Page Number : 34 of 73 TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



Report No.: I15D00083-BT

Result= $P_{Mea} + A_{Rpi}$ 

### For GFSK

Channel	Frequency Range	Test Results	Conclusion
Ch0 2402MHz	30MH~1GHz	Fig.40	Р
	1GHz~3GHz	Fig.41	Р
	3GHz~18GHz	Fig.42	Р
Power	2.38GHz~2.4GHz	Fig.43	Р
Power	2.45GHz~2.5GHz	Fig.44	Р
All channels	18GHz~26GHz	Fig.45	Р

### For $\pi/4$ DQPSK

Channel	Frequency Range	Test Results	Conclusion
	30MH~1GHz	Fig.46	Р
Ch0 2402MHz	1GHz~3GHz	Fig.47	Р
	3GHz~18GHz	Fig.48	Р
Power	2.38GHz~2.4GHz	Fig.49	Р
Power	2.45GHz~2.5GHz	Fig.50	Р
All channels	18GHz~26GHz	Fig.51	Р


### For 8DPSK

Channel	Frequency Range	Test Results	Conclusion
	30MH~1GHz	Fig.52	Р
Ch0 2402MHz	1GHz~3GHz	Fig.53	Р
	3GHz~18GHz	Fig.54	Р
Power	2.38GHz~2.4GHz	Fig.55	Р
Power	2.45GHz~2.5GHz	Fig.56	Р
All channels	18GHz~26GHz	Fig.57	Р

#### GFSK Ch0 30MHz-1GHz

Frequency(MHz)	Result(dBuV/m)	ARpl (dB)	PMea(dBuV/m)	Polarity
34.550692	9.49	-25.9	35.39	V

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 35 of 73 Report Issued Date : Jul, 30, 2015



44.772752	9.38	-25	34.38	V
54.10184	9.94	-25	34.94	٧
70.184308	3.56	-28.3	31.86	V
210.504276	6.06	-24.3	30.36	V
675.999396	24.26	-11.7	35.96	V

### **GFSK Ch0 1GHz-3GHz**

Frequency(MHz)	Result(dBuV/m)	ARpl (dB)	PMea(dBuV/m)	Polarity
2033.6872	45.54	2.6	42.94	Н
2367.1268	51.29	7.5	43.79	Н
2679.839231	53.07	9.6	43.47	Н
2804.180577	53.75	10.6	43.15	Н
2885.735	54.36	11.4	42.96	V
2983.12827	56.81	13.2	43.61	Н

### GFSK Ch0 3GHz-18GHz


Frequency(MHz)	Result(dBuV/m)	ARpl (dB)	PMea(dBuV/m)	Polarity
12824.2846	51.71	16.7	35.01	V
14233.81253	54.12	19.8	34.32	Н
14920.02473	56.19	22.1	34.09	V
16045.90253	59.65	25.1	34.55	Н
16843.8674	60.64	27.3	33.34	V
17803.4334	61.64	28.3	33.34	V

### $\pi/4$ DQPSK Ch0 30MHz-1GHz

Frequency(MHz)	Result(dBuV/m)	ARpl (dB)	PMea(dBuV/m)	Polarity
31.422728	6.87	-26	32.87	V
34.805412	13.3	-25.9	39.2	V

: 36 of 73

East China Institute of Telecommunications Page Number Report Issued Date : Jul, 30, 2015 TEL: +86 21 63843300 FAX: +86 21 63843301



17.2

-12

29.2

٧

#### π/4 DQPSK Ch0 1GHz-3GHz

634.911672

Frequency(MHz)	Result(dBuV/m)	ARpl (dB)	PMea(dBuV/m)	Polarity
2615.635	52.39	9	43.39	Н
2759.215769	53.3	10.1	43.2	Н
2798.500384	53.73	10.5	43.23	V
2872.668846	54.9	11.3	43.6	Н
2916.133462	56.01	11.8	44.21	V
2987.0025	56.69	13.3	43.39	Н

#### π/4 DQPSK Ch0 3GHz-18GHz

Frequency(MHz)	Result(dBuV/m)	ARpl (dB)	PMea(dBuV/m)	Polarity
12938.50253	52.4	16.6	35.8	Н
14310.99873	55.54	20.7	34.84	Н
14990.29	56.14	21.7	34.44	Н
15557.6166	56.85	23.1	33.75	Н
16813.774	60.65	27.3	33.35	Н
17579.82313	62.84	29.5	33.34	V

#### 8DPSK 30MHz-1GHz

Frequency(MHz)	Result(dBuV/m)	ARpl (dB)	PMea(dBuV/m)	Polarity
32.373124	8.83	-26	34.83	V
34.680244	9.51	-25.9	35.41	V
57.341172	8	-25.1	33.1	V

Page Number

: 37 of 73

Report Issued Date : Jul, 30, 2015

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301



ECIT RF Test Report			Report No	o.: I15D00083-BT
160.611888	3.42	-26.6	30.02	V
675.98428	23.95	-11.7	35.65	V
907.063392	21.44	-7.5	28.94	V

#### 8DPSK 1GHz-3GHz

Frequency(MHz)	Result(dBuV/m)	ARpl (dB)	PMea(dBuV/m)	Polarity
2484.084231	53.89	10.5	43.39	Н
2608.275577	52.08	8.9	43.18	Н
2743.573461	53.29	10	43.29	Н
2833.88077	53.61	11	42.61	V
2916.015	54.43	11.8	42.63	Н
2988.660769	56.68	13.4	43.28	V

### 8DPSK 3GHz-18GHz

Frequency(MHz)	Result(dBuV/m)	ARpl (dB)	PMea(dBuV/m)	Polarity
14315.07913	55.14	20.6	34.54	V
14847.41347	55.49	21.1	34.39	V
15999.8036	59.29	25.3	33.99	Н
16510.1274	59.77	26.8	32.97	V
17284.0098	60.89	28.1	32.79	V
17609.0264	62.23	29.5	32.73	V

### All Ch 18GHz~26.5GHz

Frequency(MHz)	Result(dBuV/m)	ARpl (dB)	PMea(dBuV/m)	Polarity
19525.786000	49.0	6.97	42.03	V
20684.980000	47.7	6.97	40.73	Н
22119.789000	45.3	3.05	42.05	V
23627.899000	43.8	3.05	40.75	Н
24606.319000	43.4	3.05	40.35	V

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 38 of 73 Report Issued Date : Jul, 30, 2015



25244.558000 43.6 3.05 40.55	Н
------------------------------	---

Report No.: I15D00083-BT

Note: all the test data shown was peak detected.

Conclusion: PASS
Test graphs as below:




Fig.40 Radiated emission: GFSK, Ch0, 30MHz~1GHz




Fig.41 Radiated emission: GFSK, Ch0, 1GHz~3GHz

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 39 of 73 Report Issued Date : Jul, 30, 2015






Fig.42 Radiated emission: GFSK, Ch0, 3GHz~18GHz





Fig.43 Radiated emission (Power): GFSK, low channel

Page Number : 40 of 73 Report Issued Date : Jul, 30, 2015





: 41 of 73

Report Issued Date : Jul, 30, 2015

Page Number

Fig.44 Radiated emission (Power): GFSK, high channel




Fig.45 Radiated emission: GFSK, 18 GHz - 26 GHz






Fig.46 Radiated emission:  $\pi/4$  DQPSK, Ch0, 30MHz~1GHz




Fig.47 Radiated emission: π/4 DQPSK, Ch0, 1GHz~3GHz

Page Number

: 42 of 73






Fig.48 Radiated emission:  $\pi/4$  DQPSK, Ch0, 3GHz~18GHz




Fig.49 Radiated emission (Power):  $\pi/4$  DQPSK, low channel

Page Number

: 43 of 73






Fig.50 Radiated emission (Power):  $\pi/4$  DQPSK, high channel




Fig.51 Radiated emission:  $\pi/4$  DQPSK, 18 GHz - 26 GHz

Page Number

: 44 of 73






Fig.52 Radiated emission: 8DPSK, Ch0, 30MHz~1GHz




Fig.53 Radiated emission: 8DPSK, Ch0, 1GHz~3GHz

Page Number : 45 of 73 Report Issued Date : Jul, 30, 2015






Fig.54 Radiated emission: 8DPSK, Ch0, 3GHz~18GHz




Fig.55 Radiated emission (Power): 8DPSK, low channel

Page Number : 46 of 73 Report Issued Date : Jul, 30, 2015






Fig.56 Radiated emission (Power): 8DPSK, high channel




Fig.57 Radiated emission: 8DPSK, 18 GHz - 26 GHz

### 6.5. Time Of Occupancy (Dwell Time)

### 6.5.1 Measurement Limit:

Standard	Limit (ms)
FCC 47CFR Part 15.247 (a) (1) (iii)	< 400

### 6.5.2 Test procedures



The measurement is according to ANSI C63.10 clause 7.8.4

1. Connect the EUT through cable and divide with CBT32 and spectrum analyzer.

Report No.: I15D00083-BT

- 2. Enable the EUT transmit maximum power.
- 3. Set the spectrum analyzer as step 4 to step 8.
- 4. Span: Zero span, centered on a hopping channel.
- 5. RBW shall be ≤ channel spacing and where possible RBW should be set >> 1 / T, where T is the expected dwell time per channel.
- 6. Sweep: As necessary to capture the entire dwell time per hopping channel; where possible use a video trigger and trigger delay so that the transmitted signal starts a little to the right of the start of the plot. The trigger level might need slight adjustment to prevent triggering when the system hops on an adjacent channel; a second plot might be needed with a longer sweep time to showtwo successive hops on a channel.
- 7. Detector function: Peak.
- 8. Trace: Max hold.
- 9. Use the marker-delta function, and record it.

#### 6.5.3 Measurement Result

#### For GFSK

Channel	Packet	Dwell Time (ms)		Conclusion
DH1		Fig.58	220,400	Р
	υпι	Fig.59	238.400	
39	DH3	Fig.60	282.080	Р
		Fig.61		
	DH5	Fig.62	320.533	Р
		Fig.63		

#### For π/4 DQPSK

Channel	Packet	Dwell Time (ms)		Conclusion
2DH1 39 2DH3 2DH5	00114	Fig.64	161 600	Р
	ZUNT	Fig.65	161.600	
	2DH3	Fig.66	282.080	Р
		Fig.67		
	2DH5	Fig.68	- 321.386	Р
		Fig.69		

#### For 8DPSK

East China Institute of Telecommunications Page Number : 48 of 73 TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



ecn	THE POST TOPOTE		э 110000000 Б1	
Channel	Packet	Dwell Time (ms)		Conclusion
	3DH1 Fig.70 164.160	Fig.70	404 400	1
		Р		
20	39 Fig.72 282.080 Fig.73	Б		
39		Fig.73	202.000	Р
	2015	Fig.74	224 206	D
	3DH5	Fig.75	321.386	Р

Report No.: I15D00083-BT

Note: the dwell time is Calculated of the sum of test time about 31.5 seconds.

Equation: dwell time = pusletime \*(1600/N)/79\*T . N is the number of timeslot; T is the time about 31.5s.

The time of DH5=3.01\*(1600/6)/79\*31.6=321.06ms.

Date: 10.JUN.2015 20:04:11

Conclusion: PASS
Test graphs as below:





Fig.58 Time of occupancy (Dwell Time): Ch39, Packet DH1

East China Institute of Telecommunications Page Nu TEL: +86 21 63843300 FAX: +86 21 63843301 Report Is


Page Number : 49 of 73 Report Issued Date : Jul, 30, 2015



Report No.: I15D00083-BT

Date: 10.JUN.2015 20:04:18

Fig.59 Number of Transmissions Measurement: Ch39, Packet DH1



Date: 10.JUN.2015 20:05:49


Fig.60 Time of occupancy (Dwell Time): Ch39, Packet DH3

Page Number

: 50 of 73


Report Issued Date : Jul, 30, 2015

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301



Date: 10.JUN.2015 20:05:57

Fig.61 Number of Transmissions Measurement: Ch39, Packet DH3




Date: 10.JUN.2015 20:06:21

Fig.62 Time of occupancy (Dwell Time): Ch39, Packet DH5

Page Number


: 51 of 73



Report No.: I15D00083-BT

Date: 10.JUN.2015 20:06:29

Fig.63 Number of Transmissions Measurement: Ch39, Packet DH5




Date: 10.JUN.2015 20:06:41

Fig.64 Time of occupancy (Dwell Time): Ch39,Packet 2-DH1


Page Number

: 52 of 73



Date: 10.JUN.2015 20:06:48


Fig.65 Number of Transmissions Measurement: Ch39, Packet 2-DH1



Date: 10.JUN.2015 20:06:59


Fig.66 Time of occupancy (Dwell Time): Ch39, Packet 2-DH3

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 53 of 73 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 20:07:07

Fig.67 Number of Transmissions Measurement: Ch39, Packet 2-DH3




Date: 10.JUN.2015 20:07:39

Fig.68 Time of occupancy (Dwell Time): Ch39, Packet 2-DH5

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 54 of 73 Report Issued Date : Jul, 30, 2015


Report No.: I15D00083-BT



Report No.: I15D00083-BT

Date: 10.JUN.2015 20:07:46

Fig.69 Number of Transmissions Measurement: Ch39, Packet 2-DH5




Date: 10.JUN.2015 20:07:59

Fig.70 Time of occupancy (Dwell Time): Ch39, Packet 3-DH1


Page Number

: 55 of 73



Date: 10.JUN.2015 20:08:06


Fig.71 Number of Transmissions Measurement: Ch39, Packet 3-DH1



Date: 10.JUN.2015 20:09:04


Fig.72 Time of occupancy (Dwell Time): Ch39, Packet 3-DH3

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 56 of 73 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 20:09:12

Fig.73 Number of Transmissions Measurement: Ch39, Packet 3-DH3




Date: 10.JUN.2015 20:09:22

Fig.74 Time of occupancy (Dwell Time): Ch39,Packet 3-DH5

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 57 of 73 Report Issued Date : Jul, 30, 2015





Date: 10.JUN.2015 20:09:29

Fig.75 Number of Transmissions Measurement: Ch39, Packet 3-DH5

#### 6.6. 20dB Bandwidth

#### 6.6.1 Measurement Limit:

Standard	Limit
FCC 47 CFR Part 15.247 (a) (1)	N/A

#### 6.6.2 Test procedures

The measurement is according to ANSI C63.10 clause 7.8.7

- 1. Connect the EUT through cable and divide with CBT32 and spectrum analyzer.
- 2. Enable the EUT transmit maximum power.
- 3. Set the spectrum analyzer as
- 4. Span: two or five times of OBW
- 5. RBW= 1% to 5% of the OBW; VBW ≥ 3RBW; Max Hold.
- Select the max peak, and N DB DOWN=20dB.
- Record the results. 7.

#### **Measurement Result:**

#### For GFSK

Channel	20dB Bandwidth (MHz)		Conclusion
0	Fig.76	1.034	Р
39	Fig.77	1.029	Р

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 58 of 73 Report Issued Date : Jul, 30, 2015



		•	
78	Fig.78	1.029	Р

Report No.: I15D00083-BT


#### For π/4 DQPSK

Channel	20dB Bandwidth (MHz)		Conclusion
0	Fig.79	1.091	Р
39	Fig.80	1.091	Р
78	Fig.81	1.091	Р

#### For 8DPSK

Channel	20dB Bandwidth (MHz)		Conclusion
0	Fig.82	1.188	Р
39	Fig.83	1.188	Р
78	Fig.84	1.192	Р

# Conclusion: PASS Test graphs as below:



Date: 10.JUN.2015 20:10:11

Fig.76 20dB Bandwidth: GFSK, Ch0

East China Institute of Telecommunications Page Number : 59 of 73 TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 20:10:26

### Fig.77 20dB Bandwidth: GFSK, Ch39




Fig.78 20dB Bandwidth: GFSK, Ch78


Page Number

: 60 of 73



Date: 10.JUN.2015 20:10:54

### Fig.79 20dB Bandwidth: $\pi/4$ DQPSK, Ch0



Date: 10.JUN.2015 20:11:09

Fig.80 20dB Bandwidth:  $\pi/4$  DQPSK, Ch39

Page Number


: 61 of 73



Report No.: I15D00083-BT

Date: 10.JUN.2015 20:11:23

Fig.81 20dB Bandwidth:  $\pi/4$  DQPSK, Ch78




Date: 10.JUN.2015 20:11:38

Fig.82 20dB Bandwidth: 8DPSK, Ch0


Page Number

: 62 of 73



Date: 10.JUN.2015 20:11:52

Fig.83 20dB Bandwidth: 8DPSK, Ch39



Date: 10.JUN.2015 20:12:06

Fig.84 20dB Bandwidth: 8DPSK, Ch78

### 6.7. Carrier Frequency Separation

#### 6.7.1 Measurement Limit:

Standard	Limit (KHz)
FCC 47 CFR Part 15.247 (a) (1)	Over 25KHz or (2/3)*20dB bandwidth

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 63 of 73 Report Issued Date : Jul, 30, 2015

Report No.: I15D00083-BT



### 6.7.2 Test procedures

The measurement is according to ANSI C63.10 clause 7.8.2.

- 1. Connect the EUT through cable and divide with CBT32 and spectrum analyzer.
- Enable the EUT transmit in hopping mode.
- 3. Span: Wide enough to capture the peaks of two adjacent channels.
- 4. RBW: Start with the RBW set to approximately 30% of the channel spacing; adjust as necessary to best identify the center of each individual channel.

Report No.: I15D00083-BT

- 5. Video (or average) bandwidth (VBW) ≥ RBW.
- 6. Sweep: Auto.
- 7. Detector function: Peak.
- 8. Trace: Max hold.
- 9. Allow the trace to stabilize.

#### 6.7.3 Measurement Result:

#### For GFSK

Channel	Carrier separation (KHz)		Conclusion
39	Fig.85	1000	Р

#### For π/4 DQPSK

Channel	Carrier separation (KHz)		Conclusion
39	Fig.86	1019.2308	Р

#### For 8DPSK

Channel	Carrier separation (KHz)		Conclusion
39	Fig.87	971.1538	Р


Conclusion: PASS
Test graphs as below:

East China Institute of Telecommunications Page Number : 64 of 73 TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 20:13:47

Fig.85 Carrier separation measurement: GFSK, Ch39



Date: 10.JUN.2015 20:14:58

Fig.86 Carrier separation measurement:  $\pi/4$  DQPSK, Ch39

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 65 of 73 Report Issued Date : Jul, 30, 2015

Report No.: I15D00083-BT





Report No.: I15D00083-BT

Date: 10.JUN.2015 20:16:08

Fig.87 Carrier separation measurement: 8DPSK, Ch39

### 6.8. Number Of Hopping Channels

#### 6.8.1 Measurement Limit:

Standard	Limit
FCC 47 CFR Part 15.247 (a)(1)(iii)	At least 15 non-overlapping channels

#### 6.8.2 Test procedure

The measurement is according to ANSI C63.10 clause 7.8.3.

- 1. Connect the EUT through cable and divide with CBT32 and spectrum analyzer.
- 2. Enable the EUT transmit in hopping mode.
- 3. Span: The frequency band of operation. Depending on the number of channels the device supports, it may be necessary to divide the frequency range of operation across multiple spans, to allow the individual channels to be clearly seen.
- 4. RBW: To identify clearly the individual channels, set the RBW to less than 30% of the channel spacing or the 20 dB bandwidth, whichever is smaller.
- 5. VBW  $\geq$  RBW.
- 6. Sweep: Auto.
- 7. Detector function: Peak.
- 8. Trace: Max hold.
- 9. Allow the trace to stabilize.
- 10. Record the test rsults.

#### 6.8.3 Measurement Result:

#### For GFSK

East China Institute of Telecommunications Page Number : 66 of 73 TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



Channel	Number of hopping channels		Conclusion
0~39	Fig.88	79	Р
40~78	Fig.89	79	Р

Report No.: I15D00083-BT


#### For $\pi/4$ DQPSK

Channel	Number of hopping channels		Conclusion
0~39	Fig.90	79	Р
40~78	Fig.91	79	Р

#### For 8DPSK

Channel	Number of hop	Conclusion	
0~39	Fig.92	79	Р
40~78	Fig.93	79	Р

Conclusion: PASS
Test graphs as below:



Date: 10.JUN.2015 20:18:42


Fig.88 Number of hopping frequency: GFSK, Ch0~39

East China Institute of Telecommunications Page Number : 67 of 73
TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015



Date: 10.JUN.2015 20:20:47

### Fig.89 Number of hopping frequency: GFSK, Ch40~78



Date: 10.JUN.2015 20:22:51

Fig.90 Number of hopping frequency: π/4 DQPSK, Ch0~39

Page Number

: 68 of 73


Report Issued Date : Jul, 30, 2015

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301



Date: 10.JUN.2015 20:24:56

Fig.91 Number of hopping frequency: π/4 DQPSK, Ch40~78




Date: 10.JUN.2015 20:27:01

Fig.92 Number of hopping frequency: 8DPSK, Ch0~39

Page Number

: 69 of 73



Date: 10.JUN.2015 20:29:06

Fig.93 Number of hopping frequency: 8DPSK, Ch40~78

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 70 of 73 Report Issued Date : Jul, 30, 2015

# 7. Test Equipments and Ancillaries Used For Tests

The test equipments and ancillaries used are as follows.

#### Conducted test system

No.	Equipment	Model	Serial Number	Manufacturer	Calibration Date	Cal.interva
1	Vector Signal Analyser	FSQ26	101096	Rohde&Schw arz	2015-05-13	1
2	Bluetooth Tester	CBT32	100785	Rohde&Schw arz	2015-05-13	1
3	DC Power Supply	ZUP60-14	LOC-220Z006 -0007	TDL-Lambda	2015-05-13	1

Report No.: I15D00083-BT

### Radiated emission test system

No.	Equipment	Model	Serial Number	Manufacturer	Calibratio n Date	Cal.interv al
1	Universal Radio Communicati	CMU200	123126	R&S	2015-05-1 3	1
2	Test Receiver	ESU40	100307	R&S	2015-05-1 3	1
3	Trilog Antenna	VULB916 3	VULB9163-51 5	Schwarzbeck	2014-11-0 5	3
4	Double Ridged Guide Antenna	ETS-311 7	00135885	ETS	2014-05-0 6	3
5	2-Line V-Network	ENV216	101380	R&S	2015-05-1 3	1

### **Anechoic chamber**

Fully anechoic chamber by Frankonia German.

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301 Page Number : 71 of 73 Report Issued Date : Jul, 30, 2015

### 8. Test Environment

**Shielding Room1** (6.0 meters×3.0 meters×2.7 meters) did not exceed following limits along the conducted RF performance testing:

Report No.: I15D00083-BT

: 72 of 73

Report Issued Date : Jul, 30, 2015

Temperature	Min. = 15 °C, Max. = 30 °C
Relative humidity	Min. = 30 %, Max. = 60 %
Shielding effectiveness	> 110 dB
Ground system resistance	< 0.5 Ω
Uniformity of field strength	Between 0 and 6 dB, from 80MHz to 3000 MHz

Control room did not exceed following limits along the EMC testing:

Temperature	Min. = 15 °C, Max. = 35 °C
Relative humidity	Min. =30 %, Max. = 60 %
Shielding effectiveness	> 110 dB
Electrical insulation	> 10 kΩ
Ground system resistance	< 0.5 Ω

**Fully-anechoic chamber1** (6.8 meters×3.08 meters×3.53 meters) did not exceed following limits along the EMC testing:

Temperature	Min. = 15 $^{\circ}$ C, Max. = 30 $^{\circ}$ C		
Relative humidity	Min. = 30 %, Max. = 60 %		
Shielding effectiveness	> 110 dB		
Electrical insulation	> 10 kΩ		
Ground system resistance	< 0.5 Ω		
Uniformity of field strength	Between 0 and 6 dB, from 80MHz to 3000		
·	MHz		

**Fully-anechoic chamber2** (Tapered Section: 8.75 meters×3.66 meters×3.66 meters, Rectangular Section: 7.32 meters×3.97 meters×3.66 meters) did not exceed following limits along the EMC testing:

Temperature	Min. = 15 °C , Max. = 30 °C
Relative humidity	Min. = 35 %, Max. = 60 %

Page Number

East China Institute of Telecommunications TEL: +86 21 63843300 FAX: +86 21 63843301



Shielding effectiveness	> 110 dB	
Electrical insulation	> 10 kΩ	
Ground system resistance	< 0.5 Ω	
Uniformity of field strength	Between 0 and 6 dB, from 30MHz to	

Report No.: I15D00083-BT

# **ANNEX A.** Deviations from Prescribed Test Methods

No d	eviation	from	Prescribed	Test I	Methods.
------	----------	------	------------	--------	----------

\*\*\*\*\*\*\*\*End The Report\*\*\*\*\*\*

East China Institute of Telecommunications Page Number : 73 of 73 TEL: +86 21 63843300 FAX: +86 21 63843301 Report Issued Date : Jul, 30, 2015