Report No: CCISE180711006

FCC REPORT

Applicant: PCD, LLC

Address of Applicant: 1500 Tradeport Drive, ORLANDO, Florida, 32824. United States

Equipment Under Test (EUT)

Product Name: Jaguar PRO LTE

Model No.: PL570

Trade mark: PCD

FCC ID: 2ALJJPL570

Applicable standards: FCC CFR Title 47 Part 15 Subpart B

Date of sample receipt: 27 Jul., 2018

Date of Test: 27 Jul., to 27 Aug., 2018

Date of report issued: 28 Aug., 2018

Test Result: PASS *

Authorized Signature:



Bruce Zhang Laboratory Manager

This report details the results of the testing carried out on one sample. The results contained in this test report do not relate to other samples of the same product and does not permit the use of the CCIS product certification mark. The manufacturer should ensure that all products in series production are in conformity with the product sample detailed in this report.

This report may only be reproduced and distributed in full. If the product in this report is used in any configuration other than that detailed in the report, the manufacturer must ensure the new system complies with all relevant standards.

This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 90 days only.

^{*} In the configuration tested, the EUT complied with the standards specified above.





2 Version

Reviewed by:

| Version No. | Date | Description | | | |
|-------------|---------------|-------------|--|--|--|
| 00 | 28 Aug., 2018 | Original | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

Tested by: Date: 28 Aug., 2018

Test Engineer

Date: 28 Aug., 2018

Project Engineer





3 Contents

| | | | Page |
|---|-----|----------------------------------|------|
| 1 | С | OVER PAGE | 1 |
| 2 | ٧ | ERSION | 2 |
| 3 | С | CONTENTS | 3 |
| 4 | | EST SUMMARY | |
| 5 | | ENERAL INFORMATION | |
| _ | 5.1 | CLIENT INFORMATION | |
| | 5.2 | GENERAL DESCRIPTION OF E.U.T. | |
| | 5.3 | TEST MODE | |
| | 5.4 | Measurement Uncertainty | |
| | 5.5 | DESCRIPTION OF SUPPORT UNITS | |
| | 5.6 | RELATED SUBMITTAL(S) / GRANT (S) | 6 |
| | 5.7 | LABORATORY FACILITY | 6 |
| | 5.8 | LABORATORY LOCATION | |
| | 5.9 | TEST INSTRUMENTS LIST | |
| 6 | T | EST RESULTS AND MEASUREMENT DATA | 8 |
| | 6.1 | CONDUCTED EMISSION | 8 |
| | 6.2 | RADIATED EMISSION | |
| 7 | T | EST SETUP PHOTO | 17 |
| R | F | UT CONSTRUCTIONAL DETAILS | 18 |





4 Test Summary

| Test Item | Section in CFR 47 | Result | | |
|--------------------|-------------------|--------|--|--|
| Conducted Emission | Part 15.107 | Pass | | |
| Radiated Emission | Part 15.109 | Pass | | |

Remark.

Pass: The EUT complies with the essential requirements in the standard.

N/A: The EUT not applicable of the test item.



5 General Information

5.1 Client Information

| Applicant: | PCD, LLC |
|-----------------------|--|
| Address of Applicant: | 1500 Tradeport Drive, ORLANDO, Florida, 32824. United States |
| Manufacturer: | PCD, LLC |
| Address: | 1500 Tradeport Drive, ORLANDO, Florida, 32824. United States |

Report No: CCISE180711006

5.2 General Description of E.U.T.

| Product Name: Jaguar PRO LTE | |
|------------------------------|---|
| Model No.: PL570 | |
| Power supply: | Rechargeable Li-ion Battery DC3.8V2800mAh |
| AC adapter : | Model: PL570 Input: AC100-240V, 50/60Hz, 0.2A Output: DC 5.0V, 1.0A |

5.3 Test Mode

| Operating mode | Detail description |
|-------------------------|--|
| PC mode | Keep the EUT in Downloading mode(Worst case) |
| Charging+Recording mode | Keep the EUT in Charging+Recording mode |
| Charging+Playing mode | Keep the EUT in Charging+Playing mode |
| FM mode | Keep the EUT in FM receiver mode |
| GPS mode | Keep the EUT in GPS receiver mode |

The sample was placed 0.8m above the ground plane of 3m chamber. Measurements in both horizontal and vertical polarities were performed. During the test, each emission was maximized by: having the EUT continuously working, investigated all operating modes, rotated about all 3 axis (X, Y & Z) and considered typical configuration to obtain worst position, manipulating interconnecting cables, rotating the turntable, varying antenna height from 1m to 4m in both horizontal and vertical polarizations. The emissions worst-case are shown in Test Results of the following pages.

5.4 Measurement Uncertainty

| Parameters | Expanded Uncertainty | | |
|-------------------------------------|----------------------|--|--|
| Conducted Emission (9kHz ~ 30MHz) | ±2.22 dB (k=2) | | |
| Radiated Emission (9kHz ~ 30MHz) | ±2.76 dB (k=2) | | |
| Radiated Emission (30MHz ~ 1000MHz) | ±4.28 dB (k=2) | | |
| Radiated Emission (1GHz ~ 18GHz) | ±5.72 dB (k=2) | | |
| Radiated Emission (18GHz ~ 40GHz) | ±2.88 dB (k=2) | | |



Report No: CCISE180711006

5.5 Description of Support Units

| Manufacturer | Description | Model | Serial Number | FCC ID/DoC |
|--------------|-------------|-------------|---------------|------------|
| DELL | PC | OPTIPLEX745 | N/A | DoC |
| DELL | MONITOR | E178FPC | N/A | DoC |
| DELL | KEYBOARD | SK-8115 | N/A | DoC |
| DELL | MOUSE | MOC5UO | N/A | DoC |
| LENOVO | Laptop | SL510 | 2847A65 | DoC |

5.6 Related Submittal(s) / Grant (s)

This is an original grant, no related submittals and grants.

5.7 Laboratory Facility

The test facility is recognized, certified, or accredited by the following organizations:

FCC - Registration No.: 727551

Shenzhen Zhongjian Nanfang Testing Co., Ltd. has been accredited as a testing laboratory by FCC (Federal Communications Commission). The Registration No. is 727551.

• IC - Registration No.: 10106A-1

The 3m Semi-anechoic chamber of Shenzhen Zhongjian Nanfang Testing Co., Ltd. has been Registered by Certification and Engineering Bureau of Industry Canada for radio equipment testing with Registration No.: 10106A-1.

• CNAS - Registration No.: CNAS L6048

Shenzhen Zhongjian Nanfang Testing Co., Ltd. is accredited to ISO/IEC 17025:2005 General Requirements for the Competence of Testing and Calibration laboratories for the competence of testing. The Registration No. is CNAS L6048.

A2LA - Registration No.: 4346.01

This laboratory is accredited in accordance with the recognized International Standard ISO/IEC 17025:2005 General requirements for the competence of testing and calibration laboratories. The test scope can be found as below link: https://portal.a2la.org/scopepdf/4346-01.pdf

5.8 Laboratory Location

Shenzhen Zhongjian Nanfang Testing Co., Ltd.

Address: No. B-C, 1/F., Building 2, Laodong No.2 Industrial Park, Xixiang Road,

Bao'an District, Shenzhen, Guangdong, China

Tel: +86-755-23118282, Fax: +86-755-23116366

Email: info@ccis-cb.com, Website: http://www.ccis-cb.com

Shenzhen Zhongjian Nanfang Testing Co., Ltd.
No. B-C, 1/F., Building 2, Laodong No.2 Industrial Park, Xixiang Road,
Bao'an District, Shenzhen, Guangdong, China
Telephone: +86 (0) 755 2311 8282 Fax: +86 (0) 755 2311 6366



5.9 Test Instruments list

| Radiated Emission: | | | | | | |
|---------------------------------|-----------------------------------|-----------------|-----------------------------|-------------------------|-----------------------------|--|
| Test Equipment | Manufacturer | Model No. | Inventory No. | Cal. Date (mm-dd-yy) | Cal. Due date (mm-dd-yy) | |
| 3m SAC | SAEMC | 9(L)*6(W)* 6(H) | CCIS0001 | 07-22-2017 | 07-21-2020 | |
| BiConiLog Antenna | SCHWARZBECK | VULB9163 | CCIS0005 | 03-16-2018 | 03-15-2019 | |
| Horn Antenna | SCHWARZBECK | BBHA9120D | CCIS0006 | 03-16-2018 | 03-15-2019 | |
| Pre-amplifier (10kHz-1.3GHz) | HP | 8447D | CCIS0003 | 03-07-2018 | 03-06-2019 | |
| Pre-amplifier (1GHz-18GHz) | Compliance Direction Systems Inc. | PAP-1G18 | CCIS0011 | 03-07-2018 | 03-06-2019 | |
| Spectrum analyzer 9k-30GHz | Rohde & Schwarz | FSP30 | CCIS0023 | 03-07-2018 | 03-06-2019 | |
| EMI Test Receiver | Rohde & Schwarz | ESRP7 | CCIS0167 | 03-07-2018 | 03-06-2019 | |
| EMI Test Software | AUDIX | E3 | Version: 6.110919b | | | |
| Coaxial Cable | N/A | N/A | CCIS0018 03-07-2018 03-06-2 | | 03-06-2019 | |
| Coaxial Cable | N/A | N/A | CCIS0020 | 03-07-2018 | 03-06-2019 | |

| Conducted Emission: | | | | | | | |
|---------------------|--------------------|-----------------------|--------------------|------------------------|----------------------------|--|--|
| Test Equipment | Manufacturer | Model No. | Inventory No. | Cal.Date (mm-dd-yy) | Cal.Due date (mm-dd-yy) | | |
| Shielding Room | ZhongShuo Electron | 11.0(L)x4.0(W)x3.0(H) | CCIS0061 | 07-22-2017 | 07-21-2020 | | |
| EMI Test Receiver | Rohde & Schwarz | ESCI | CCIS0002 | 03-07-2018 | 03-06-2019 | | |
| LISN | CHASE | MN2050D | CCIS0074 | 03-19-2018 | 03-18-2019 | | |
| LISN | Rohde & Schwarz | ESH3-Z5 | 8438621/010 | 07-21-2017 | 07-20-2018 | | |
| Coaxial Cable | CCIS | N/A | CCIS0086 | 03-07-2018 | 03-06-2019 | | |
| EMI Test Software | AUDIX | E3 | Version: 6.110919b | | | | |



6 Test results and Measurement Data


6.1 Conducted Emission

| Test Requirement: | FCC Part 15 B Section 15.107 | | | | |
|-----------------------|---|---|---|--|--|
| Test Method: | ANSI C63.4:2014 | | | | |
| Test Frequency Range: | 150kHz to 30MHz | | | | |
| Class / Severity: | Class B | | | | |
| Receiver setup: | RBW=9kHz, VBW=30kHz | | | | |
| Limit: | Frequency range (MHz) | Limit (| (dBµV) | | |
| | , , , | Average | | | |
| | 0.15-0.5 | 66 to 56* | 56 to 46* | | |
| | 0.5-5 | 56 | 46 | | |
| | 0.5-30 * Decreases with the logarith | 60 | 50 | | |
| Toot cotup: | | | | | |
| Test setup: | Reference Plan | LISN | | | |
| | AUX Full Filter AC power Remark E.U.T Remark E.U.T Remark E.U.T. Equipment Under Test LISN Line Impedence Stabilization Network Test table height=0.8m | | | | |
| Test procedure | The E.U.T and simulators line impedance stabilization 500hm/50uH coupling impedance. The peripheral devices are a LISN that provides a 500 termination. (Please refers photographs). Both sides of A.C. line are interference. In order to fir positions of equipment an according to ANSI C63.4: | on network(L.I.S.N.). The pedance for the measure also connected to the ohm/50uH coupling imports to the block diagram of the maximum emiss and all of the interface ca | ne provide a ring equipment. e main power through bedance with 50ohm of the test setup and n conducted ion, the relative bles must be changed | | |
| Test environment: | Temp.: 23 °C Hun | nid.: 56% Pro | ess.: 101kPa | | |
| Test Instruments: | Refer to section 5.9 for details | | | | |
| Test mode: | Refer to section 5.3 for details | | | | |
| Test results: | Pass | | | | |
| | | | | | |






Measurement data:



Notes:

- 1. An initial pre-scan was performed on the line and neutral lines with peak detector.
- 2. Quasi-Peak and Average measurement were performed at the frequencies with maximized peak emission.
- 3. Final Level =Receiver Read level + LISN Factor + Cable Loss.





Notes:

- 1. An initial pre-scan was performed on the line and neutral lines with peak detector.
- 2. Quasi-Peak and Average measurement were performed at the frequencies with maximized peak emission.
- 3. Final Level =Receiver Read level + LISN Factor + Cable Loss.



6.2 Radiated Emission

| | J.Z Radiated Elliission | | | | | | | | |
|------|---|--|-----------|---|--------------|--------------|------------------|------------------|--|
| Te | est Requirement: | FCC Part 15 B Section 15.109 | | | | | | | |
| Te | est Method: | ANSI C63.4:2014 | | | | | | | |
| Te | est Frequency Range: | 30MHz to 6000MHz | | | | | | | |
| Te | est site: | Measurement Distance: 3m (Semi-Anechoic Chamber) | | | | | | | |
| Re | eceiver setup: | Frequency Detector RBW VBW | | | | | Remark | | |
| | | 30MHz-1GHz | Quasi- | | 120kHz 300k | | • | | |
| | | Above 1GHz | Pea RM | | 1MHz 1MHz | 3MHz 3MHz | | Peak Value | |
| l ir | mit: | Frequenc | | | (dBuV/m @ | | | | |
| _,, | | 30MHz-88M | | - | 40.0 | , | (| Quasi-peak Value | |
| | | 88MHz-216N | | | 43.5 | | Quasi-peak Value | | |
| | | 216MHz-960 | | | 46.0 | | | Quasi-peak Value | |
| | | 960MHz-1G | | | 54.0 | | | Quasi-peak Value | |
| | | Abovo 1CL | J-, | | 54.0 | | | Average Value | |
| | | Above 1GI | 12 | | 74.0 | | | Peak Value | |
| | est setup: | Above 1GHz 54.0 Average Value | | | | | | | |
| | Ground Reference Plane Test Receiver Amplifer Controller | | | | | oller | | | |






| Test Procedure: | The EUT was placed on the top of a rotating table 0.8 meters above the ground at a 3 meter semi-anechoic camber. The table was rotated 360 degrees to determine the position of the highest radiation. | | | | | |
|-------------------|--|-------|---------|-----|---------|---------|
| | The EUT was set 3 meters away from the interference-receiving antenna, which was mounted on the top of a variable-height antenna tower. | | | | | |
| | The antenna height is varied from one meter to four meters above the ground to determine the maximum value of the field strength. Both horizontal and vertical polarizations of the antenna are set to make the measurement. | | | | | |
| | 4. For each suspected emission, the EUT was arrange and then the antenna was tuned to heights from 1 n and the rotatable table was turned from 0 degrees the find the maximum reading. | | | | | |
| | The test-receiver system was set to Peak Detect Function and Specified Bandwidth with Maximum Hold Mode. | | | | | |
| | 6. If the emission level of the EUT in peak mode was 10dB lower than the limit specified, then testing could be stopped and the peak values of the EUT would be reported. Otherwise the emissions that did not have 10dB margin would be re-tested one by one using peak, quasi-peak or average method as specified and then reported in a data sheet. | | | | | |
| Test environment: | Temp.: | 25 °C | Humid.: | 55% | Press.: | 1 01kPa |
| Test Instruments: | Refer to section 5.9 for details | | | | | |
| Test mode: | Refer to section 5.3 for details | | | | | |
| Test results: | Passed | | | | | |
| Remark: | All of the observed value above 6GHz ware the niose floor , which were no recorded | | | | | |






Measurement Data:



Remark:

- 1. Final Level = Receiver Read level + Antenna Factor + Cable Loss Preamplifier Factor.
- 2. The emission levels of other frequencies are very lower than the limit and not show in test report.






Remark:

1. Final Level = Receiver Read level + Antenna Factor + Cable Loss - Preamplifier Factor.

2. The emission levels of other frequencies are very lower than the limit and not show in test report.








Remark:

- 1. Final Level = Receiver Read level + Antenna Factor + Cable Loss Preamplifier Factor.
- The emission levels of other frequencies are very lower than the limit and not show in test report.





Remark:

- 1. Final Level = Receiver Read level + Antenna Factor + Cable Loss Preamplifier Factor.
- 2. The emission levels of other frequencies are very lower than the limit and not show in test report.