

849 NW State Road 45 Newberry, F1 32669 USA Phone: 888.472.2424 or

352.472.5500

Fax: 352.472.2030

Email: <u>info@timcoengr.com</u>
Website: <u>www.timcoengr.com</u>

FCC PART 15.209 LOW POWER TRANSMITTER TEST REPORT

Applicant	KASTLE SYSTEMS INTERNATONAL
Address	6402 ARLINGTON BLVD.
Address	FALLS CHURCH, VA 22042
FCC ID	2ALZS-AIO-W
Models	1301, 1301-P, 1301-W, 1301-PW
Product Description	BLE WALL READER
Date Sample Received	5/2/2017
Date Tested	5/2/2017
Tested By	Tim Royer
Approved By	Sid Sanders
Test Results	

Report	Version	Description	Issue Date
Number	Number		
787UT17TestReport1	Rev1	Initial Issue	5/5/2017
	Rev2	Corrected Report	5/17/2017
	Rev3	Added test set up photos and	5/25/2017
		AC conducted emissions	

THE ATTACHED REPORT SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT THE WRITTEN APPROVAL OF TIMCO ENGINEERING, INC.

TABLE OF CONTENTS

GENERAL REMARKS	2
REPORT SUMMARY	
TEST ENVIRONMENT	3
TEST SETUP SUMMARY	3
DUT SPECIFICATION	4
TEST SUPPORTING EQUIPMENT	
TEST PROCEDURES	5
POWER LINE CONDUCTED INTERFERENCE	6
RADIATED SPURIOUS EMISSIONS	9
OCCUPIED BANDWIDTH	
Test Data: 20dB Occupied Bandwidth Plot	
TEST EQUIPMENT LIST	. 11



GENERAL REMARKS

The attached report shall not be reproduced except in full without the written permission of Timco Engineering Inc.

Summary

The device under test does:

Fulfill the general approval requirements as identified in this test report and was selected by the customer.

Not fulfill the general approval requirements as identified in this test report

Attestations

This equipment has been tested in accordance with the standards identified in this test report. To the best of my knowledge and belief, these tests were performed using the measurement procedures described in this report.

All instrumentation and accessories used to test products for compliance to the indicated standards are calibrated regularly in accordance with ISO 17025 requirements.

I attest that the necessary measurements were made at:

Timco Engineering Inc. 849 NW State Road 45 Newberry, FL 32669

Tested by:

Name and Title: Tim Royer, Project Manager/Testing Engineer

Date: 5/5/2017

Reviewed and approved by:

Name and Title: Sid Sanders, Engineer

Date: 5/16/17

Table of Contents

Applicant: KASTLE SYSTEMS INTERNATIONAL <u>Table Of Contents</u>

FCC ID: 2ALZS-AIO-W

Report: 787UT17TestReport_Rev Page 2 of 11



REPORT SUMMARY

Disclaimer	The test results only relate to the item tested.
Applicable Rule(s)	Pt 15.209, ANSI C63.10: 2013
Related Report	None

TEST ENVIRONMENT

Test Facility	Timco Engineering, Inc. 849 NW State Road 45 Newberry, FL 32669 USA.						
Test Condition in the							

TEST SETUP SUMMARY

Test Setup Diagram/ Description	The DUT was placed on the turntable per setup per ANS C63.4: 2014. A test set up photo is provided for clarification.						
Deviation from the standard/procedure	No deviation						
Modification of DUT	No modification						

Table of Contents

Applicant: KASTLE SYSTEMS INTERNATIONAL

FCC ID: 2ALZS-AIO-W 787UT17TestR

Report: 787UT17TestReport_Rev Page 3 of 11



DUT SPECIFICATION

DUT Description	BLE WALL READER						
FCC ID	2ALZS-AIO-W						
Models	1301, 1301-P, 1301-W, 1301-PW						
	☐ 110-120Vac/50- 60Hz						
DUT Power Source	☑ DC Power, 12V						
	☐ Battery Operated Exclusively						
	☐ Prototype						
Test Item	☑ Pre-Production						
	☐ Production						
	⊠ Fixed						
Type of Equipment	Mobile						
	Portable						
Laboratory	Temperature: 26°C						
Test Conditions	Humidity: 55%						
Modifications to DUT:							

TEST SUPPORTING EQUIPMENT

Device	Manufacturer	Model	S/N	Supplied By	Used For
12V cupply	Security and	V6T	N/A	Security and	Powerline
12V supply	Fire Electronics	٧٥١	IN/A	Fire Electroics	

Table Of Contents

Table of Contents

Applicant: KASTLE SYSTEMS INTERNATIONAL

2ALZS-AIO-W

FCC ID: Report: Page 4 of 11 787UT17TestReport_Rev



TEST PROCEDURES

Power line conducted Emission: The test procedure used was ANSI C63.4-2009. The spectrum was scanned from 0.15 to 30 MHz.

Radiation Interference: The test procedure used was ANSI C63.4 using a spectrum analyzer with a preselector. The bandwidth of the spectrum analyzer was 100 kHz with an appropriate sweep speed. The analyzer was calibrated in dB above a microvolt at the output of the antenna. The video bandwidth was always greater than or equal to the RBW.

The frequency was scanned from 30 MHz to 1.0 GHz. When an emission was found, the table was rotated to produce the maximum signal strength. The DUT was measured in three (3) orthogonal planes when necessary.

Formula of Conversion Factors: The field strength at 3m was established by adding the meter reading of the spectrum analyzer (which is set to read in units of dB μ V) to the antenna correction factor supplied by the antenna manufacturer plus the coax loss. The antenna correction factors are stated in terms of dB. The gain of the preselector was accounted for in the spectrum analyzer meter reading.

Example:

Freq (MHz) Meter Reading + ACF + CL = FS

33 $20 \text{ dB}\mu\text{V}$ + 10.36 dB/m + 0.40 dB = $30.76 \text{ dB}\mu\text{V/m}$ @ 3m

ANSI C63.4 Measurement Procedures: The EUT was placed on a non-conducting table 80 cm above the ground plane with the EUT located in the center of the table. With the antenna vertical a preliminary scan was done at 1 meters distance, the EUT was moved to a 3.0-meter distance and the antenna height varied and also placed in a horizontal position. The frequency was scanned from 9.0 kHz to 1.0 GHz. When an emission was found, the table was rotated to produce the maximum signal strength. The EUT was measured in three (3) orthogonal planes (as necessary).

Table of Contents

Applicant: KASTLE SYSTEMS INTERNATIONAL <u>Table Of Contents</u>

FCC ID: 2ALZS-AIO-W

Report: 787UT17TestReport_Rev Page 5 of 11



POWER LINE CONDUCTED INTERFERENCE

Rules Part No.: Part 15.107

Requirements:

Frequency (MHz)	Quasi Peak Limits (dBµV)	Average Limits (dBµV)					
0.15 - 0.5	66 – 56 *	56 – 46 *					
0.5 - 5.0	56	46					
5.0 - 30	60	50					
* Decrease with logarithm of frequency							

Test Data: The following plots represent the emissions read for power line conducted. Both lines were observed.

Table of Contents

Applicant: KASTLE SYSTEMS INTERNATIONAL

2ALZS-AIO-W

FCC ID: Report: 787UT17TestReport_Rev Page 6 of 11



POWER LINE CONDUCTED INTERFERENCE

Test Data: Line 1

25.May 17 09:55

Time Domain Scan (1 Range)

Scan Start: 150 kHz Scan Stop: 30 MHz

Detector: Trace 1: MAX PEAK Trace 2: Average

Transducer: tdf_21

Start			Ste	ор				Ste	ер								Meas		RF				
Frequ	ency		Fre	eque	ency	r		Siz	ze		- 1	Res	ви	/			Time		Atten		Pre	amp	Input
150.0	00000	0 kH	z 3	0.0	0000	000	М	Hz	2.25	kHz		9	.00	0 }	κHz	2	500	ms	Auto		0 0	dΒ	INPUT2
*	Step	TD A	UTO E	PULS	E	Att	. 1	LO dB A	AUTO	RBW MT PREA		k H s F F	z										
dΒμV	90			Т	Τ	П	i	LIMI	т си	вск	PASS			П	1	o i	ннг						
1 PK	-80-			\dagger	$^{+}$	H	t						Н	\forall	†	H				SOL			
2 AV	-70			+	+	H	+		-				Н	+	+	H				TDF			
HAXH	-60			\perp	+	H	+		_				_	_	+					TDF			
	-50					Ц	ļ								1								
	40				\pm	Ħ	t													220			
																				AC AC			
	-30-	M	4	\top	Ť	Ħ	t						ı		Ť	Ħ							
	20			\dashv	+	H	+	_			-		N _a	١,	+	Н							
	10	~~		m	houle	w	4	Mucha	Malpon		للنا	W		1		J	116.4	W	is at the				
	10-				١.	П	T						j,	ŀ	1		W-04-M	n. b.	1				

Final Measurement

 Meas Time:
 2 s

 Margin:
 30 dB

 Subranges:
 3

Trace	Frequenc	У	Level (dBµV)	Detecto	or	Delta Limit/dB		
1	150.000000000	kHz	32.73	Quasi	Peak	-33.27		
1	260.250000000	kHz	24.69	Quasi	Peak	-36.73		
1	5.943750000	MHz	24.06	Quasi	Peak	-35.94		

Page 1 of 2

Table of Contents

Applicant: KASTLE SYSTEMS INTERNATIONAL

FCC ID: 2ALZS-AIO-W

Report: 787UT17TestReport_Rev Page 7 of 11



POWER LINE CONDUCTED INTERFERENCE

Test Data: Line 2

25.May 17 09:52


Time Domain Scan (1 Range)

Scan Start: 150 kHz Scan Stop: 30 MHz

Detector: Trace 1: MAX PEAK Trace 2: Average

Transducer: tdf_21

Start		Stop	Step			Meas	RF		Input
Frequency		Frequency	Size		Res BW	Time	Atten	Preamp	
150.000000	kHz	30.000000 MH	z 2.25	kHz	9.00 kHz	500 ms	Auto	0 dB	INPUT2



Final Measurement

Meas Time: 2 s Margin: 30 dB Subranges: 5

Trace	Frequency		Level (dBµV)	Detector	Delta Limit/dB	
1	150.000000000	kHz	32.30	Quasi Peak	-33.70	
1	5.946000000	MHz	26.17	Quasi Peak	-33.83	
1	6.202500000	MHz	25.93	Quasi Peak	-34.07	
1	22.121250000	MHz	28.95	Quasi Peak	-31.05	
2	22.121250000	MHz	21.80	Average	-28.20	

Page 1 of 2

Table of Contents

Applicant: KASTLE SYSTEMS INTERNATIONAL

FCC ID: 2ALZS-AIO-W

Report: 787UT17TestReport_Rev Page 8 of 11



RADIATED SPURIOUS EMISSIONS

Rules Part No.: 15.109(a) and 15.209

Requirements: CARRIER FREQUENCY WILL NOT EXCEED 2400/F (kHz)uV/m

AT 300 METERS

OUT-OF-BAND EMISSIONS SHALL NOT EXCEED THE LEVEL OF

THE FUNDAMENTAL.

Frequency MHz	Limits		
9 – 490 kHz	2400/F (kHz) μV/m @ 300 meters		
490 – 1705 kHz	24000/F (kHz) μV/m @ 30 meters		
1705 – 30 MHz	29.54 dBµV/m measured @ 30 meters		
30 – 88	40.0 dBµV/m measured @ 3 meters		
88 – 216	43.5 dBµV/m measured @ 3 meters		
216 – 960	46.0 dBµV/m measured @ 3 meters		
Above 960	54.0 dBµV/m measured @ 3 meters		

The spectrum was scanned from 10 kHz to 1000 MHz.

Test Data:

Tuned Freq MHz	Emission Frequency MHz	Meter Reading dBu V		Antenna Polarity	Coax Loss Db	Correction Factor dB/M	Field Strength dBu V/M	Margin
0.125	0.125	88.39		V	0.43	11.38	100.19	5.47
0.125	9.96	26.73		V	0.65	10.60	37.98	31.50
0.125	20.13	25.47		V	0.70	10.08	36.25	33.23
0.125	29.28	23.15		V	0.74	8.56	32.45	37.03
0.125	29.76	36.47		V	0.67	8.45	45.59	23.89
0.125	90.64	25.17	*	Н	1.12	10.66	36.95	6.55
0.125	133.90	14.99	*	V	1.33	13.97	30.29	13.21
0.125	467.73	13.09	*	Н	2.49	17.02	32.60	13.40
0.125	511.02	12.95	*	V	2.62	17.60	33.17	12.83

^{*}denotes ambient measurement

Table of Contents

Applicant: KASTLE SYSTEMS INTERNATIONAL <u>Table Of Contents</u>

FCC ID: 2ALZS-AIO-W

Report: 787UT17TestReport_Rev Page 9 of 11



OCCUPIED BANDWIDTH

RULES PART NO.: 15.215 (c)

REQUIREMENTS: Intentional radiators operating under the alternative provisions to the general emission limits, as contained in §§15.217 through 15.257 and in subpart E of this part, must be designed to ensure that the 20 dB bandwidth of the emission, or whatever bandwidth may otherwise be specified in the specific rule section under which the equipment operates, is contained within the frequency band designated in the rule section under which the equipment is operated. In the case of intentional radiators operating under the provisions of subpart E, the emission bandwidth may span across multiple contiguous frequency bands identified in that subpart. The requirement to contain the designated bandwidth of the emission within the specified frequency band includes the effects from frequency sweeping, frequency hopping and other modulation techniques that may be employed as well as the frequency stability of the transmitter over expected variations in temperature and supply voltage

Test Data: 20dB Occupied Bandwidth Plot




Table of Contents

Applicant: KASTLE SYSTEMS INTERNATIONAL

FCC ID: 2ALZS-AIO-W

Report: 787UT17TestReport_Rev Page 10 of 11



TEST EQUIPMENT LIST

Device	Manufacturer	Model	Serial Number	Cal/Char Date	Due Date
Antenna: Biconical 1096 Chamber	Eaton	94455-1	1096	07/14/15	07/14/17
Antenna: Log-Periodic 1122	Electro- Metrics	LPA-25	1122	07/14/15	07/14/17
CHAMBER	Panashield	3M	N/A	04/25/16	12/31/17
Software: Field Strength Program	Timco	N/A	Version 4.10.7.0	12/12/99	N/A
EMI Test Receiver R & S ESU 40 Chamber	Rohde & Schwarz	ESU 40	100320	04/01/16	04/01/18
Coaxial Cable - Chamber 3 cable set (Primary)	Micro-Coax	Chamber 3 cable set (Primary)	KMKM-0244- 01; KMKM- 0670-00; KFKF-0198- 01	08/09/16	08/09/18
Bore-sight Antenna Positioning Tower	Sunol Sciences	TLT2	N/A	12/12/99	N/A
Pre-amp	RF-LAMBDA	RLNA00M45GA	NA	01/04/16	01/04/18
Coaxial Cable - BMBM- 1000-00 Silver	Semflex	LISN Cable	BMBM-1000- 00	01/05/17	01/05/18
LISN (Primary)	Electro- Metrics	ANS-25/2	2604	07/13/15	07/13/17
LISN (Secondary)	Electro- Metrics	EM-7820	2682	N/A	N/A

*EMI RECEIVER SOFTWARE VERSION

The receiver firmware used was version 4.43 Service Pack 3

END OF TEST REPORT

Table of Contents

Applicant: KASTLE SYSTEMS INTERNATIONAL Table Of Contents

2ALZS-AIO-W

FCC ID: Report: 787UT17TestReport_Rev Page 11 of 11