

7. Channel Number


7.1. Test Equipment

| | Equipment | Manufacturer | Model No./Serial No. | Last Cal. |
|---|-------------------|--------------|----------------------|------------|
| | Spectrum Analyzer | R&S | FSP40 / 100170 | Jun, 2012 |
| | Spectrum Analyzer | Agilent | E4407B / US39440758 | Jun, 2012 |
| X | Spectrum Analyzer | Agilent | N9010A / MY48030495 | Apr., 2013 |

Note: 1. All equipments are calibrated every one year.

2. The test instruments marked by "X" are used to measure the final test results.

7.2. Test Setup



7.3. Limit

Frequency hopping systems operating in the 2400-2483.5 MHz bands shall use at least 75 hopping frequencies.

7.4. Test Procedure

The EUT was setup to ANSI C63.10, 2009; tested to FHSS test procedure of FCC Public Notice DA 00-705 for compliance to FCC 47CFR 15.247 requirements.

7.5. Uncertainty

N/A



7.6. Test Result of Channel Number

Product : Tablet PC


Test Item : Channel Number
Test Site : No.3 OATS

Test Mode : Mode 1: Transmit - 1Mbps (GFSK)

| Frequency Range | Measurement | Required Limit | Result | |
|-----------------|-------------------|-------------------|--------|--|
| (MHz) | (Hopping Channel) | (Hopping Channel) | Result | |
| 2402 ~ 2480 | 79 | >75 | Pass | |


2402-2421MHz

2422-2441MHz



2442-2461MHz

2462-2480MHz






Test Item : Channel Number
Test Site : No.3 OATS

Test Mode : Mode 2: Transmit - 3Mbps (8DPSK)

| Frequency Range | Measurement | Required Limit | Result | |
|-----------------|-------------------|-------------------|--------|--|
| (MHz) | (Hopping Channel) | (Hopping Channel) | | |
| 2402 ~ 2480 | 79 | >75 | Pass | |


2402-2421MHz

2422-2441MHz



2442-2461MHz

2462-2480MHz





8. Channel Separation


8.1. Test Equipment

| | Equipment | Manufacturer | Model No./Serial No. | Last Cal. |
|---|-------------------|--------------|----------------------|------------|
| | Spectrum Analyzer | R&S | FSP40 / 100170 | Jun, 2012 |
| | Spectrum Analyzer | Agilent | E4407B / US39440758 | Jun, 2012 |
| X | Spectrum Analyzer | Agilent | N9010A / MY48030495 | Apr., 2013 |

Note: 1. All equipments are calibrated every one year.

2. The test instruments mark by "X" are used to measure the final test results.

8.2. Test Setup



8.3. Limit

Frequency hopping systems shall have hopping channel carrier frequencies separated by a minimum of 25 kHz or the 20 dB bandwidth of the hopping channel, whichever is greater.

8.4. Test Procedure

The EUT was setup to ANSI C63.10, 2009; tested to FHSS test procedure of FCC Public Notice DA 00-705 for compliance to FCC 47CFR 15.247 requirements.

8.5. Uncertainty

± 150Hz



8.6. Test Result of Channel Separation

Product : Tablet PC

Test Item : Channel Separation


Test Site : No.3 OATS

Test Mode : Mode 1: Transmit - 1Mbps (GFSK)

| | Fraguanay | Measurement | Limit | Limit of (2/3)*20dB | |
|-------------|--------------------|----------------|-----------------------|---------------------|--------|
| Channel No. | Frequency (MHz) | Level (kHz) | (kHz) Bandwidth (kHz) | | Result |
| 00 | 2402 | 1000 | >25 kHz | 753.3 | Pass |
| 39 | 2441 | 1000 | >25 kHz | 753.3 | Pass |
| 78 | 2480 | 1000 | >25 kHz | 753.3 | Pass |


NOTE: The 20dB Bandwidth is refer to section 10.

Channel 00 2402MHz






Channel 39 2441MHz



Channel 78 2480 MHz





Test Item : Channel Separation


Test Site : No.3 OATS

Test Mode : Mode 2: Transmit - 3Mbps (8DPSK)

| Channel No. | Frequency | Measurement | Limit | Limit of (2/3)*20dB | |
|-------------|-----------|---------------------|---------|---------------------|--------|
| | (MHz) | Level (kHz) (kHz | | Bandwidth (kHz) | Result |
| 00 | 2402 | 1000 | >25 kHz | 946.7 | Pass |
| 39 | 2441 | 1000 | >25 kHz | 953.3 | Pass |
| 78 | 2480 | 1000 | >25 kHz | 946.7 | Pass |


NOTE: The 20dB Bandwidth is refer to section 10.

Channel 00 2402MHz






Channel 39 2441MHz



Channel 78 2480 MHz





9. **Dwell Time**


9.1. Test Equipment

| | Equipment | Manufacturer | Model No./Serial No. | Last Cal. |
|---|-------------------|--------------|----------------------|------------|
| | Spectrum Analyzer | R&S | FSP40 / 100170 | Jun, 2012 |
| | Spectrum Analyzer | Agilent | E4407B / US39440758 | Jun, 2012 |
| X | Spectrum Analyzer | Agilent | N9010A / MY48030495 | Apr., 2013 |

Note: 1. All equipments are calibrated every one year.

2. The test instruments marked by "X" are used to measure the final test results.

9.2. Test Setup



9.3. Limit

The dwell time shall be the average time of occupancy on any frequency shall not be greater than 0.4 seconds within a 30 second period.

9.4. Test Procedure

The EUT was setup to ANSI C63.10, 2009; tested to FHSS test procedure of FCC Public Notice DA 00-705 for compliance to FCC 47CFR 15.247 requirements.

9.5. Uncertainty

± 25msec



9.6. Test Result of Dwell Time

Product : Tablet PC
Test Item : Dwell Time
Test Site : No.3 OATS

Test Mode : Mode 1: Transmit - 1Mbps (GFSK) (Channel 00,39,78 –DH5)


| Frequency (MHz) | Time slot length (ms) | Hopping of Number | Sweep time (ms) | Duty cycle | Dwell Time (Sec) | Limit (Sec) | Result |
|-----------------|-----------------------------|----------------------|-----------------|------------|---------------------|-------------|--------|
| 2402 | 2.890 | 13 | 50 | 0.75 | 0.301 | 0.4 | Pass |
| 2441 | 2.890 | 13 | 50 | 0.75 | 0.301 | 0.4 | Pass |
| 2480 | 2.880 | 13 | 50 | 0.75 | 0.300 | 0.4 | Pass |

Duty cycle =((Time slot length(ms)*Hopping of Number) / Sweep time (ms)

Dwell time = (Duty cycle /79) * (79*0.4)


CH 00 Time Interval between hops

CH 00 Transmission Time



CH39 Time Interval between hops

CH 39Transmission Time




Page: 62 of 75



CH 78 Time Interval between hops

CH 78 Transmission Time



Note:

The dwell times of the packet type of DH1, DH3, and DH5 are tested. Only the worst case is shown on the report.



Product : Tablet PC
Test Item : Dwell Time
Test Site : No.3 OATS

Test Mode : Mode 2: Transmit - 3Mbps (8DPSK) (Channel 00,39,78 –DH5)


| Frequency (MHz) | Time slot length (ms) | Hopping of Number | Sweep time (ms) | Duty cycle | Dwell Time (Sec) | Limit (Sec) | Result |
|-----------------|-----------------------------|----------------------|-----------------|------------|---------------------|-------------|--------|
| 2402 | 1.640 | 13 | 50 | 0.43 | 0.171 | 0.4 | Pass |
| 2441 | 1.640 | 13 | 50 | 0.43 | 0.171 | 0.4 | Pass |
| 2480 | 1.640 | 13 | 50 | 0.43 | 0.171 | 0.4 | Pass |

Duty cycle =((Time slot length(ms)*Hopping of Number) / Sweep time (ms)

Dwell time = (Duty cycle /79) * (79*0.4)


CH 00 Time Interval between hops

CH 00 Transmission Time



CH39 Time Interval between hops


CH 39Transmission Time





CH 78 Time Interval between hops

CH 78 Transmission Time



Note:

The dwell times of the packet type of DH1, DH3, and DH5 are tested. Only the worst case is shown on the report.



10. Occupied Bandwidth


10.1. Test Equipment

| | Equipment | Manufacturer | Model No./Serial No. | Last Cal. |
|---|-------------------|--------------|----------------------|------------|
| | Spectrum Analyzer | R&S | FSP40 / 100170 | Jun, 2012 |
| | Spectrum Analyzer | Agilent | E4407B / US39440758 | Jun, 2012 |
| X | Spectrum Analyzer | Agilent | N9010A / MY48030495 | Apr., 2013 |

Note: 1. All equipments are calibrated every one year.

2. The test instruments marked by "X" are used to measure the final test results.

10.2. Test Setup



10.3. Limits

N/A

10.4. Test Procedure

The EUT was setup to ANSI C63.10, 2009; tested to FHSS test procedure of FCC Public Notice DA 00-705 for compliance to FCC 47CFR 15.247 requirements.

10.5. Uncertainty

± 150Hz



10.6. Test Result of Occupied Bandwidth

Product : Tablet PC


Test Item : Occupied Bandwidth Data

Test Site : No.3 OATS

Test Mode : Mode 1: Transmit - 1Mbps (GFSK)(2402MHz)

| Channel No. | Frequency (MHz) | Measurement Level (kHz) | Required Limit (kHz) | Result |
|-------------|-----------------|-------------------------|-------------------------|--------|
| 00 | 2402 | 1130 | | NA |

Figure Channel 00:






Test Item : Occupied Bandwidth Data

Test Site : No.3 OATS

Test Mode : Mode 1: Transmit - 1Mbps (GFSK)(2441MHz)

| Channel No. | Frequency (MHz) | Measurement Level (kHz) | Required Limit (kHz) | Result |
|-------------|-----------------|-------------------------|-------------------------|--------|
| 39 | 2441 | 1130 | | NA |

Figure Channel 39:






Test Item : Occupied Bandwidth Data

Test Site : No.3 OATS

Test Mode : Mode 1: Transmit - 1Mbps (GFSK)(2480MHz)

| Channel No. | Frequency (MHz) | Measurement Level (kHz) | Required Limit (kHz) | Result |
|-------------|-----------------|-------------------------|-------------------------|--------|
| 78 | 2480 | 1130 | | NA |

Figure Channel 78:






Test Item : Occupied Bandwidth Data

Test Site : No.3 OATS

Test Mode : Mode 2: Transmit - 3Mbps (8DPSK) (2402MHz)

| Channel No. | Frequency (MHz) | Measurement Level (kHz) | Required Limit (kHz) | Result |
|-------------|-----------------|-------------------------|----------------------|--------|
| 00 | 2402 | 1420 | | NA |

Figure Channel 00:






Test Item : Occupied Bandwidth Data

Test Site : No.3 OATS

Test Mode : Mode 2: Transmit - 3Mbps (8DPSK) (2441MHz)

| Channel No. | Frequency (MHz) | Measurement Level (kHz) | Required Limit (kHz) | Result |
|-------------|-----------------|-------------------------|-------------------------|--------|
| 39 | 2441 | 1430 | | NA |

Figure Channel 39:






Test Item : Occupied Bandwidth Data

Test Site : No.3 OATS

Test Mode : Mode 2: Transmit - 3Mbps (8DPSK)(2480MHz)

| Channel No. | Frequency (MHz) | Measurement Level (kHz) | Required Limit (kHz) | Result |
|-------------|-----------------|-------------------------|-------------------------|--------|
| 78 | 2480 | 1420 | | NA |

Figure Channel 78:





11. EMI Reduction Method During Compliance Testing

No modification was made during testing.



Attachment 1: EUT Test Photographs



Attachment 2: EUT Detailed Photographs