

FCC RF Test Report

APPLICANT : CT Asia

EQUIPMENT : **GSM** mobile phone

BRAND NAME : BLU
MODEL NAME : Deejay
FCC ID : YHLBLUDJ

STANDARD : FCC 47 CFR Part 2, 22(H), 24(E)

CLASSIFICATION : PCS Licensed Transmitter Held to Ear (PCE)

Tx/Rx FREQUENCY RANGE : GSM850 : 824.2 ~ 848.8 MHz /

869.2 ~ 893.8 MHz

GSM1900: 1850.2 ~ 1909.8 MHz / 1930.2 ~ 1989.8 MHz

CMOEO (CCM) : 0.74 W

MAX. ERP/EIRP POWER : GSM850 (GSM) : 0.71 W

GSM1900 (GSM): 1.00 W

EMISSION DESIGNATOR : 246KGXW

The product was received on Sep. 08, 2010 and completely tested on Sep. 23, 2010. We, SPORTON INTERNATIONAL (KUNSHAN) INC., would like to declare that the tested sample has been evaluated in accordance with the procedures given in ANSI / TIA / EIA-603-C-2004 and shown compliance with the applicable technical standards.

The test results in this report apply exclusively to the tested model / sample. Without written approval of SPORTON INTERNATIONAL (KUNSHAN) INC., the test report shall not be reproduced except in full.

Reviewed by:

Anderson Chiu / Deputy Manager

Iac-MRA



Report No.: FG090824

SPORTON INTERNATIONAL (KUNSHAN) INC. No. 3-2, PingXiang Road, Kunshan, Jiangsu Province, P.R.C.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 1 of 37
Report Issued Date : Sep. 28, 2010

Report Version : Rev. 01



TABLE OF CONTENTS

| RE | VISIO | N HISTORY | 3 |
|----|--------|---|----|
| SL | IMMA | RY OF TEST RESULT | 4 |
| | | | |
| 1 | GEN | ERAL DESCRIPTION | 5 |
| | 1.1 | Applicant | 5 |
| | 1.2 | Manufacturer | |
| | 1.3 | Feature of Equipment Under Test | 5 |
| | 1.4 | Testing Site | 6 |
| | 1.5 | Applied Standards | 6 |
| | 1.6 | Ancillary Equipment List | 6 |
| 2 | TES | T CONFIGURATION OF EQUIPMENT UNDER TEST | 7 |
| | 2.1 | Test Mode | 7 |
| | 2.2 | Connection Diagram of Test System | |
| 3 | TES | T RESULT | 9 |
| | 3.1 | Conducted Output Power Measurement | 9 |
| | 3.2 | Effective Radiated Power and Effective Isotropic Radiated Power Measurement | |
| | 3.3 | Occupied Bandwidth Measurement | |
| | 3.4 | Band Edge Measurement | |
| | 3.5 | Conducted Emission Measurement | |
| | 3.6 | Field Strength of Spurious Radiation Measurement | 26 |
| | 3.7 | Frequency Stability Measurement | |
| 4 | LIST | OF MEASURING EQUIPMENT | 36 |
| 5 | UNC | ERTAINTY OF EVALUATION | 37 |
| ۸. | DENIF | DIX A. PHOTOGRAPHS OF EUT | |
| Αr | TENL | DIA A. FROTOGRAFRS OF EUT | |
| | יחרגים | NIV D. CETUD DUCTOOD ADUC | |

APPENDIX B. SETUP PHOTOGRAPHS

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 2 of 37 Report Issued Date : Sep. 28, 2010

Report No.: FG090824

Report Version : Rev. 01



REVISION HISTORY

| REPORT NO. | VERSION | DESCRIPTION | ISSUED DATE |
|------------|---------|-------------------------|---------------|
| FG090824 | Rev. 01 | Initial issue of report | Sep. 28, 2010 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 3 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



SUMMARY OF TEST RESULT

| Report Section | FCC Rule | IC Rule | Description | Limit | Result | Remark |
|-------------------|-------------------------------------|--|---|-------------------------------------|--------|---|
| 3.1 | §2.1046 | N/A | Conducted Output Power | N/A | PASS | - |
| 3.2 | §22.913(a)(2) | RSS-132(4.4) SRSP-503(5.1.3) | Effective Radiated Power | < 7 Watts | PASS | - |
| 3.2 | §24.232(c) | RSS-133 (6.4) SRSP-510(5.1.2) | Equivalent Isotropic Radiated Power | < 2 Watts | PASS | - |
| 3.3 | §2.1049 §22.917(a) §24.238(a) | N/A | Occupied Bandwidth | N/A | PASS | - |
| 3.4 | §2.1051 §22.917(a) §24.238(a) | 17(a) RSS-132 (4.5.1) Band Edge RSS-133 (6.5.1) Measurement | | < 43+10log ₁₀ (P[Watts]) | PASS | - |
| 3.5 | §2.1051 §22.917(a) §24.238(a) | RSS-132 (4.5.1) RSS-133 (6.5.1) | Conducted Emission | < 43+10log ₁₀ (P[Watts]) | PASS | - |
| 3.6 | §2.1053 §22.917(a) §24.238(a) | RSS-132 (4.5.1) RSS-133 (6.5.1) | Field Strength of Spurious Radiation | < 43+10log ₁₀ (P[Watts]) | PASS | Under limit 13.12 dB at 5640.00 MHz |
| 3.7 | §2.1055 §22.355 §24.235 | RSS-132(4.3) RSS-133(6.3) | Frequency Stability for Temperature & Voltage | < 2.5 ppm | PASS | - |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 4 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



1 General Description

1.1 Applicant

CT Asia

RMA2011, 20/F., GOLDEN CENTRAL TOWER, NO. 3037# JINTIAN ROAD, FUTIAN DISTRICT

1.2 Manufacturer

Telacom INT'L Limited (Shenzhen) Office

Office Tower 28/F., the Pavilion Hotel, Hua Qiang Bei Road 4002, Futian District, 518028, Shenzhen, P.R.C.

1.3 Feature of Equipment Under Test

| Product Feature & Specification | | | | | |
|---------------------------------|---|--|--|--|--|
| Equipment | GSM mobile phone | | | | |
| Brand Name | BLU | | | | |
| Model Name | Deejay | | | | |
| FCC ID | YHLBLUDJ | | | | |
| Tx Frequency | GSM850 : 824 MHz ~ 849 MHz GSM1900 : 1850 MHz ~ 1910 MHz | | | | |
| Rx Frequency | GSM850 : 869 MHz ~ 894 MHz GSM1900 : 1930 MHz ~ 1990 MHz | | | | |
| Maximum Output Power to Antenna | GSM850 : 32.38 dBm GSM1900 : 28.94 dBm | | | | |
| Maximum ERP/EIRP | GSM850 (GSM) : 0.71 W (28.52 dBm) GSM1900 (GSM) : 1.00 W (30.02 dBm) | | | | |
| Antenna Type | Fixed Internal Antenna | | | | |
| HW Version | M118D_P2 | | | | |
| SW Version | TL_M118DPU818_F05LK0A_00_26_100915 | | | | |
| Type of Modulation | GMSK | | | | |
| Type of Emission | 246KGXW | | | | |
| EUT Stage | Production Unit | | | | |

Remark:

- 1. For other wireless features of this EUT, the test report will be issued separately.
- 2. This test report recorded only product characteristics and test results of PCS Licensed Transmitter Held to Ear (PCE).
- **3.** The above EUT's information was declared by manufacturer. Please refer to the specifications or user's manual for more detailed description.
- **4.** This product has two versions, Single SIM and Dual SIM. And the difference of SIM can't relate any RF effect, so only Single SIM is used for the test.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 5 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



1.4 Testing Site

| Test Site | SPORTON INTERNATIONAL (KUNSHAN) INC. |
|--------------------|--|
| | No. 3-2, PingXiang Road, Kunshan, Jiangsu Province, P.R.C. |
| Test Site Location | TEL: +86-0512-5790-0158 |
| | FAX: +86-0512-5790-0958 |
| Took Site No. | Sporton Site No. |
| Test Site No. | TH01-KS; 03CH01-KS |

1.5 Applied Standards

According to the specifications of the manufacturer, the EUT must comply with the requirements of the following standards:

- FCC 47 CFR Part 2, 22(H), 24(E)
- ANSI / TIA / EIA-603-C-2004
- IC RSS-132 Issue 2
- IC RSS-133 Issue 5

Remark:

- 1. All test items were verified and recorded according to the standards and without any deviation during the test.
- 2. This EUT has also been tested and complied with the requirements of FCC Part 15, Subpart B, recorded in a separate test report.

1.6 Ancillary Equipment List

| Item | Equipment | Trade Name | Model No. | FCC ID | Data Cable | Power Cord |
|------|------------------|------------|-----------|--------|------------|-------------------|
| 1. | System Simulator | R&S | CMU200 | N/A | N/A | Unshielded, 1.8 m |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 6 of 37
Report Issued Date : Sep. 28, 2010

Report No.: FG090824

Report Version : Rev. 01



2 Test Configuration of Equipment Under Test

2.1 Test Mode

During all testing, EUT is in link mode with base station emulator at maximum power level. The spurious emission measurements were carried out in semi-anechoic chamber with 3-meter test range, and EUT is rotated on three test planes to find out the worst emission.

Frequency range investigated for radiated emission is as follows:

- 1. 30 MHz to 9000 MHz for GSM850.
- 30 MHz to 19000 MHz for GSM1900.

| Test Modes | | | | | | |
|------------|--------------|---------------|--|--|--|--|
| Band | Radiated TCs | Conducted TCs | | | | |
| GSM 850 | ■ GSM Link | ■ GSM Link | | | | |
| GSM 1900 | ■ GSM Link | ■ GSM Link | | | | |

Note: The maximum power levels are GSM mode for GMSK link, only these modes were used for all tests.

The conducted power tables are as follows:


| Conducted Power (*Unit: dBm) | | | | | | | |
|------------------------------|--------------------|-------------|-------|---------|--------|--------------------|--|
| Band | | GSM850 | | GSM1900 | | | |
| Channel | 128 | 128 189 251 | | | 661 | 810 | |
| Frequency | 824.2 | 836.4 | 848.8 | 1850.2 | 1880.0 | 1909.8 | |
| GSM | <mark>32.38</mark> | 32.15 | 32.06 | 28.19 | 28.50 | <mark>28.94</mark> | |
| GPRS 8 | 32.36 | 32.12 | 32.03 | 28.04 | 28.26 | 28.65 | |
| GPRS 10 | 32.02 | 31.80 | 31.75 | 27.34 | 27.70 | 28.27 | |
| GPRS 12 | 31.23 | 30.95 | 30.91 | 26.49 | 26.78 | 27.46 | |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 7 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



2.2 Connection Diagram of Test System



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 8 of 37
Report Issued Date : Sep. 28, 2010

Report Version : Rev. 01



3 Test Result

3.1 Conducted Output Power Measurement

3.1.1 Description of the Conducted Output Power Measurement

A base station simulator was used to establish communication with the EUT. Its parameters were set to transmit the maximum power on the EUT. The measured power in the radio frequency on the transmitter output terminals shall be reported.


3.1.2 Measuring Instruments

See list of measuring instruments of this test report.

3.1.3 Test Procedures

- 1. The transmitter output port was connected to base station.
- 2. Set EUT at maximum power through base station.
- 3. Select lowest, middle, and highest channels for each band and different modulation.

3.1.4 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 9 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01

3.1.5 Test Result of Conducted Output Power

| Cellular Band | | | | | | | |
|---------------|------------|--------------------|-----------------------------|-------------------------------|--|--|--|
| Modes | Channel | Frequency (MHz) | Conducted Power (dBm) | Conducted Power (Watts) | | | |
| | 128 (Low) | 824.2 | 32.38 | 1.73 | | | |
| GSM850 (GSM) | 189 (Mid) | 836.4 | 32.15 | 1.64 | | | |
| | 251 (High) | 848.8 | 32.06 | 1.61 | | | |

| PCS Band | | | | | | | |
|---------------|------------|--------------------|-----------------------------|-------------------------------|--|--|--|
| Modes | Channel | Frequency (MHz) | Conducted Power (dBm) | Conducted Power (Watts) | | | |
| | 512 (Low) | 1850.2 | 28.19 | 0.66 | | | |
| GSM1900 (GSM) | 661 (Mid) | 1880.0 | 28.50 | 0.71 | | | |
| | 810 (High) | 1909.8 | 28.94 | 0.78 | | | |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 10 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01

3.2 Effective Radiated Power and **Effective Isotropic Radiated Power Measurement**

3.2.1 Description of the ERP/EIRP Measurement

ERP/EIRP is measured by substitution method according to ANSI / TIA / EIA-603-C-2004. The ERP of mobile transmitters must not exceed 7 Watts and the EIRP of mobile transmitters are limited to 2 Watts.

3.2.2 Measuring Instruments

See list of measuring instruments of this test report.

3.2.3 Test Procedures

- 1. The EUT was placed on a turntable with 1.0 meter height in a fully anechoic chamber.
- 2. The EUT was set at 1.2 meters from the receiving antenna, which was mounted on the antenna tower.
- 3. The table was rotated 360 degrees to determine the position of the highest radiated power.
- 4. The height of the receiving antenna is adjusted to look for the maximum ERP/EIRP.
- 5. Taking the record of maximum ERP/EIRP.
- A dipole antenna was substituted in place of the EUT and was driven by a signal generator. 6.
- 7. The conducted power at the terminal of the dipole antenna is measured.
- 8. Repeat step 3 to step 5 to get the maximum ERP/EIRP of the substitution antenna.
- 9. ERP/EIRP = Ps + Et - Es + Gs = Ps + Rt - Rs + Gs

Ps (dBm): Input power to substitution antenna.

Gs (dBi or dBd): Substitution antenna Gain.

Et = Rt + AF

Es = Rs + AF

AF (dB/m): Receive antenna factor

Rt: The highest received signal in spectrum analyzer for EUT.

Rs: The highest received signal in spectrum analyzer for substitution antenna.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ


Page Number : 11 of 37 Report Issued Date : Sep. 28, 2010

Report No.: FG090824

Report Version : Rev. 01



3.2.4 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 12 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



3.2.5 Test Result of ERP

| GSM850 (GSM) Radiated Power ERP | | | | | | | |
|---------------------------------|-------------|-------------|--------------------|-------------|--------------|------------|--|
| | | Hoi | rizontal Polariza | tion | | | |
| Frequency (MHz) | Rt (dBm) | Rs (dBm) | Ps (dBm) | Gs (dBd) | ERP (dBm) | ERP (W) | |
| 824.20 | -19.91 | -48.12 | 0.00 | -1.08 | 27.13 | 0.52 | |
| 836.40 | -18.97 | -48.28 | 0.00 | -0.93 | 28.38 | 0.69 | |
| 848.80 | -19.07 | -48.35 | 0.00 | -0.76 | 28.52 | 0.71 | |
| | | Ve | ertical Polarizati | on | | | |
| Frequency (MHz) | Rt (dBm) | Rs (dBm) | Ps (dBm) | Gs (dBd) | ERP (dBm) | ERP (W) | |
| 824.20 | -32.98 | -47.97 | 0.00 | -1.08 | 13.91 | 0.02 | |
| 836.40 | -31.83 | -48.01 | 0.00 | -0.93 | 15.25 | 0.03 | |
| 848.80 | -31.36 | -48.05 | 0.00 | -0.76 | 15.93 | 0.04 | |

3.2.6 Test Result of EIRP

| GSM1900 (GSM) Radiated Power EIRP | | | | | | | |
|-----------------------------------|-------------|-------------|--------------------|-------------|---------------|-------------|--|
| | | Hoi | rizontal Polariza | tion | | | |
| Frequency (MHz) | Rt (dBm) | Rs (dBm) | Ps (dBm) | Gs (dBi) | EIRP (dBm) | EIRP (W) | |
| 1850.20 | -23.82 | -51.88 | 0.00 | 1.96 | 30.02 | 1.00 | |
| 1880.00 | -25.42 | -52.99 | 0.00 | 2.00 | 29.57 | 0.91 | |
| 1909.80 | -26.86 | -54.28 | 0.00 | 1.98 | 29.40 | 0.87 | |
| | | Ve | ertical Polarizati | on | | | |
| Frequency (MHz) | Rt (dBm) | Rs (dBm) | Ps (dBm) | Gs (dBi) | EIRP (dBm) | EIRP (W) | |
| 1850.20 | -28.23 | -52.13 | 0.00 | 1.96 | 25.86 | 0.39 | |
| 1880.00 | -29.50 | -53.17 | 0.00 | 2.00 | 25.67 | 0.37 | |
| 1909.80 | -30.19 | -54.13 | 0.00 | 1.98 | 25.92 | 0.39 | |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 13 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



3.3 Occupied Bandwidth Measurement

3.3.1 Description of Occupied Bandwidth Measurement

The emission bandwidth is defined as the width of the signal between two points, located at the 2 sides of the carrier frequency, outside of which all emissions are attenuated at least 26 dB below the transmitter power.


3.3.2 Measuring Instruments

See list of measuring instruments of this test report.

3.3.3 Test Procedures

- 1. The EUT was connected to Spectrum Analyzer and Base Station via power divider.
- 2. The 99% and 26 dB occupied bandwidth (BW) of the middle channel for the highest RF powers were measured.

3.3.4 Test Setup



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ


Page Number : 14 of 37 Report Issued Date: Sep. 28, 2010 Report Version : Rev. 01



3.3.5 Test Result (Plots) of Occupied Bandwidth


| Band : | GSM 850 | Power Stage : | High |
|-------------|----------|---------------|------|
| Test Mode : | GSM Link | | |

99% Occupied Bandwidth Plot on Channel 189



Date: 16.SEP.2010 08:07:19

26dB Bandwidth Plot on Channel 189



Date: 16.SEP.2010 08:06:00


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ

Page Number : 15 of 37 Report Issued Date : Sep. 28, 2010 Report Version : Rev. 01




| Band : | GSM 1900 | Power Stage : | High |
|-------------|----------|---------------|------|
| Test Mode : | GSM Link | | |

99% Occupied Bandwidth Plot on Channel 661



Date: 16.SEP.2010 08:49:45

26dB Bandwidth Plot on Channel 661



Date: 16.SEP.2010 08:48:26

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 16 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



3.4 Band Edge Measurement

3.4.1 Description of Band Edge Measurement

The power of any emission outside of the authorized operating frequency ranges must be lower than the transmitter power (P) by a factor of at least 43 + 10 log (P) dB.

3.4.2 Measuring Instruments


See list of measuring instruments of this test report.

3.4.3 Test Procedures

- 1. The EUT was connected to Spectrum Analyzer and Base Station via power divider.
- 2. The band edges of low and high channels for the highest RF powers were measured. Setting RBW as roughly BW/100.

3.4.4 Test Setup

<Conducted Band Edge >



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 17 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



3.4.5 Test Result (Plots) of Conducted Band Edge


| Band : | GSM850 | Power Stage : | High |
|-------------|----------|---------------|------|
| Test Mode : | GSM Link | | |

Lower Band Edge Plot on Channel 128



Date: 16.SEP.2010 08:09:12

Higher Band Edge Plot on Channel 251



Date: 16.SEP.2010 08:09:38


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ

Page Number : 18 of 37 Report Issued Date : Sep. 28, 2010 Report Version : Rev. 01




| Band : | GSM1900 | Power Stage : | High |
|-------------|----------|---------------|------|
| Test Mode : | GSM Link | | |

Lower Band Edge Plot on Channel 512



Date: 16.SEP.2010 08:51:37

Higher Band Edge Plot on Channel 810



Date: 16.SEP.2010 08:52:04

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 19 of 37 Report Issued Date : Sep. 28, 2010

Report No.: FG090824

Report Version : Rev. 01



3.5 Conducted Emission Measurement

3.5.1 Description of Conducted Emission Measurement

The power of any emission outside of the authorized operating frequency ranges must be lower than the transmitter power (P) by a factor of at least 43 + 10 log (P) dB.

It is measured by means of a calibrated spectrum analyzer and scanned from 30 MHz up to a frequency including its 10th harmonic.


3.5.2 Measuring Instruments

See list of measuring instruments of this test report.

3.5.3 Test Procedures

- 1. The EUT was connected to spectrum analyzer and base station via power divider.
- 2. The middle channel for the highest RF power within the transmitting frequency was measured.
- 3. The conducted spurious emission for the whole frequency range was taken.

3.5.4 Test Setup




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 20 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



3.5.5 Test Result (Plots) of Conducted Emission


| Band : | GSM850 | Channel: | CH189 |
|-------------|----------|----------|-------|
| Test Mode : | GSM Link | | |

Conducted Emission Plot between 30MHz ~ 1GHz



Date: 16.SEP.2010 08:33:47

Conducted Emission Plot between 1GHz ~ 3GHz



Date: 16.SEP.2010 09:30:45


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 21 of 37
Report Issued Date : Sep. 28, 2010

Report No.: FG090824

Report Version : Rev. 01








Date: 16.SEP.2010 09:31:28

Conducted Emission Plot between 7GHz ~ 9GHz



Date: 16.SEP.2010 09:32:15


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 22 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



Band: GSM1900 Channel: CH661


Test Mode: GSM Link

Conducted Emission Plot between 30MHz ~ 1GHz



Date: 16.SEP.2010 09:05:56

Conducted Emission Plot between 1GHz ~ 3GHz




Date: 16.SEP.2010 09:10:05

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ








Date: 16.SEP.2010 09:22:32

Conducted Emission Plot between 7GHz ~ 13.6GHz




Date: 16.SEP.2010 09:17:05

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 24 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



Conducted Emission Plot between 13.6GHz ~ 19.1GHz



Date: 16.SEP.2010 09:18:51

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 25 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01

3.6 Field Strength of Spurious Radiation Measurement

3.6.1 Description of Field Strength of Spurious Radiated Measurement

The radiated spurious emission was measured by substitution method according to ANSI / TIA / EIA-603-C-2004. The power of any emission outside of the authorized operating frequency ranges must be attenuated below the transmitter power (P) by a factor of at least 43 + 10 log (P) dB. The spectrum is scanned from 30 MHz up to a frequency including its 10th harmonic.

3.6.2 Measuring Instruments

See list of measuring instruments of this test report.


3.6.3 Test Procedures

- 1. The EUT was placed on a rotatable wooden table with 0.8 meter about ground.
- 2. The EUT was set 3 meters from the receiving antenna, which was mounted on the antenna tower.
- 3. The table was rotated 360 degrees to determine the position of the highest spurious emission.
- 4. The height of the receiving antenna is varied between one meter and four meters to search the maximum spurious emission for both horizontal and vertical polarizations.
- 5. Make the measurement with the spectrum analyzer's RBW = 1MHz, VBW = 3MHz, Sweep = 500ms, Taking the record of maximum spurious emission.
- 6. A horn antenna was substituted in place of the EUT and was driven by a signal generator.
- 7. Tune the output power of signal generator to the same emission level with EUT maximum spurious emission.
- 8. Taking the record of output power at antenna port.
- 9. Repeat step 7 to step 8 for another polarization.
- 10. EIRP (dBm) = S.G. Power Tx Cable Loss + Tx Antenna Gain
- 11. ERP (dBm) = EIRP 2.15

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 26 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01




3.6.4 Test Setup




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 27 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



3.6.5 Test Result of Field Strength of Spurious Radiated



Spurious emissions within 30-1000MHz were found more than 20dB below limit line. Remark:



: 03CH01-KS Site

Condition: FCC PART22 24 HF EIRP FACTOR-09020 HORIZONTAL

: Mode 1 Mode plane : H

| - 2 | ASSOCIATION OF | | | | | | | | |
|-----------|----------------|-------|--------|---------|--------|----------|------------|--------------|--------|
| Frequency | ERP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 1672 | -36.71 | -13 | -23.71 | -37.13 | -37.36 | 0.57 | 3.37 | Н | Pass |
| 2510 | -47.40 | -13 | -34.40 | -50.03 | -49.63 | 0.78 | 5.16 | Н | Pass |
| 3345 | -60.46 | -13 | -47.46 | -62.40 | -64.10 | 0.87 | 6.66 | Н | Pass |
| 4182 | -57.66 | -13 | -44.66 | -62.25 | -62.25 | 0.97 | 7.71 | Н | Pass |
| 5018 | -57.90 | -13 | -44.90 | -63.10 | -63.57 | 1.09 | 8.91 | Н | Pass |
| 5856 | -47.03 | -13 | -34.03 | -55.74 | -53.47 | 1.22 | 9.81 | Н | Pass |
| 6692 | -44.98 | -13 | -31.98 | -56.30 | -52.20 | 1.25 | 10.62 | Н | Pass |
| 7526 | -50.75 | -13 | -37.75 | -63.52 | -58.65 | 1.42 | 11.47 | Н | Pass |
| 8366 | -48.05 | -13 | -35.05 | -61.09 | -56.63 | 1.5 | 12.23 | Н | Pass |


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ

Page Number : 28 of 37 Report Issued Date : Sep. 28, 2010 Report Version : Rev. 01



Band :GSM850Temperature :22~23°CTest Mode :GSM LinkRelative Humidity :41~42%Test Engineer :Feixiang RuiPolarization :Vertical

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-KS

Condition: FCC PART22 24 HF EIRP FACTOR-09020 VERTICAL

Mode : Mode 1 plane : H

| Frequency | ERP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 1674 | -28.66 | -13 | -15.66 | -33.99 | -29.31 | 0.57 | 3.37 | V | Pass |
| 2510 | -45.92 | -13 | -32.92 | -50.48 | -48.15 | 0.78 | 5.16 | V | Pass |
| 3345 | -61.55 | -13 | -48.55 | -63.53 | -65.19 | 0.87 | 6.66 | V | Pass |
| 4182 | -52.90 | -13 | -39.90 | -56.74 | -57.49 | 0.97 | 7.71 | V | Pass |
| 5018 | -57.90 | -13 | -44.90 | -62.84 | -63.57 | 1.09 | 8.91 | V | Pass |
| 5854 | -52.73 | -13 | -39.73 | -60.72 | -59.17 | 1.22 | 9.81 | V | Pass |
| 6692 | -43.41 | -13 | -30.41 | -62.12 | -50.63 | 1.25 | 10.62 | V | Pass |
| 7526 | -49.76 | -13 | -36.76 | -62.90 | -57.66 | 1.42 | 11.47 | V | Pass |
| 8364 | -50.81 | -13 | -37.81 | -62.97 | -59.39 | 1.50 | 12.23 | V | Pass |


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 29 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01

Band: GSM1900 Temperature: 22~23°C

Test Mode: GSM Link Relative Humidity: 41~42%

Test Engineer: Feixiang Rui Polarization: Horizontal

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-KS

Condition: FCC PART22 24 HF EIRP FACTOR-09020 HORIZONTAL

Mode : Mode 1 plane : H

| Frequency | EIRP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 3760 | -43.00 | -13 | -30.00 | -48.75 | -49.38 | 0.78 | 7.16 | Н | Pass |
| 5640 | -28.79 | -13 | -15.79 | -42.33 | -37.33 | 1.04 | 9.58 | Н | Pass |
| 7520 | -33.42 | -13 | -20.42 | -49.47 | -43.53 | 1.35 | 11.46 | Н | Pass |
| 9400 | -58.13 | -13 | -45.13 | -61.39 | -69.19 | 1.75 | 12.81 | Н | Pass |
| 11280 | -54.07 | -13 | -41.07 | -65.56 | -65.16 | 2 | 13.09 | Н | Pass |
| 13160 | -50.33 | -13 | -37.33 | -62.04 | -62.04 | 2.04 | 13.75 | Н | Pass |


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 30 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01

Band: GSM1900 Temperature: 22~23°C

Test Mode: GSM Link Relative Humidity: 41~42%

Test Engineer: Feixiang Rui Polarization: Vertical

Remark: Spurious emissions within 30-1000MHz were found more than 20dB below limit line.



Site : 03CH01-KS

Condition: FCC PART22 24 HF EIRP FACTOR-09020 VERTICAL

Mode : Mode 1 plane : H

| Frequency | EIRP | Limit | Over | SPA | S.G. | TX Cable | TX Antenna | Polarization | Result |
|-----------|--------|-------|--------|---------|--------|----------|------------|--------------|--------|
| | | | Limit | Reading | Power | loss | Gain | | |
| (MHz) | (dBm) | (dBm) | (dB) | (dBm) | (dBm) | (dB) | (dBi) | (H/V) | |
| 3760 | -54.54 | -13 | -41.54 | -55.91 | -60.92 | 0.78 | 7.16 | V | Pass |
| 5640 | -26.12 | -13 | -13.12 | -40.47 | -34.66 | 1.04 | 9.58 | V | Pass |
| 7520 | -28.34 | -13 | -15.34 | -46.02 | -38.45 | 1.35 | 11.46 | V | Pass |
| 9400 | -59.25 | -13 | -46.25 | -60.47 | -70.31 | 1.75 | 12.81 | V | Pass |
| 11280 | -53.19 | -13 | -40.19 | -64.43 | -64.28 | 2 | 13.09 | V | Pass |
| 13160 | -52.76 | -13 | -39.76 | -63.95 | -64.47 | 2.04 | 13.75 | V | Pass |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 31 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01

3.7 Frequency Stability Measurement

3.7.1 Description of Frequency Stability Measurement

The frequency stability shall be measured by variation of ambient temperature and variation of primary supply voltage to ensure that the fundamental emission stays within the authorized frequency block. The frequency stability of the transmitter shall be maintained within ±0.00025% (±2.5ppm) of the center frequency.

Report No.: FG090824

3.7.2 Measuring Instruments

See list of measuring instruments of this test report.

3.7.3 Test Procedures for Temperature Variation

- 1. The EUT was set up in the thermal chamber and connected with the base station.
- With power OFF, the temperature was decreased to -30°C and the EUT was stabilized for three
 hours. Power was applied and the maximum change in frequency was recorded within one
 minute.
- 3. With power OFF, the temperature was raised in 10°C step up to 50°C. The EUT was stabilized at each step for at least half an hour. Power was applied and the maximum frequency change was recorded within one minute.
- 4. If the EUT can not be turned on at -30°C, the testing lowest temperature will be raised in 10°C step until the EUT can be turned on.

3.7.4 Test Procedures for Voltage Variation

- 1. The EUT was placed in a temperature chamber at 25±5° C and connected with the base station.
- 2. The power supply voltage to the EUT was varied from BEP to 115% of the nominal value measured at the input to the EUT.

Page Number

Report Version

: 32 of 37


: Rev. 01

Report Issued Date: Sep. 28, 2010

3. The variation in frequency was measured for the worst case.



3.7.5 Test Setup



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 33 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01

3.7.6 Test Result of Temperature Variation

| Band : | GSM 850 | Channel: | 189 |
|--------------|---------|----------|-----|
| Limit (ppm): | 2.5 | | |

| | GSM | | | | | |
|---------------------|--------------------|--------------------|--------|--|--|--|
| Temperature (°C) | Freq. Dev. (Hz) | Deviation (ppm) | Result | | | |
| -30 | -17 | -0.02 | | | | |
| -20 | 19 | 0.02 | | | | |
| -10 | 23 | 0.03 | | | | |
| 0 | 26 | 0.03 | | | | |
| 10 | 25 | 0.03 | PASS | | | |
| 20 | -12 | -0.01 | | | | |
| 30 | -16 | -0.02 | | | | |
| 40 | -19 | -0.02 | | | | |
| 50 | -11 | -0.01 | | | | |

| Band : | GSM 1900 | Channel: | 661 |
|--------------|----------|----------|-----|
| Limit (ppm): | 2.5 | | |

| _ , | GSM | | | |
|---------------------|--------------------|-----------------|--------|--|
| Temperature (°C) | Freq. Dev. (Hz) | Deviation (ppm) | Result | |
| -30 | 54 | 0.03 | | |
| -20 | 33 | 0.02 | | |
| -10 | 34 | 0.02 | | |
| 0 | 31 | 0.02 | | |
| 10 | 34 | 0.02 | PASS | |
| 20 | -24 | -0.01 | | |
| 30 | -27 | -0.01 | | |
| 40 | -26 | -0.01 | | |
| 50 | -28 | -0.01 | | |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 34 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



3.7.7 Test Result of Voltage Variation

| Band & Channel | Mode | Voltage (Volt) | Freq. Dev. (Hz) | Deviation (ppm) | Limit (ppm) | Result |
|-------------------|------|-------------------|--------------------|--------------------|----------------|--------|
| GSM 850 CH189 | GSM | 3.8 | -15 | -0.02 | 2.5 | PASS |
| | | BEP | -24 | -0.03 | | |
| | | 4.2 | -16 | -0.02 | | |
| GSM 1900 CH661 | GSM | 3.8 | -31 | -0.02 | | |
| | | BEP | -24 | -0.01 | | |
| | | 4.2 | -28 | -0.01 | | |

Note:

- 1. Normal Voltage = 3.8V.
- 2. Battery End Point (BEP) = 3.4 V.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 35 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



List of Measuring Equipment

| Instrument | Manufacturer | Model No. | Serial No. | Characteristics | Calibration Date | Due Date | Remark |
|------------------------------|--------------|-----------|------------|-----------------|---------------------|---------------|--------------------------|
| Spectrum Analyzer | R&S | FSP40 | 100319 | 9kHz~40GHz | Jan. 18, 2010 | Jan. 17, 2011 | Conducted (TH01-KS) |
| Thermal Chamber | Ten Billion | TTC-B3S | TBN-960502 | N/A | Dec. 28, 2009 | Dec. 27, 2010 | Conducted (TH01-KS) |
| EMI Test Receiver | R&S | ESCI | 100724 | 9kHz – 2.75GHz | Mar. 09, 2010 | Mar. 08, 2011 | Radiation (03CH01-KS) |
| Spectrum Analyzer | R&S | FSP40 | 100319 | 9kHz~40GHz | Jan. 18, 2010 | Jan. 17, 2011 | Radiation (03CH01-KS) |
| Bilog Antenna | SCHAFFNER | CBL6112D | 23182 | 25MHz~2GHz | Jan. 18, 2010 | Jan. 17, 2011 | Radiation (03CH01-KS) |
| Double Ridge Horn Antenna | EMCO | 3117 | 00075959 | 1GHz~18GHz | Jan. 18, 2010 | Jan. 17, 2011 | Radiation (03CH01-KS) |
| Amplifier | Wireless | FPA-6592G | 060004 | 30MHz~2GHz | Feb. 02, 2010 | Feb. 01, 2011 | Radiation (03CH01-KS) |
| Amplifier | Agilent | 8449B | 3008A02370 | 1GHz~26.5GHz | Jan. 18, 2010 | Jan. 17, 2011 | Radiation (03CH01-KS) |
| Actice hore antenna | com-power | AHA-118 | 701023 | 1G-18GHz | Nov. 18, 2009 | Nov. 17, 2010 | Radiation (03CH01-KS) |
| Signal Generator | R&S | SMR40 | 100455 | 10MHz~40GHz | Jan. 18, 2010 | Jan. 17, 2011 | Radiation (03CH01-KS) |
| SHF-EHF Horn | Schwarzbeck | BBHA 9170 | BBHA170249 | 15-40GHz | Oct. 22, 2009 | Oct. 21, 2010 | Radiation (03CH01-KS) |
| Loop Antenna | R&S | HFH2-Z2 | 860004/001 | 9 kHz~30 MHz | Jul. 29, 2010 | Jul. 28, 2011 | Radiation (03CH01-KS) |
| System Simulator | R&S | CMU200 | 837587/066 | Full-Band | Jan. 08, 2009 | Jan. 07, 2011 | Radiation (03CH01-KS) |

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ

: 36 of 37 Page Number Report Issued Date : Sep. 28, 2010

Report No.: FG090824

Report Version : Rev. 01



5 Uncertainty of Evaluation

Uncertainty of Radiated Emission Measurement (30 MHz ~ 1000 MHz)

| | Uncerta | | | |
|---|---------------|-----------------------------|--------------------|--|
| Contribution | dB | Probability Distribution | u(X _i) | |
| Receiver Reading | 0.41 | Normal (k=2) | 0.21 | |
| Antenna Factor Calibration | 0.83 | Normal (k=2) | 0.42 | |
| Cable Loss Calibration | 0.25 | Normal (k=2) | 0.13 | |
| Pre-Amplifier Gain Calibration | 0.27 | Normal (k=2) | 0.14 | |
| RCV/SPA Specification | 2.50 | Rectangular | 0.72 | |
| Antenna Factor Interpolation for Frequency | 1.00 | Rectangular | 0.29 | |
| Site Imperfection | 1.43 | Rectangular | 0.83 | |
| Mismatch | +0.39 / -0.41 | U-Shape | 0.28 | |
| Combined Standard Uncertainty Uc(y) | 1.27 | | | |
| Measuring Uncertainty for a Level of Confidence of 95% (U = 2Uc(y)) | 2.54 | | | |

Uncertainty of Radiated Emission Measurement (1 GHz ~ 40 GHz)

| | Uncertainty of X _i | | | | |
|--|-------------------------------|-----------------------------|--------------------|----------------|-------------------------------------|
| Contribution | dB | Probability Distribution | u(X _i) | C _i | C _i * u(X _i) |
| Receiver Reading | ±0.10 | Normal (k=2) | 0.10 | 1 | 0.10 |
| Antenna Factor Calibration | ±1.70 | Normal (k=2) | 0.85 | 1 | 0.85 |
| Cable Loss Calibration | ±0.50 | Normal (k=2) | 0.25 | 1 | 0.25 |
| Receiver Correction | ±2.00 | Rectangular | 1.15 | 1 | 1.15 |
| Antenna Factor Directional | ±1.50 | Rectangular | 0.87 | 1 | 0.87 |
| Site Imperfection | ±2.80 | Triangular | 1.14 | 1 | 1.14 |
| Mismatch Receiver VSWR Γ 1 = 0.197 Antenna VSWR Γ 2 = 0.194 Uncertainty = 20Log(1- Γ 1* Γ 2) | +0.34 / -0.35 | U-Shape | 0.244 | 1 | 0.244 |
| Combined Standard Uncertainty Uc(y) | 2.36 | | | | |
| Measuring Uncertainty for a Level of Confidence of 95% (U = 2Uc(y)) | 4.72 | | | | |

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 37 of 37
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01

Appendix A. Photographs of EUT

Please refer to Sporton report number EP090824 as below.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : A1 of A1
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01