


| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 41 of 63 |

Test Mode: Transmitting Mode

30MHz -1GHz



Test Data


Vertical Polarity Plot @3m

| No. | P/L | Frequency | Reading | Detect | Ant_F | PA_G | Cab_L | Result | Limit | Margin | Height | Degr |
|-----|-------|-----------|----------|--------|--------|-------|-------|----------|----------|--------|--------|------|
| | - , - | | | or | | | | | | | | ее |
| | | (MHz) | (dBuV/m) | | (dB/m) | (dB) | (dB) | (dBuV/m) | (dBuV/m) | (dB) | (cm) | () |
| 1 | V | 50.4089 | 35.94 | peak | 8.36 | 22.38 | 0.80 | 22.72 | 40.00 | -17.28 | 100 | 219 |
| 2 | ٧ | 79.8003 | 33.10 | peak | 7.60 | 22.42 | 1.05 | 19.33 | 40.00 | -20.67 | 200 | 28 |
| 3 | > | 120.2766 | 27.46 | peak | 13.88 | 22.36 | 1.16 | 20.14 | 43.50 | -23.36 | 100 | 253 |
| 4 | > | 175.6516 | 32.60 | peak | 11.35 | 22.25 | 1.36 | 23.06 | 43.50 | -20.44 | 100 | 199 |
| 5 | ٧ | 299.3158 | 28.23 | peak | 13.57 | 22.29 | 1.79 | 21.30 | 46.00 | -24.70 | 100 | 8 |
| 6 | V | 661.1505 | 28.60 | peak | 19.77 | 21.45 | 2.61 | 29.53 | 46.00 | -16.47 | 100 | 44 |



| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 42 of 63 |

30MHz -1GHz



Horizontal Polarity Plot @3m

| N | P/ | Frequency | Reading | Detect | Ant_F | PA_G | Cab_L | Result | Limit | Margin | Height | Degr |
|----|----|-----------|---------|--------|--------|-------|-------|----------|----------|--------|--------|------|
| 0. | L | | | or | | | | | | | | ее |
| | | (MHz) | (dBuV/m | | (dB/m) | (dB) | (dB) | (dBuV/m) | (dBuV/m) | (dB) | (cm) | () |
| | | |) | | | | | | | | | |
| 1 | Н | 312.1794 | 29.02 | peak | 13.86 | 22.26 | 1.85 | 22.47 | 46.00 | -23.53 | 100 | 55 |
| 2 | Н | 397.6334 | 27.07 | peak | 15.65 | 22.02 | 2.01 | 22.71 | 46.00 | -23.29 | 100 | 42 |
| 3 | Н | 785.0935 | 25.45 | peak | 21.22 | 21.18 | 2.93 | 28.42 | 46.00 | -17.58 | 100 | 65 |
| 4 | Н | 193.0945 | 28.24 | peak | 11.72 | 22.34 | 1.54 | 19.16 | 43.50 | -24.34 | 100 | 8 |
| 5 | Н | 99.5281 | 29.02 | peak | 10.29 | 22.32 | 1.11 | 18.10 | 43.50 | -25.40 | 200 | 354 |
| 6 | Н | 44.2752 | 25.58 | peak | 11.08 | 22.29 | 0.76 | 15.13 | 40.00 | -24.87 | 100 | 81 |



| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 43 of 63 |

Above 1GHz

Low Channel (2412 MHz) (b mode worst case)

| Frequency (MHz) | S.A. Reading (dBµV) | Detector (PK/AV) | Polarity (H/V) | Ant. Factor (dB/m) | Cable Loss (dB) | Pre-Amp. Gain (dB) | Cord Amp. (dBµV/m) | Limit (dBµV/m) | Margin (dB) |
|--------------------|---------------------------|---------------------|-------------------|--------------------------|-----------------------|--------------------------|--------------------------|-------------------|----------------|
| 4824 | 48.07 | AV | V | 33.39 | 7.22 | 48.46 | 40.22 | 54 | -13.78 |
| 4824 | 43.06 | AV | Ι | 33.39 | 7.22 | 48.46 | 35.21 | 54 | -18.79 |
| 4824 | 66.39 | PK | ٧ | 33.39 | 7.22 | 48.46 | 58.54 | 74 | -15.46 |
| 4824 | 62.91 | PK | Н | 33.39 | 7.22 | 48.46 | 55.06 | 74 | -18.94 |
| 12404 | 18.2 | AV | ٧ | 41.14 | 12.74 | 46.74 | 25.34 | 54 | -28.66 |
| 12404 | 19.57 | AV | Н | 41.14 | 12.74 | 46.74 | 26.71 | 54 | -27.29 |
| 12404 | 39.63 | PK | V | 41.14 | 12.74 | 46.74 | 46.77 | 74 | -27.23 |
| 12404 | 40.49 | PK | Н | 41.14 | 12.74 | 46.74 | 47.63 | 74 | -26.37 |

Middle Channel (2437 MHz) (b mode worst case)

| Frequency (MHz) | S.A. Reading (dBµV) | Detector (PK/AV) | Polarity (H/V) | Ant. Factor (dB/m) | Cable Loss (dB) | Pre-Amp. Gain (dB) | Cord Amp. (dBµV/m) | Limit (dBµV/m) | Margin (dB) |
|--------------------|---------------------------|---------------------|-------------------|--------------------------|-----------------------|--------------------------|--------------------------|-------------------|----------------|
| 4874 | 45.49 | AV | V | 33.62 | 7.53 | 48.36 | 38.28 | 54 | -15.72 |
| 4874 | 46.86 | AV | Ι | 33.62 | 7.53 | 48.36 | 39.65 | 54 | -14.35 |
| 4874 | 66.35 | PK | ٧ | 33.62 | 7.53 | 48.36 | 59.14 | 74 | -14.86 |
| 4874 | 62.99 | PK | Н | 33.62 | 7.53 | 48.36 | 55.78 | 74 | -18.22 |
| 9553 | 39.56 | AV | V | 39.3 | 9.09 | 47.21 | 40.74 | 54 | -13.26 |
| 9553 | 37.86 | AV | Н | 39.3 | 9.09 | 47.21 | 39.04 | 54 | -14.96 |
| 9553 | 49.68 | PK | V | 39.3 | 9.09 | 47.21 | 50.86 | 74 | -23.14 |
| 9553 | 48.49 | PK | Н | 39.3 | 9.09 | 47.21 | 49.67 | 74 | -24.33 |



| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 44 of 63 |

High Channel (2462 MHz) (b mode worst case)

| Frequency (MHz) | S.A. Reading (dBµV) | Detector (PK/AV) | Polarity (H/V) | Ant. Factor (dB/m) | Cable Loss (dB) | Pre-Amp. Gain (dB) | Cord Amp. (dBµV/m) | Limit (dBµV/m) | Margin (dB) |
|--------------------|---------------------------|---------------------|-------------------|--------------------------|-----------------------|--------------------------|--------------------------|-------------------|----------------|
| 4924 | 42.34 | AV | V | 33.74 | 7.78 | 48.34 | 35.52 | 54 | -18.48 |
| 4924 | 43.93 | AV | Н | 33.74 | 7.78 | 48.34 | 37.11 | 54 | -16.89 |
| 4924 | 61.21 | PK | V | 33.74 | 7.78 | 48.34 | 54.39 | 74 | -19.61 |
| 4924 | 56.97 | PK | Ι | 33.74 | 7.78 | 48.34 | 50.15 | 74 | -23.85 |
| 17885 | 20.58 | AV | V | 41.95 | 17.84 | 45.46 | 34.91 | 54 | -19.09 |
| 17885 | 18.72 | AV | Ι | 41.95 | 17.84 | 45.46 | 33.05 | 54 | -20.95 |
| 17885 | 38.93 | PK | V | 41.95 | 17.84 | 45.46 | 53.26 | 74 | -20.74 |
| 17885 | 41.74 | PK | Н | 41.95 | 17.84 | 45.46 | 56.07 | 74 | -17.93 |

Note:

- 1, The testing has been conformed to 10*2462MHz=24,620MHz
- 2, All other emissions more than 30 dB below the limit
- 3, X-Axis, Y-Axis and Z-Axis were investigated. The results above show only the worst case.
- 4, The radiated spurious test above 18GHz is subcontracted to SIEMIC (Nanjing-China) Laboratories. and found 30dB below the limit at least.



| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 45 of 63 |

Annex A. TEST INSTRUMENT

| Instrument | Model | Serial# | Cal Date | Cal Due | In use |
|---|----------|-------------|------------|------------|-------------|
| AC Line Conducted | | | | | |
| EMI test receiver | ESCS30 | 8471241027 | 09/15/2017 | 09/14/2018 | > |
| Line Impedance | LI-125A | 191106 | 09/23/2017 | 09/22/2018 | • |
| Line Impedance | LI-125A | 191107 | 09/23/2017 | 09/22/2018 | • |
| ISN | ISN T800 | 34373 | 09/23/2017 | 09/22/2018 | |
| Transient Limiter | LIT-153 | 531118 | 08/30/2017 | 08/29/2018 | ✓ |
| RF conducted test | | | | | |
| Agilent ESA-E SERIES | E4407B | MY45108319 | 09/15/2017 | 09/14/2018 | > |
| Power Splitter | 1# | 1# | 08/30/2017 | 08/29/2018 | ~ |
| DC Power Supply | E3640A | MY40004013 | 09/15/2017 | 09/14/2018 | > |
| Radiated Emissions | | | | | |
| EMI test receiver | ESL6 | 100262 | 09/15/2017 | 09/14/2018 | • |
| Positioning Controller | UC3000 | MF780208282 | 11/17/2017 | 11/16/2018 | • |
| OPT 010 AMPLIFIER | 04475 | 0707400400 | 00/00/0047 | 00/00/0040 | _ |
| (0.1-1300MHz) | 8447E | 2727A02430 | 08/30/2017 | 08/29/2018 | • |
| Horn Antenna | BBHA9170 | 3145226D1 | 09/27/2017 | 09/26/2018 | \ |
| Microwave Preamplifier (1 ~ 26.5GHz) | 8449B | 3008A02402 | 03/23/2017 | 03/22/2018 | > |
| Active Antenna (9kHz-30MHz) | AL-130 | 121031 | 10/12/2017 | 10/11/2018 | <u><</u> |
| Bilog Antenna (30MHz~6GHz) | JB6 | A110712 | 09/19/2017 | 09/18/2018 | > |
| Double Ridge Horn Antenna (1 ~18GHz) | AH-118 | 71283 | 09/22/2017 | 09/21/2018 | V |
| Universal Radio Communication Tester | CMU200 | 121393 | 09/23/2017 | 09/22/2018 | V |



| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 46 of 63 |


Annex B. EUT and Test Setup Photographs

Annex B.i. Photograph: EUT External Photo





Adapter View





| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 47 of 63 |

EUT - Front View



EUT - Rear View






| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 48 of 63 |

EUT - Top View




EUT - Bottom View






| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 49 of 63 |

EUT - Left View




EUT - Right View





| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 50 of 63 |

Annex B.ii. Photograph: EUT Internal Photo





Cover Off - Top View 2





| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 51 of 63 |

Battery - Front View



Battery - Rear View






| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 52 of 63 |

Mainboard with Shielding - Front View



Mainboard with Shielding - Rear View






| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 53 of 63 |

Mainboard without Shielding - Rear View




Small Mainboard - Front View





| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 54 of 63 |

Small Mainboard - Rear View



LCD - Front View





| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 55 of 63 |

LCD - Rear View



GSM/PCS/UMTS-FDD - Antenna View





| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 56 of 63 |


WIFI/BT/BLE/GPS - Antenna View





| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 57 of 63 |


Annex B.iii. Photograph: Test Setup Photo



Conducted Emissions Test Setup Front View



Conducted Emissions Test Setup Side View



Radiated Spurious Emissions Test Setup Below 1GHz



Radiated Spurious Emissions Test Setup Above 1GHz




| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 58 of 63 |

Annex C. TEST SETUP AND SUPPORTING EQUIPMENT

Annex C.ii. TEST SET UP BLOCK


Block Configuration Diagram for AC Line Conducted Emissions





| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 59 of 63 |


Block Configuration Diagram for Radiated Emissions (Below 1GHz).





| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 60 of 63 |

Block Configuration Diagram for Radiated Emissions (Above 1GHz) .





| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 61 of 63 |

Annex C. il. SUPPORTING EQUIPMENT DESCRIPTION

The following is a description of supporting equipment and details of cables used with the EUT.

Supporting Equipment:

| Manufacturer | Equipment Description | Model | Serial No |
|--------------------|--------------------------|----------------|-----------|
| BLU Products, Inc. | Adapter | TPA-46050150UU | N/A |
| BLU Products, Inc. | headset | HORIZON R2 | N/A |

Supporting Cable:

| Cable type | Shield Type | Ferrite Core | Length | Serial No |
|-------------|--------------|--------------|--------|-----------|
| Power Cable | Un-shielding | No | 0.8m | N/A |



| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 62 of 63 |

Annex D. User Manual / Block Diagram / Schematics / Partlist Please see the attachment



| Test Report No. | 18070843-FCC-R4 |
|-----------------|-----------------|
| Page | 63 of 63 |

Annex E. DECLARATION OF SIMILARITY

BLU Products, Inc.

To: SIEMIC, 775 Montague Expressway, Milpitas, CA95035, USA

Declaration Letter

Dear Sir,

For our business issue and marketing requirement, we'd like to shift the main and serial model numbers in the reports, No.17071301, as following:

Main Model No.: C6

Serial Model No.: STUDIO J7

And we'd like to use all the former data in the reports of 17071301.

We declare that each of the model's PCB, antenna and appearance shape, accessories are the same. The difference between the two is model name only.

Thank you!

Signature:

Printed name/title: Zeng wei

Address: Address: 10814 NW 33rd St # 100 Doral, FL 33172

Zerg Wei