

POWER BOARD Change Part





After Schematic


Change list

Item	before	after	비고
Varistor	10D331	10D471	Value change
Bridge Diode	DBS10	DF1510S	Part change
Thermisitor	-	WTR08D100M	Circuit add
Transistor	APT13003EZ(EU)TR-G1	KSC5026M	Part change

Power board photos

Before





After



