Discrimination Analysis Report

Relay Settings

Relay	Pickup Current (A)	Time Dial	Curve Type
1	1.00	1.00	IEC Standard Inverse
2	2.00	2.00	IEC Standard Inverse

Fault Levels

Analysis performed at: 1234.0A

Coordination Results

1 \rightarrow 2: Coordinated

Fault Current (A)	Time Margin (s)	Status
1234.0	1.13	✓

Time-Current Curves




Figure 1: Time-Current Characteristic Curves and Discrimination Margins