
DI8L9-01

Headrest Limit Switch Circuit

CIRCUIT DESCRIPTION

The rear RH seat ECU is detecting the condition of the headrest limit switch.

WIRING DIAGRAM



INSPECTION PROCEDURE

HINT:

Incase of using the LEXUS hand-held tester, start the inspection from step of and incase of the LEXUS hand-held tester, start from step 2.

1[]

Check[the[headrest[]imit[switch[using[LEXUS[hand-held[tester.

PREPARATION:

Connect@he@LEXUS@hand-held@ester@o@he@DLC3.

CHECK:

Check@he@headrest@imit@switch@using@DATA@LIST.



Proceed_to_next_circuit_inspection_shown_on problem_symptom_table_see_page_DI-765).

NG

2 | Check[headrest[limit[switch[See[page[BE-13]]).

NG□

Replace[the[limit[switch.

OK

3 Check[harness[and[connector[between[rear[RH[seat[ECU[and[]imit[switch,]imit switch[and[body[ground[See[page[N-35].

OK□

Repair or replace harness or connector.

NG

Proceed to next circuit nspection shown n problem symptoms table See page DI-765).