
DI7PF-03

## 22. Radio broadcast cannot be received. Bad reception



No

Take measures for contact.

Yes

5	Is antenna terminal on glass surface in contact with the defogger terminal?
	No Take measures for contact.
Yes	
6	Is there continuity in antenna cord?
	No Replace antenna cord.
Yes	
7	Check grounding of antenna, antenna cord and noise filter.
	NG Grounding failure.
ОК	
8	Does condition get better by replacing antenna cord?
	Yes Replace antenna cord.
No	
Repla	ce rear window glass.