
Migration Assistant

Temporary Windows Profiles – Quick Manual Fix




1. Open the Registry as an administrator...



4. Locate the offending entries with the .bak extensions...



2. Find the registry profiles...



5. Rename the temporary profile (without ".bak") to .tmp and remove ".bak" from the correct profile.

```
S-1-5-21-1343024091-2000478354-725345543-1222

added): Imp/to/thestemporary

S-1-5-21-1343024091-2000478354-725345543-3340

profile 24091-2000478354-725345543-3377

S-1-5-21-1343024091-2000478354-725345543-5879

S-1-5-21-1343024091-2000478354-725345543-5879.

S-1-5-21-1343024091-2000478354-725345543-5879.

S-1-5-21-851980644-979844176-2155038653-1001

Profile Notification
```

3. Locate the matching profiles to the .bak entries...



Managing the profiles in this fashion helps preserve things. Simply removing the .bak from the offending profile is an option but you run the risk of migrating bad data.

Note: If the TM does not have another registry entry, minus the .bak extension, then just delete the entry with .bak
If accounts are not removed via
Advanced system settings you risk causing this.

https://docs.microsoft.com/en-us/windows/deployment/usmt/usmt-best-practices