


01 POWER / INPUT FILTER


H01: likely S-120845 LDO. Nominal 4.5 V is a candidate, not a measured rail.



Empty options: R1/C3 free ends join regulated VDD; R2/C4 free ends join GND.


02 PIC CONTROLLER / CLOCK / ICSP

Users: RA3/R14, RA4/R15, RA5/R16, RC0/R11, RC6/R13, RC2 -> TP3; R80 -> TP16 / Q2; VREF tie withdrawn, RC1 -> R18 via V053-V070.



03 MOTOR / BUTTON / BATTERY INTERFACE

Users: PIC15/RC4 -> INA pin2; PIC16/RC5 -> INB pin3. Motor output polarity remains Inferred.




Q1: R1A -> FMOS3401A PMOS candidate, Battery+ at D3; post-Q1 supply at S2; G1 via R44.

H06c S1 common pairs and normally-open action measured. RC timing unmeasured.

04 ANTENNA EXCITATION / LOGIC / INDICATOR

H07: C14R inverter candidate. C6 parallels C5 by photo: Q8 source rail supported by B37.




IMG_2431: TP3/PIC13 drives R6/R7/D1 midpoint. Diode Identity and timing unverified.

05 RF RECEIVE / GAIN / ENVELOPE


H10-H12: working topology around photographed 120k feedback resistors. Filters, bias, and interstage routes inferred.

Q7: 11.2 kohm V064-V070 flts R18+R19. Supply-switch topology inferred; RC1 drives R18 via V053-V070.




06 SWITCHED ANTENNA CAPACITANCE

H13: 2H devices are probably PHP BJTs (MMBTA55 family; P8SS5140T is an alternative). Capacitor values unknown.



07 PIR / AUXILIARY RAIL

H14-H15: C2N supports S-812C33AMC 3.3V LDO. C/R3 ground supported by resistance.



READING THIS WORKING RECONSTRUCTION

One sheet. Functional wiring is proposed; this is not a verified production circuit.

148 retained catalog entries; unsupported TP9 and R33 entries withdrawn.

H_L^* = Inferred Inter-block net. Other set names do not imply measurement.

² on a part value or pin function means an estimate or candidate identity.

the following table presents comparative information about the membership of each

PIC pads have local nets; some onward routes remain unresolved.

DNP = unpopulated. An open pin means unresolved, not a certified no-con

PIR daughterboard Internals are not yet traced; J3 represents its Interface

No capacitor value or rail voltage in this drawing was electrically measured.

v0.9.34 | KICad 10.0.5 | 2026-10-09

S1 contact pairs and normally-open action verified: F05 closed

KiCad 10 libraries + four datasheet symbols | MCP authoring

Sheet: /

File: PetSafe_1001339.kicad_sch

Title: PetSafe 100-1339 R03

Size: A2	
----------	--

ev: 0.9,34

1/1