



Legacy OTA extra characterization | TT / 1.8 V / 27 C
Returned data reviewed; full original acceptance remains incomplete


10 pF and 20 pF fail the margin limit



All four steps settle; margin is a separate requirement



Original rules pass sampled points 0.8 to 1.2 V



Stationary noise: 401.15 nV/sqrt(Hz) at 1 kHz

