

Resolution Document: Context Definition Deployment Error — SalesTransactionContextExt

1. Overview

This document provides the resolution steps for a Salesforce CML deployment failure involving the **Context Definition** `SalesTransactionContextExt`.

The deployment may fail with one or both of the following errors:

1. A **Context Attribute deletion** error involving
`FOLI_is_supplemental_Order__c`.
2. A **mappedContextDefinition** change error involving the Salesforce ID
`11Oau000000PW6LEAW`.

This document captures the resolution steps performed and provides a repeatable procedure for future deployments.

2. Issue 1 — Context Attribute Being Deleted

Error Message

```
Context Attribute is being deleted:
FOLI_is_supplemental_Order__c
from node FulfillmentTransactionItem
```

Root Cause

The Context Definition being deployed contains a difference between the source/promotion branch and the target org.

Salesforce detects that the following Context Attribute is being removed from the `FulfillmentTransactionItem` node:

```
FOLI_is_supplemental_Order__c
```

This can happen when:

- The attribute exists in the target org but is not present in the metadata being deployed.
- The attribute was unintentionally removed from the source Context Definition.
- The attribute is no longer required and should be removed from the target org.

Resolution

Step 1 — Check the deployment XML

Verify that the following Context Attribute is present in the XML being deployed:

```
FOLI_is_supplemental_Order__c
```

The attribute should exist under the appropriate:

```
FulfillmentTransactionItem
```

node.

Step 2 — If the attribute is required

If `FOLI_is_supplemental_Order__c` is still required:

- Add/restore the attribute in the Context Definition XML.

- Ensure the XML represents the expected Context Definition configuration.
- Commit the change to the promotion branch.
- Re-run the deployment.

Step 3 — If the attribute is no longer required

If `FOLI_is_supplemental_Order__c` is intentionally being removed:

- Confirm that the attribute is no longer required by downstream functionality.
- Remove `FOLI_is_supplemental_Order__c` from the target org.
- Re-run the deployment.

Important: Do not remove the target attribute simply to make the deployment pass unless the business and technical owners have confirmed that the attribute is no longer required.

3. Issue 2 — mappedContextDefinition Changed

Error Message

```
SalesTransactionContextExt
Context Definition
0
0
mappedContextDefinition changed for 110au000000PW6LEAW
new value: SalesTransactionContextExt
```

Root Cause

This issue is related to the `mappedContextDefinition` value in the Context Definition metadata.

The Salesforce Context Definition contains a mapping to another Context Definition using a Salesforce ID.

In Production, the mapping is represented by the Salesforce ID:

```
110au000000PW6LEAW
```

However, the version being promoted contains:

```
<mappedContextDefinition>SalesTransactionContextExt</mappedContextDefinition>
```

Salesforce therefore detects the mapping as a change:

```
110au000000PW6LEAW
```

↓

```
SalesTransactionContextExt
```

This is a known Salesforce issue/bug, and a Salesforce Support Case has been opened for this behavior.

4. Resolution for Issue 2

The workaround is to align the promotion branch with the mapping currently present in Production.

Step 1 — Retrieve the Latest Context Definition from Production

Get the latest version of the relevant Context Definition from Production.

Identify:

```
SalesTransactionContextExt
```

and inspect the XML for the node containing the `mappedContextDefinition`.

Step 2 — Identify the Production Salesforce ID

In the Production version, identify the node where the Salesforce ID is used.

The expected Production mapping is:

```
110au000000PW6LEAW
```

Step 3 — Update the Promotion Branch

In the promotion branch, locate:

```
<mappedContextDefinition>SalesTransactionContextExt</mappedContextDefinition>
```

Change it to:

```
<mappedContextDefinition>110au000000PW6LEAW</mappedContextDefinition>
```

Before

```
<mappedContextDefinition>SalesTransactionContextExt</mappedContextDefinition>
```

After

```
<mappedContextDefinition>110au000000PW6LEAW</mappedContextDefinition>
```

Step 4 — Commit the Change

Commit the updated Context Definition XML to the promotion branch.

Example:

```
Fix mappedContextDefinition for SalesTransactionContextExt
```


Step 5 — Re-run the Deployment


After the change has been committed:

1. Re-run the CML deployment.
 2. Verify that the `mappedContextDefinition` error is no longer reported.
 3. Verify that there are no additional Context Attribute deletion errors.
 4. Validate the deployed Context Definition in the target org.
-

5. Complete Resolution Procedure

When the deployment fails with these errors, use the following sequence.





6. Validation Checklist

Before re-running the deployment, verify the following:

Context Attribute

- ☐ FOLI_is_supplemental_Order__c exists in the deployment XML if it is required.
- ☐ The attribute is under the correct FulfillmentTransactionItem node.
- ☐ If the attribute is no longer required, it has been intentionally removed from the target org.
- ☐ No dependent configuration still references the attribute.

Context Definition Mapping

- ☐ Latest Context Definition has been retrieved from Production.
- ☐ Production `mappedContextDefinition` value has been identified.
- ☐ Promotion branch has been updated to use the Production Salesforce ID.
- ☐ The following value is used where applicable:

```
<mappedContextDefinition>11Oau000000PW6LEAW</mappedContextDefinition>
```

- ☐ Changes have been committed.
 - ☐ CML deployment has been re-run.
 - ☐ Deployment completes successfully.
-

7. Important Considerations

Do not blindly replace Context Definition names with IDs

The Salesforce ID should be obtained from the **latest Production Context Definition**. Do not assume or manually construct the ID.

Validate the Production version first

Production should be treated as the source of truth for the `mappedContextDefinition` value when applying this workaround.

Salesforce Known Issue / Support Case

The `mappedContextDefinition` behavior is associated with a Salesforce bug. A Salesforce Support Case has been opened to track the issue.

The workaround documented here should therefore be considered a deployment workaround until Salesforce provides a permanent fix.

8. Summary

The CML deployment issue can be resolved by addressing the two errors independently:

Issue	Error	Resolution
Issue 1	Context Attribute is being deleted: FOlI_is_supplemental_Order__c	Ensure the attribute exists in the deployment XML if required; otherwise intentionally remove it from the target org
Issue 2	mappedContextDefinition changed for 110au000000PW6LEAW	Obtain the latest Production Context Definition and update the promotion branch to use the Production Salesforce ID

Final Workaround

Change:

```
<mappedContextDefinition>SalesTransactionContextExt</mappedContextDefinition>
```

to:

```
<mappedContextDefinition>110au000000PW6LEAW</mappedContextDefinition>
```

Commit the change and re-run the CML deployment.