Oracle Utilities Customer to Meter v25.10HOT

Product Fix Design

Bug 39004385

Last Modified: April 8, 2026 1:28 AM
Printed On: November 29, 2022

Oracle Utilities Customer Care and Billing Product Fix Design

Copyright 2026 by Oracle. All rights reserved.

The information contained in this document is proprietary and confidential to Oracle and is subject to the non-disclosure obligations described in the license agreement between your company and Oracle. You may not provide this document or any copy of this document to third parties outside your company unless you first obtain the written permission of Oracle.

This document introduces new and changed business and technical features that Oracle has included in the ”Single Fix” described in this document.

The functionality of the Single Fix described in this document may be superseded by functionality included in a future Single Fix, Release or Update. Oracle reserves the right to revise or expand the functionality of any future Single Fix, Release or Update of Oracle Utilities Customer Care and Billing in a manner compatible with Oracle’s business objectives, and the business objectives of each of Oracle’s customers, at the time that Oracle makes the software code generally commercially available.

Oracle will provide you with additional information concerning product Releases or Updates after Oracle finalizes the related specifications and tests the product component(s). Final documentation will be shipped to you with the media containing the Release or Update.

Please contact Oracle Customer Service Group if you have any questions or comments concerning this document, which has been prepared for your benefit as a licensee of Oracle Utilities Customer Care and Billing.

 Copyright ©2026, Oracle. All rights reserved.

Table of Contents

Reported Issue....3
Description....3
Steps to Recreate....3

Solution Design....6
Summary....6
Other Changes....6
Service Script....6

Data Clean-Up / Fixes....7

Recommended Test Cases....7
Test Case 1: Verifying X1-ServicePoint. createServicePoint operation....7
Test Case 2: Verifying X1-ServicePoint. updateServicePoint operation....8
Test Case 2.1: Verify whether SP chars applicable to both D1 SP and C1 SP are synchronized correctly....8
Test Case 2.2: Verify error for missing char value in input for a required char....10
Test Case 3: Verify no duplicate ODM SP sync requests (Regression for Bug 38504075)....11
Test Case 4: Verify defaulting and sync of required SP chars on create SP through UI....12

Reported Issue

Description

- When a Service Point is created or updated using X1-ServicePoint IWS, the Service Point characteristics are getting updated only on the MDM (D1) side and are not being synchronized to the corresponding CCB (C1) Service Point. As a result, there is a data inconsistency of Service Point characteristics between the D1 (MDM) SP and C1 (CCB) SP char tables.

Steps to Recreate

- Frame the HTTP Method POST operation (createServicePoint) by providing following input through REST Client or View Specification
  - **HTTP Method:** POST
  - **Request URI:** https://ipAddress:portNum/spl/rest/apis/cross/v-model/servicePoints
  - **Sample Request**

```
{
  "sourceStatus": "****",
```

Copyright ©2026, Oracle. All rights reserved.

```
    "servicePointType": {
      "servicePointType": "*****"
    },
    "timeZone": {
      "timeZone": "*********"
    },
    "premise": {
      "premiseId": "**********"
    },
    "characteristicList": {
      "_data": [
        {
          "characteristicType": {
            "characteristicType": "********"
          },
          "effectiveDate": "**********",
          "value": "*******"
        }
      ]
    }
  }
```


- **Response:**


```
    {
      "_self": "/rest/apis/cross/v-model/servicePoints/************",
      "servicePointId": "************",
      "servicePointType": {
    .
    .
    .
    .
    .
      "equipments": {},
      "characteristicList": {
        "_data": [
          {
```


 Copyright ©2026, Oracle. All rights reserved.

```
            "characteristicType": {
              "characteristicType": “BENCHID”,
              "_link": "*************"
            },
            "typeOfCharacteristicValue": "***",
            "effectiveDate": "**********",
            "value": "*",
            "characteristicValue": "*",
            "version": *
          }
        ]
      }
    }
```


- **DB Verification:**
- Characteristics Table for the D1 SP Created in the above Req:



- Characteristics Table for the C1 SP Created in the above Req:



- **Expected Result:** The Service Point should be created successfully, and the chars should stay in sync between C1 and D1 SP char tables.
- **Actual Result:** The Service Point is created successfully, but the chars are not in sync, resulting in discrepancies between C1 and D1 SP char tables.

Copyright ©2026, Oracle. All rights reserved.

Solution Design

- Modify the X1ServicePnt IWS script to ensure the characteristic sync logic for CCB SP is invoked as needed.
- Enhance the X1-SpCharUpd SS to synchronize only those Service Point chars that are applicable to the C1 SP entity, ensuring consistency between D1 and C1 without redundant updates.

Summary

Change Type	Y/N
Does this fix require any Admin (Soft) Table Changes to be made by the client?	N
Does this fix require upgrade data changes to be applied?	N
Does the fix involve DB Changes?	N
Is there an impact on any user interface or any other on-line behavior?	N
Is there an impact on any batch process?	N
Is there an impact on CM – Custom Modification processing?	N
Does this fix require an application viewer update for Algorithm data (run F1-AVALG)?	N
Does this fix require an application viewer update for MO data (run F1-AVMO)?	N
Does this fix require an application viewer update for Table data (run F1-AVTBL)?	N

Other Changes

Service Script

Service Point Service (X1ServicePnt) (Existing)

- Step 20(Existing)
  - Modify the SS logic to get the SP char list from the newly created D1 SP, then for each char if it already exists in the inbound SP chars keep the inbound value otherwise add the char to inbound, and finally set ccbSpExists to true.
- Step 30(Existing)
  - Update the script logic to set ccbSpExists to true.

CCB-MDM Service Point Char Update (X1-SpCharUpd) (Existing)

- Step 10(Existing)

 Copyright ©2026, Oracle. All rights reserved.

- Modify the SS logic so that only SP chars applicable to the C1 SP entity are synced to C1, and flattened D1-only chars are not synced.

Data Clean-Up / Fixes

- None

Recommended Test Cases

Test Case 1: Verifying X1-ServicePoint. createServicePoint operation

- Frame the HTTP Method POST operation (createServicePoint) by providing following input through REST Client or View Specification
  - **HTTP Method:** POST
  - **Request URI:** https://ipAddress:portNum/spl/rest/apis/cross/v-model/servicePoints
  - **Sample Request**

```
{
  "sourceStatus": "****",
  "servicePointType": {
    "servicePointType": "*****"
  },
  "timeZone": {
    "timeZone": "*********"
  },
  "premise": {
    "premiseId": "**********"
  },
  "characteristicList": {
    "_data": [
      {
        "characteristicType": {
          "characteristicType": "********"          // D1-only (flattened) characteristic
        },
```

Copyright ©2026, Oracle. All rights reserved.

```
            "effectiveDate": "**********",
            "value": "*******"
          }
        ]
      }
    }
```

- **Expected Result:** The Service Point should be created successfully, and the chars should stay in sync across C1 and D1, while D1-only(flattened) chars should be stored only in D1 only and not synced to C1.

Test Case 2: Verifying X1-ServicePoint. updateServicePoint operation

Test Case 2.1: Verify whether SP chars applicable to both D1 SP and C1 SP are synchronized correctly

- Frame the HTTP Method PUT operation (updateServicePoint) by providing following input through REST Client or View Specification
  - **HTTP Method:** PUT
  - **Request URI:** https://ipAddress:portNum/spl/rest/apis/cross/v-model/servicePoints/**********
  - **Sample Request**

```
    {
      "servicePointId": "************",
      "servicePointType": {
        "servicePointType": "*****"
      },
    .
    .
    .
    .
    .
    .
```


Copyright ©2026, Oracle. All rights reserved.

```
        "installDate": "**********",
        "characteristicList": {
          "_data": [
            {
              "characteristicType": {
                "characteristicType": "*******",
                "_link": "*************"
              },
              "effectiveDate": "**********",
              "typeOfCharacteristicValue": "***",
              "value": "*",
              "characteristicValue": "*",
              "version": *
            },
            {
              "characteristicType": {
                "characteristicType": "********",                //D1 only characteristic type
                "_link": "*************"
              },
              "effectiveDate": "**********",
              "typeOfCharacteristicValue": "***",
              "value": "**************",              //Updated only this char value
              "adhocCharacteristicValue": "********",
              "version": *
            },
            {
              "characteristicType": {
.
.
.
      }
        ]
    }
}
```

Copyright ©2026, Oracle. All rights reserved.

- **Expected Result:** The Service Point should be Updated successfully, D1-only char changes persist only in D1 and do not sync to C1; all other char updates remain in sync between D1 and C1.

Test Case 2.2: Verify error for missing char value in input for a required char

- Frame the HTTP Method PUT operation (updateServicePoint) by providing following input through REST Client or View Specification
  - **HTTP Method:** PUT
  - **Request URI:** https://ipAddress:portNum/spl/rest/apis/cross/v-model/servicePoints/**********
  - **Sample Request**

```
{
    "servicePointId": "************",
    "servicePointType": {
        "servicePointType": "*****"
    },
    "externalId": "**********",
    "status": "******",
    "timeZone": {
        "timeZone": "*********"
    },
    "sourceStatus": "****",
    "premise": {
        "premiseId": "**********"
    },
    "geocodeLatitude": 0,
    "geocodeLongitude": 0,
    "assetSystemSPId": "************",
    "version": **,
    "address": {
        "country": {
            "country": "***"
        },
        "postal": "*****",
        "address1": "***********",
        "city": "*********",
```

 Copyright ©2026, Oracle. All rights reserved.

```
        "inCityLimit": false
    },
    "statusDateTime": "*************************",
    "creationDateTime": "*************************",
    "measurementCycleRouteSequence": 0,
    "installDate": "**********",
    "characteristicList": {
        "_data": [
            {
                "characteristicType": {
                    "characteristicType": "********"            //Required default char
                },
                "effectiveDate": "**********",
                //Char value is not provided
                "version": *
            }
        ]
    }
}
```

- **Expected Result:** The API should give a response with 400 status code and return a meaningful error message.

Test Case 3: Verify no duplicate ODM SP sync requests (Regression for Bug 38504075)

- Navigate to Main Menu → Customer Information → Add Service Point.
- Create a new Service Point.
- Verify that sync request for BO D1-ODMSPSyncRequest is generated.
- Update any value in the created Service Point.
- Verify a new, single sync request is generated after the update.

Copyright ©2026, Oracle. All rights reserved.

Test Case 4: Verify defaulting and sync of required SP chars on create SP through UI

- Navigate to Main Menu → Customer Information → Add Service Point.
- Create a new Service Point.
- Verify that the required characteristics are correctly defaulted.
- Add additional SP characteristics.
- Verify that newly added characteristics are synchronized to the CCB SP char table.

Copyright ©2026, Oracle. All rights reserved.