

GE Healthcare MI&CT Class C eService Notes are copyright (c) protected to General Electric Company Inc with all rights reserved. Class C eService Notes issued by GE Healthcare are proprietary to GE Healthcare. Disclosure to persons not employed by GE Healthcare or not in possession of an Advanced Service Agreement with GE Healthcare is prohibited. Duplication and distribution of any class of eService Notes, in any form by entities other than GE Healthcare is strictly prohibited.

MI&CT eSERVICE NOTE
SN0803070720a

Class C information. Property of GE Healthcare

This short-term informational note is invalid 6 months after the issue date.


Date: March 7, 2008

Subject: Collimator Cam Motor FRUs

Effectivity: VCT systems

Details:

One older version of the collimator cam motor FRU has a small circuit board attached to the power plug of the cam motor when shipped as a replacement part. This small circuit board is for shipping purposes only to provide a back potential to keep the motor from spinning during shipping and handling. It is not part of the system design.



Resolution:

Remove the small circuit board and discard it, it is only for shipping purposes for one version of the cam motor. The small circuit board is not used on the collimator. This notation will be added to the replacement procedure.

Affected Service Publication:

7.x VCT Service documentation 5193575

Tracking Number (PQR/SPR/ECR):

13126683

Steve Merritt
MICT Service Engineering