Name: Exam Key Student ID #: _____

CS472 / ECE472 / CS572 / ECE572

Fall 2018 Midterm Exam

You may use a calculator and a double-sided 8.5" x 11" notesheet.

Indicate whether the following statements are True or False.

False 1. (2 pt) Assuming that the pipeline is initially empty, a pipelined CPU can fully execute a single instruction in less time than the non-pipelined equivalent CPU.

False 2. (2 pt) Anytime a CPU writes to a page of virtual memory, the corresponding page is immediately written to disk to avoid loss of data.

True 3. (2 pt) The execution time of a benchmark program is generally considered to be a fair comparison between processors with different Instruction Set Architectures (ISAs).

True 4. (2 pt) The programmer's choice of compiler could have an impact on the order that instructions will be executed within the computer.

True 5. (2 pt) A program's memory access patterns will have a significant impact on the hit rate of a data cache.

False 6. (2 pt) A conflict miss can never occur in a direct-mapped cache.

False
7. (2 pt) In the MIPS architecture, the machine code of a branch instruction indicates the absolute memory address that should be placed inside the program counter (PC).

Dropped due to possible ambiguity. I should have used the phrasing "...machine code of a branch instruction contains the absolute memory address"

True 8. (2 pt) As the level of associativity increases, it becomes more difficult to implement a least-recently-used (LRU) cache replacement policy.

False 9. (2 pt) Anytime a CPU writes to a page of virtual memory, the corresponding page is immediately written to disk to avoid loss of data. (duplicate)

True 10. (2 pt) Static RAM (SRAM) is generally used to implement memory caches while dynamic RAM (DRAM) is generally used as the basis for system memory.

True
11. (2 pt) The decimal value 62.53125 can be exactly represented in IEEE 754 single precision format.

Two ways to solve this: 53125/100000 = 17/32. Since 32 is factorable by 2, this can be represented correctly in binary. 17/32 = 16/32 + 1/32. This floating point number will definitely fit into the 23 bit mantissa. The other way is to simply see that the fraction is 0.5 + 0.03125 and verify that the number fits.

False 12. (2 pt) In a virtual memory system, a translation-lookaside buffer (TLB) miss implies that the specified memory page must be retrieved from swap space (on the HDD).

True
13. (2 pt) The MIPS ISA uses a load/store architecture that requires operands to be moved into registers before ALU operations can take place.

I'll give this one to students since it's possible to make the argument that an instruction such as addi has one operand included in the instruction and is therefore not using a register for that operand. The phrasing should have said "...requires operands to be moved from memory into registers..."

False 14. (2 pt) The highest addressable virtual memory location must always be less than or equal to the highest physical memory address within a computer.

False 15. (2 pt) A write-through cache scheme implies that a cache will write changes only to the cache block (and set a dirty bit). The modified cache block will then be written to main memory only when it is replaced by a different block.

Provide the appropriate answer in the blank space.

16. (2 pts) In a pipelined CPU design, situations that prevent the next instruction stream from being executed during its designated clock cycle are called: hazards or pipeline hazards

For each of the following questions, choose the best answer.

- 17. (2 pts) Which of the following is a technique that computer architects can take in order to avoid hitting the metaphorical "power wall"?
 - A. Increase the clock frequency
 - B. Decrease the clock period to reduce power consumption
- C. Improve parallelization to execute multiple instructions simultaneously
- D. All of the above
- 18. (2 pts) In a CMOS IC design, power consumption is improved by lowering which of the following?
 - A. The capacitive load
 - B. The operating frequency

- C. The operating voltage
- D. All of the above
- 19. (2 pts) Suppose that you are implementing an associative cache with N=3. Assume that the block size has been selected as 8 bytes and that there are 32 block indices in the cache (i.e. there are 32 sets of 3 blocks). The cache uses a 20 bit addressing scheme. How many bits will each individual tag occupy? 3 bits for byte offset, 5 bits for block index. 20 - 3 - 5 = 12
 - A. 10

C. 12

B. 11

D. 13

- 20. (2 pts) Suppose your coworkers at ACME Computer Design have a problem. They implemented a virtual memory system to provide each process with its own virtual address space (each page with a size of 2K). Unfortunately, the corresponding page table is ginormous. Which of the following suggestions would be wisest?
 - A. Remove the translation-lookaside buffer (TLB) so that all queries can go directly to main memory
 - B. Increase the size of each memory page
- C. Decrease the size of each memory
- D. Move 90% of the memory pages into swap space (on HDD) so that additional memory is available for the page table
- 21. (2 pts) An immediate-format MIPS instruction requires how many registers to be specified?
 - A. 1

C. 3

B. 2

D. 4

22.	(2 pts)) Which	of the	following	statements	best	describes	memory	behavior	in the	MIPS	archited	ture?
~~.	\2 PC3	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	OI CIIC	10110 11115	Juacunicines	SCJE	463611863	TITCITION Y	DCIIGVIOI			ar critice c	carc.

- A. The stack and the heap each start at high memory addresses and work towards low addresses
- B. The stack and the heap both start near the middle of main memory and they grow away from each other
- C. The stack and the heap each start at low memory addresses and work towards high addresses
- D. The stack starts at a high memory address, the heap starts at a low address and they grow towards each other
- 23. (2 pts) Suppose that the MIPS architects decided to change the instruction length and develop a CPU with sixty-four 32 bit registers. If all other features remain intact, how many bits should the machine code of an R-format instruction occupy?
 - A. 33
 - B. 34

- C. 35
- D. 36

For each of the following problems, assume that the main memory contents are as shown in the diagram. Each problem is independent (e.g. the memory is initialized to match the diagram prior to each question). Important reminder: MIPS registers are 32 bits wide. This matters when we are reading or writing from memory. Side note: we are assuming big endian mode since that's what our textbook uses

24. (4 pts) Assume that the initial register values are as follows:

```
$t1 = 0x0004, $s0 = 0x0107,
$a1 = 0x1c28, $a2 = 0x1c34
```

```
addi $s0, $t1, 17 s0 = 0x4+17 = 21

sub $s0, $a1, $s0 s0 = 0x1c28-21 = 0x1c13

add $a2, $t1, $zero a2 = 0x04+0 = 4

add $t1, $s0, $a1 t1 = 0x1c13+0x1c28
```

After the assembly code has finished execution, what are the contents of the following registers?

```
$t1 = 0x383B, $s0 = 0x1c13, $a1 = 0x1c28, $a2 = 4
```

25. (4 pts) Assume that the initial register values are as follows:

```
$t1 = 0x0004, $s0 = 0x0107,
$a1 = 0x1c28, $a2 = 0x1c34
```

```
addi $t1, $zero, 10 t1 = 10

lw $s0, 0($a2) s0 = 0x08 = 8

slt $t1, $t1, $s0 10 !< 8 → t1 = 0

beq $t1, $zero, L1 t1 is 0 so goto L1

addi $a1, $a1, 2

j L2

L1:

lw $s0, 4($a2) s0 = 0x9d5618b4

L2:
```

```
Contents of main memory
Address
 0x1c20 | 0x8a |
               0x78
                     0x42 | 0x9c
 0x1c24 | 0x97
               0x3d
                     0xff
                           0x14
 0x1c28 | 0xa3 |
               0x82
                     0xda | 0x81
 0x1c2c | 0x00
               0x00
                     0x2f
                           0x18
 0x1c30 | 0x2c
               0xe2
                     0x22
                           0x71
 0x1c34 | 0x00
               0x00
                     0x00
                           0x08
 0x1c38
        0x9d
               0x56
                     0x18
                           0xb4
 0x1c3c
        0xef
               0x02
                     0xbb
                           0x7c
    . . .
 0xffe8 | 0xf7
               0x35
                     0x21 | 0xc3
               0x55
                     0x48 | 0x8d
 0xffec | 0x8a
 0xfff0 | 0x00
               0x00
                     0x1c
                           0x28
 0xfff4 | 0x00
               0x00
                     0x3f
                           0x28
 0xfff8 | 0x2b
                     0x12
               0x7e
                           0x72
 0xfffc | 0x13
               0x48
                     0x15 0x13
```

After the assembly code has finished execution, what are the contents of the following registers?

```
$t1 = 0, $s0 = 0x9d5618b4, $a1 = 0x1c28, $a2 = 0x1c34
```

26. (8 pts) For this problem, assume that the initial register values are as follows:

```
$t1 = 0x0004, $s0 = 0x0107, $s1 = 0x571, $sp = 0xfff4
```

```
addi $sp, $sp, -8 adjust the stack pointer to 0xffec
lw $s0, 0($sp) s0 = 0x8a55488d
lw $s1, 4($sp) s1 = 0x00001c28 = 0x1c28
lw $t1, 0($s1) t1 = 0xa382da81
addi $s0, $zero, 255 s0 = 255 = 0xFF
or $t1, $t1, $s0 t1 = t1 | 0xFF = 0xa382daFF
addi $sp, $sp, 8 adjust the stack pointer back to 0xfff4
```

After the assembly code has finished execution, what are the contents of the following registers?


```
$t1 = 0xa382daFF, $s0 = 255, $s1 = 0x1c28, $sp = 0xfff4
```

- 27. (7 pts) Compute the IEEE 754 single precision (32 bit) representation of the decimal value 467.875
 - A. What is the 1 bit value of the sign bit?0 (positive number)
 - B. What is the 8 bit value of the biased exponent?

467.875 = 111010011.111 = 1.11010011111 x 2⁸ 8+127 = 135 = 0b10000111

- C. What is the 23 bit value of the mantissa? 1101 0011 1110 0000 0000 000
- 28. (3 pts) Suppose that the CPU design shown below was manufactured with a defect. The input to the ADDER was intended to be 4 (corresponding to a 4 byte instruction). Unfortunately, the input was inadvertently set to 8 (as shown). All other components of the computer are still running on the assumption that each instruction occupies 32 bits. The small box below shows the sequence of 32 bit instructions that was going to be executed. Assuming the program counter (PC) was originally pointing to the first instruction, what will be the final value of \$t0 after the program counter reaches the END label?

This broken processor will skip over every second instruction. The code will execute as 2 + 6 + 10



29. (3 pts) In a particular computer, the instruction-cache miss rate is 3% and the data-cache hit rate is 96%. There is a miss penalty of 120 cycles that occurs when either cache is unable to immediately return the data. In a given program, suppose that 30% of the instructions involve load or store operations. If the base number of cycles per instruction (CPI) is 2 (meaning the CPI with an ideal cache) then what would be the expected CPI during this particular program?

A data-cache hit rate of 96% implies a data-cache miss rate of 4%. The expected CPI is: 2 + (0.03*120) + (0.30*0.04*120) = 7.04

30. (10 pts) Suppose you are working with a direct-mapped cache implementation. The cache has a block size of 4 words (16 bytes). There are 16 entries in the cache. The cache uses a 16 bit address. Implied address format: 8 bits for tag, 4 bits for block index, 4 bits for byte offset.

Note that this implies that the tag must be 0 for any byte address < 256.

A. The following chart indicated byte addresses that are requested from the initially empty cache. Addresses are accessed in sequential order (172, 139, 301, 300, etc).

Byte	Block	Block	Tog	Hit?	
Address	address	Index	Tag	mil?	
172	10	10	00000000	N	
139	8	8	00000000	Ν	
301	18	2	0000001	Ν	
300	18	2	0000001	Υ	
249	15	15	00000000	Ν	
141	8	8	00000000	Υ	
220	13	13	00000000	N	
261	16	0	0000001	N	
208	13	13	00000000	Υ	
162	10	10	00000000	Υ	

B. <u>Complete the following table</u> showing the final state of the cache. If a value is unknown, write a question mark in that space.

Index	Valid	Tag
0	1	0000001
1	0	?
2	1	0000001
3	0	?
4	0	?
5	0	?
6	0	?
7	0	?
8	1	0000000
9	0	?
10	1	0000000
11	0	?
12	0	?
13	1	0000000
14	0	?
15	1	0000000
•	•	

How many cache hits occurred?

How many times were blocks replaced? (Loading into an empty slot does not count.)

0