PART NUMBERS 56947-02K, -03K, -04K, -05K

Large & Small Boost Valve Kits

With O-Rings

 56947-02K
 High Ratio

 56947-04K
 Low Ratio

Each kit contains the following

- 1 Sleeve
- 1 Valve
- 2 O-Rings

Factory Style without O-Rings

 56947-03K
 High Ratio


 56947-05K
 Low Ratio

Each kit contains the following

1 Sleeve

1 Valve


Boost Valve Diameter



Note: During Wet Air Test of reverse circuit, if excessive oil loss is visible at the reverse engagement control plug, the plug is either installed backward (should be large diameter outward) or the plug or bore is worn. This wear will reduce reverse boost effectiveness.

Installation Instructions

Perform a Wet Air Test to determine if the boost valve assembly is worn and needs to be replaced. Remove the worn boost valve and sleeve from the valve body. Replace with the Sonnax boost valve kit. Refer to the illustration below to ensure that all parts are returned in the proper order and correct orientation.



Wet Air Test

With the manual valve in the reverse position and the separator plate still bolted to the valve body, place a small amount of oil into the "A" orifice. Follow with low air pressure. There should be no oil or air leakage in the exhaust port at "B". If there is, the boost valve is worn at the reverse land and should be replaced. Place a small amount of oil in checkball hole "C" or "D". Follow with low air pressure while plugging the opposing hole. There should be no oil or air leakage at cutback valve "E" location. If leakage occurs, the boost valve assembly is worn and should be replaced.

Note: To ensure that the pressure regulator valve balance circuit is functional, perform a Wet Air Test at "F". A worn bore will leak to filter suction hole. Many poor converter charge and engagement concerns are related to bore valve wear here.

