

Software Quality Assurance: Bug Report Summary

- **Project:** Boost Sound App
- **Tester:** Subhendu Bachhar Setu
- **Device:** Vivo Y50 (Android 10)
- **Total Bugs Found:** 07

1. Bug ID: BUG-01

- **Bug Title:** Background audio pauses when advertisement starts.
- **Steps to Reproduce:**
 1. Play audio using any media player (e.g., MX Player)
 2. Open the application
 3. Trigger a full-screen or video advertisement
 4. Observe the background audio
- **Expected Result:** The application should maintain audio focus using audio ducking, allowing background audio to continue at reduced volume.
- **Actual Result:** Background audio is paused immediately when the advertisement starts.
- **Severity:** High
- **Device Name + Android Version:** Vivo Y50 (Android 10)

2. Bug ID: BUG-02

- **Bug Title:** Selected language does not apply to application UI.
- **Steps to Reproduce:**
 1. Navigate to Settings - Language
 2. Select a different language (e.g., **Portuguese** or **Deutsch**)
 3. Return to the main screen and navigate through the app
- **Expected Result:** All UI elements (menus, labels, and buttons) should update according to the selected language.
- **Actual Result:** The application interface remains in English despite selecting another language.
- **Severity:** High
- **Device Name + Android Version:** Vivo Y50 (Android 10)

3. Bug ID: BUG- 03

- **Bug Title:** High Battery Drain & Unexpected Background Data Usage.
- **Steps to Reproduce:**
 1. Launch the application and enable boost features
 2. Use the app briefly
 3. Minimize the application
 4. After 30 - 60 minutes, check system battery and data usage
- **Expected Result:** The application should consume minimal battery and data when running in the background.
- **Actual Result:** The application consumes approximately 3% battery (~10.1 mAh) and 155.87 MB Wi-Fi data, and triggers a system power warning.

SCREENSHOT 01:





Fig.: Showing 3% battery usage and 10.1 mAh drain & showing 155.87 MB Wi-Fi data consumption

SCREENSHOT 02:




Fig.: Showing Vivo System Power Warning notification

- **Technical Analysis (For Developer):** The issue likely originates from continuous background processes, potentially Ad SDKs or analytics services, leading to excessive resource utilization.
- **Severity: High (Performance & Resource Management Issue)**
- **Device Name + Android Version:** Vivo Y50 (Android 10)

4. Bug ID: BUG- 04

- **Bug Title:** Volume increases without user confirmation after safety warning.
- **Steps to Reproduce:**
 1. Connect headphones or a Bluetooth device
 2. Play audio through the application
 3. Tap a high-volume preset (100% or above)
 4. Observe the warning dialog
- **Expected Result:** Volume should increase only after the user taps the **confirm** button.
- **Actual Result:** Volume increases immediately without waiting for user confirmation.
- **Severity: High**
- **Device Name + Android Version:** Vivo Y50 (Android 10)

5. Bug ID: BUG-05

- **Bug Title:** Background audio does not resume after advertisement ends
- **Steps to Reproduce:**
 1. Play audio in the background
 2. Trigger an in-app advertisement
 3. Wait for the advertisement to complete
- **Expected Result:** Audio should automatically resume after the advertisement ends or is dismissed.
- **Actual Result:** Audio remains paused and requires manual restart.
- **Severity: Medium**
- **Device Name + Android Version:** Vivo Y50 (Android 10)

6. Bug ID: BUG-06

- **Bug Title:** Edge Light “Hole” effect is misaligned with camera cutout.
- **Steps to Reproduce:**
 1. Open the application
 2. Navigate to Edge Light settings
 3. Select the **Hole** notch style
 4. Observe the effect placement
- **Expected Result:** The light effect should align accurately with the device’s front camera cutout.
- **Actual Result:** The effect appears in the center of the screen instead of aligning with the camera cutout.
- **Severity: Medium** (Visual/UI functionality failure).
- **Device Name + Android Version:** Vivo Y50 (Android 10)

7. Bug ID: BUG-07

- **Bug Title:** Text wrapping issue in “Waterdrop” label
- **Steps to Reproduce:**
 1. Navigate to Edge Light style selection menu
 2. Observe the “Waterdrop” label
- **Expected Result:** The label should be displayed properly on a single line or scaled correctly.
- **Actual Result:** The text breaks into two lines (**Waterdro / p**) affecting readability.
- **Severity: Low**
- **Device Name + Android Version:** Vivo Y50 (Android 10)

Test Case Documentation: Volume Boost Feature

- **Project:** Boost Sound App
- **Tester:** Subhendu Bachhar Setu
- **Feature Name:** Boost system volume & app sound beyond default limits

1.

- **Test Case ID:** TC-BST-01
- **Test Scenario:** Verify boost limit restriction for free users.
- **Precondition:** Application is installed and running on free version
- **Steps:**
 1. Open the application
 2. Navigate to the Volume tab
 3. Play any audio
 4. Attempt to increase boost beyond 60%
- **Expected Result:** The system should restrict the boost level and display a premium upgrade notification pop-up.

2.

- **Test Case ID:** TC-BST-02
- **Test Scenario:** Verify responsiveness of preset volume buttons.
- **Precondition:** Audio is playing in the background
- **Steps:**
 1. Tap the Mute button
 2. Tap preset buttons (**30%, 60%, 100%, 125%, 140%**) sequentially.
- **Expected Result:** The system volume should adjust immediately according to the selected preset without delay.

3.

- **Test Case ID:** TC-BST-03
- **Test Scenario:** Validate combined Boost and System volume calculation.
- **Precondition:** Both Boost and System sliders are set to 0% .
- **Steps:**
 1. Set Boost slider to 30%.
 2. Set System Volume slider to 30%.
 3. Observe preset button selection.
- **Expected Result:** The 60% preset button should be automatically selected based on combined values.

4.

- **Test Case ID:** TC-BST-04
- **Test Scenario:** Verify functionality of the Mute button
- **Precondition:** Boost and System volume are set above 0%
- **Steps:**
 1. Tap the Mute button
- **Expected Result:** Audio should stop immediately and both sliders should reset to 0%.

5.

- **Test Case ID:** TC-BST-05
- **Test Scenario:** Verify automatic preset button selection based on the combination of Boost and System Volume levels.
- **Precondition:** Initial Boost and System Volume are set at 0%.
- **Steps:**
 1. Adjust the **Boost slider** to 30%.
 2. Adjust the **System Volume slider** to 30%.
 3. Observe the preset buttons (30%, 60%, 100%, 125%, 140%, 160%) at the bottom of the UI.
- **Expected Result:** The **60%** preset button should be automatically highlighted or selected to reflect the total combined volume level (30% + 30%)= **60%**