




Design C — thin cirrus



Design D1a — column gain, noise after



Design D2 — SNR + dead columns



Schematic corruption models ([bandsim/cirrus.py](#), [bandsim/noise.py](#)): a robustness stress test, not calibrated radiometry.

Bars are the across-seed sample spread of each method, NOT the paired comparison — overlapping bars do not imply a null difference. Paired 95% intervals are per level in `results_phase4_ablation.csv`.

D1b\_noise\_then\_gain measured but not plotted: a per-column scalar gain cancels exactly under mean-brightness normalization, so its retention is 100% by algebraic identity. Values in the same CSV.