



Technical Service Bulletin

Technical Service Bulletin: TSB120250

Released Date: 28-Sep-2012

New QSK45/60 Tier 1 Exhaust Gas Temperature Sensor Harnesses


New QSK45/60 Tier 1 Exhaust Gas Temperature Sensor Harnesses

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

©Cummins Inc.



11k00028

Figure 1. Original Connector Location



11k00029

Figure 2. Revised Connector Location

This document announces the release of new exhaust gas temperature sensor (EGTS) harnesses for Tier1 QSK45 and QSK60 engines. It was determined that damage could be caused to the EGTS harness when lifting the engine, due to the proximity of the lifting bracket to the EGTS connectors. This issue has been resolved by moving the connectors away from the lifting bracket.

The photographs show the original connector location (Figure 1) and the revised connector location (Figure 2).

Note : The new EGTS hardware is not backward compatible with some previous versions. Therefore, previous versions will continue to be available to service to allow repairs to be completed without requiring a complete hardware change. New and old hardware can be mixed within an engine. On the QSK45, for example, one bank can be new hardware and one bank can be old hardware.

The new EGTS hardware went into production at Daventry Engine Plant on 10 September 2012, engine serial number (ESN) first 33195022.

QSK45

Old Part Number	New Part Number	Description	Location
3645838	3648147	Harness, control module wiring	Left bank front and right bank rear

QSK45			
3645839	3648148	Harness, control module wiring	Left bank rear and right bank front

QSK60 Single Stage			
Old Part Number	New Part Number	Description	Location
3645814	3648149	Harness, control module wiring	Left bank front and right bank rear
3645815	3648150	Harness, control module wiring	Left bank rear and right bank front

QSK60 Two Stage			
Old Part Number	New Part Number	Description	Location
3645814	3648149	Harness, control module wiring	Left bank front and right bank rear
3645815	3648150	Harness, control module wiring	Left bank rear and right bank front

Document History

Date	Details
2012-9-14	Module Created