

Client: TfNSW
Project: Picton Road Upgrade
Location: Eastern Stockpile west of M1

Project No: 60739890
Logged by: AL
Start Date: 09/12/25

Checked by: PW
End Date: 10/12/25
Location Meth.: DGPS
RL: 311.2 m
Ver. Datum: AHD
Surface: Fill

Driller: Terratest
Drill Rig: Commachio MC 450
Total Depth: 20.32 m
Hole Diameter: 125 mm
Inclination: 90°
Bearing: N/A

Easting: 302987.00
Northing: 6195183.70
Hor. Datum: MGA2020-56

METHOD	SUPPORT	DCP (BLOWS PER 100 mm)	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
ADIT	U		ES: 0.00-1.00 m			0.0			FILL - Gravelly SAND: fine to coarse grained, yellow brown; gravel, fine to coarse grained, angular to sub-angular, sandstone and coal wash. From 0.1 to 0.3m, sandstone boulder, yellow brown mottled orange.			FILL
		9	SPT: 0.50-0.95 m 6,6,10 HB N=16 D: 0.50-0.95 m			311.0			from 0.7m, becoming grey mottled red.	D		
		11										
		30										
			ES: 1.00-1.80 m			1.0			FILL - Gravelly Sandy CLAY: low to medium plasticity, dark brown mottled yellow; gravel, fine to coarse grained, angular to sub-angular, sandstone; sand, fine to coarse grained.	w < PL		
			SPT: 1.50-1.65 m 8/150 mm HB N=R D: 1.50-1.65 m						FILL - Clayey SAND: fine to coarse grained, dark grey mottled yellow; with gravel, fine to coarse grained, angular to sub-angular, sandstone.	D		
									FILL - Gravelly Sandy CLAY: medium to high plasticity, yellow brown mottled grey; gravel, fine to coarse grained, angular to sub-angular, sandstone and coal wash; sand, fine to coarse grained.	w < PL		
			ES: 1.80-2.40 m			2.0						
						3.0		SM	Silty SAND: fine to coarse grained, orange brown; trace gravel, fine to medium grained, sub-angular, XW sandstone.	D	D to VD	EXTREMELY WEATHERED SANDSTONE
			SPT: 3.00-3.05 m 8/50 mm HB N=R D: 3.00-3.05 m			3.0			Log continued on next page.			
						308.0						
						4.0						
						307.0						
						5.0						
						306.0						
						6.0						
						305.0						
						7.0						
						304.0						
						8.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Eastern Stockpile west of M1

Project No: 60739890
Logged by: AL
Start Date: 09/12/25

Checked by: PW
End Date: 10/12/25
Location Meth.: DGPS

Driller: Terratest	Hole Diameter: 125 mm
Drill Rig: Commachio MC 450	Inclination: 90°
Total Depth: 20.32 m	Bearing: N/A

Easting: 302987.00
Northing: 6195183.70
Hor. Datum: MGA2020-56

RL: 311.2 m
Ver. Datum: AHD
Surface: Fill

METHOD	CORE RUN	GROUND WATER	SAMPLES & FIELD TESTS	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	MATERIAL DESCRIPTION (colour, grain size, texture and fabric, structure, bedding dip, soil moisture, consistency/density)	WEATHERING	TCR (SCR) [ROD] (%)	INFERRED STRENGTH $20 \times I_s(50)$ A: ● D: ○ UCS: □ ■ V L M H V H EH	DEFECT SPACING (mm)	VISUAL	ADDITIONAL OBSERVATIONS (Defect Descriptions)
					0.0								
				-311.0									
					1.0								
				-310.0									
					2.0								
				-309.0									
					3.0								
				-308.0									
					4.0								
				-307.0									
					5.0								
				-306.0									
					6.0								
				-305.0									
					7.0								
				-304.0									
HQ3	1 3.35		I _s (50) A=0.1 MPa				SANDSTONE: fine to medium grained, pale grey with dark brown ironstone bands, iron stained.	XW	100 (100) [0]				BULGO SANDSTONE 3.06 m: P, 20°, RF, PR, clay, 1 mm aperture 3.10-3.18 m: CS, 5°, RF, sandstone , 80 mm thick 3.18-3.20 m: EW, 5°, RF, XW sandstone, 20 mm thick 3.21 m: P, 5°, RF, CU, CT clay 3.25 m: P, 0°, RF, PR, SN Fe 3.40-4.20 m: CS, RF, 800 mm thick
	2						NO CORE:		59 (59) [0]				4.29-4.42 m: P, 30°, RF, IR, CT Fe, 40 mm spacing 4.42-4.51 m: CS, RF, IR, XW sandstone, 90 mm thick 4.58-4.60 m: CS, RF, PR, XW sandstone, 20 mm thick 4.65-4.71 m: CS, RF, IR, XW sandstone, 60 mm thick 4.75 m: P, 10°, RF, PR, CT clay 4.82 m: P, RF, PR, XW sandstone 4.92 m: DB 5.10 m: J, 80°, RF, PR, SN clay, 90 mm persistence
	6.40		I _s (50) A=0.75 MPa I _s (50) D=0.43 MPa				SANDSTONE: medium to coarse grained, pale brown to pale yellow brown, iron stained, bedded at 0 to 10°, 10 to 20 mm typical spacing.	HW to MW	100 (100) [91]				6.46 m: J, 40°, RF, PR, SN Fe, 20 mm persistence 6.47 m: J, 40°, RF, PR, SN Fe, 10 mm persistence 6.52 m: DB 6.59 m: DB 6.80 m: P, 10°, RF, PR, SN Fe
	3	09/12/2025 15:12:00 ▼	I _s (50) A=1.3 MPa I _s (50) D=1.1 MPa				SANDSTONE: fine to coarse grained, brown grey, iron stained, bedded at 0 to 10°, 5 to 20 mm typical spacing.	MW					7.10 m: DB 7.29 m: P, 0-10° RF, PR, SN Fe 7.43 m: DB 7.59 m: DB 7.77 m: DB

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Eastern Stockpile west of M1

Project No: 60739890
Logged by: AL
Start Date: 09/12/25

Checked by: PW
End Date: 10/12/25
Location Meth.: DGPS

Driller: Terratest
Drill Rig: Commachio MC 450
Total Depth: 20.32 m

Hole Diameter: 125 mm
Inclination: 90°
Bearing: N/A

Easting: 302987.00
Northing: 6195183.70
Hor. Datum: MGA2020-56

RL: 311.2 m
Ver. Datum: AHD
Surface: Fill

METHOD	CORE RUN	GROUND WATER	SAMPLES & FIELD TESTS	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	MATERIAL DESCRIPTION (colour, grain size, texture and fabric, structure, bedding dip, soil moisture, consistency/density)	WEATHERING	TCR (SCR) (RQD) (%)	INFERRED STRENGTH 20 x IS ₍₅₀₎ A: • D: ○ UCS: □	DEFECT SPACING (mm)	VISUAL	ADDITIONAL OBSERVATIONS (Defect Descriptions)
HQ3	4	15/12/2025 14:25:00	Is(50) A=0.21 MPa Is(50) A=2.4 MPa Is(50) D=1.7 MPa Is(50) A=1.1 MPa Is(50) D=0.83 MPa	303.0			SANDSTONE: fine to coarse grained, brown grey, iron stained, bedded at 0 to 10°, 5 to 20 mm typical spacing.	MW					7.96 m: P, 0-10°, RF, PR, SN Fe
							CLAYSTONE: fine grained, dark brown, iron stained.						8.29 m: DB 8.33 m: J, 0-50°, RF, UN, CT clay, 50 mm persistence
				9.0			SANDSTONE: fine to coarse grained, brown grey, iron stained, bedded at 0 to 10°, 5 to 20 mm typical spacing.						8.68-8.70 m: EW, 5°, RF, UN, CT clay, 20 mm thick
4	9.40						from 9.15 to 9.65m, frequent fine grained, dark brown bands.						8.90 m: MB 9.02 m: DB 9.04 m: P, 10°, RF, UN, CT clay 9.22 m: P, 20°, RF, UN, SN Fe 9.28 m: J, 30°, RF, UN, SN Fe
									100 (100) [95]				9.47-9.55 m: EW, RF, PR, 80 mm thick
													9.75 m: DB 9.91 m: DB
5	12.40		Is(50) A=1.1 MPa Is(50) D=0.65 MPa C: 10.45-10.75 m UCS=17.7 MPa Is(50) A=1.6 MPa Is(50) D=1.4 MPa	10.0			SANDSTONE: medium to coarse grained, pale grey, bedded at 0 to 10°, 10 to 20 mm typical spacing.	SW					10.31 m: P, 30°, RF, PR, CN
													10.75 m: DB 10.92 m: DB
													11.80 m: DB 11.83 m: DB 11.85 m: P, 10°, RF, PR, CN 12.08 m: DB 12.20 m: P, 10°, RF, IR, CT clay
5	15.40		Is(50) A=0.9 MPa Is(50) D=0.22 MPa C: 13.25-13.55 m Is(50) A=1.5 MPa Is(50) D=1.6 MPa UCS=15.3 MPa	12.0			CONGLOMERATE: medium to coarse grained, pale grey and brown, clasts up to 20 mm.		100 (100) [97]				12.42 m: P, 5°, RF, PR, CN 12.49 m: P, 5°, RF, UN, SN Fe 12.63 m: P, 0°, RF, PR, CN
							SANDSTONE: medium to coarse grained, pale grey to pale brown, bedded at 0 to 20°, variable spacing, indistinct fabric.						12.80-12.90 m: P, 20°, RF, UN, SN Fe, 40-60 mm spacing, x 3
													13.22 m: P, 30°, RF, PR, SN Fe 13.63 m: P, 30°, RF, UN, SN Fe 13.87 m: P, 5°, RF, UN, SN Fe
5			Is(50) A=0.67 MPa Is(50) D=0.12 MPa Is(50) A=2.4 MPa Is(50) D=1.6 MPa	13.0			SANDSTONE: fine grained, green grey, bedded at 0°, 0 to 10 mm typical spacing.						14.37 m: P, 0°, RF, PR, SN Fe
							from 14.91 to 15.38m, fine to medium grained, pale grey.						14.67 m: DB 14.76 m: DB 14.87 m: DB 14.90 m: P, 5°, RF, PR, SN Fe 15.08 m: DB 15.15 m: DB
								FR	100 (100) [100]				15.38 m: P, 10°, RF, PR, CN, 2 mm aperture 15.46 m: DB 15.48 m: DB 15.51 m: P, 10°, RF, PR, CN 15.53 m: DB 15.58 m: DB

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW

Project: Picton Road Upgrade

Location: Eastern Stockpile west of M1

Project No: 60739890

Logged by: AL

Start Date: 09/12/25

Checked by: PW

End Date: 10/12/25

Location Meth.: DGPS

Driller: Terratest

Drill Rig: Commachio MC 450

Total Depth: 20.32 m

Hole Diameter: 125 mm

Inclination: 90°

Bearing: N/A

Easting: 302987.00

Northing: 6195183.70

Hor. Datum: MGA2020-56

RL: 311.2 m

Ver. Datum: AHD

Surface: Fill


METHOD	CORE RUN	GROUND WATER	SAMPLES & FIELD TESTS	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	MATERIAL DESCRIPTION (colour, grain size, texture and fabric, structure, bedding dip, soil moisture, consistency/density)	WEATHERING	TCR (SCR) (RQD) (%)	INFERRED STRENGTH 20 x IS ₍₅₀₎ A: • D: ○ UCS: □	DEFECT SPACING (mm)	VISUAL	ADDITIONAL OBSERVATIONS (Defect Descriptions)
HQ3	6		Is(50) A=1.9 MPa Is(50) D=0.76 MPa	295.0			SANDSTONE: fine grained, green grey, bedded at 0°, 0 to 10 mm typical spacing.	FR	100 (100) [97]				15.59 m: DB 15.84 m: P, 10°, RF, PR, CN 16.21 m: DB
				17.0			from 16.97 to 17.45m, fine to medium grained, pale grey, regular dark grey laminations and lenses.						16.61 m: DB 16.82 m: DB 16.95 m: DB 17.10 m: DB
7	18.40		Is(50) A=0.84 MPa Is(50) D=0.43 MPa	294.0			SANDSTONE: fine to medium grained, pale grey, massive, distinct fabric.						17.44 m: DB 17.58 m: P, 5°, RF, PR, SN fe 17.70 m: DB 17.86 m: DB 18.07 m: DB
				18.0			SANDSTONE: fine to coarse grained, green grey, occasional dark grey laminations.						19.00 m: SZ, 30° 19.08 m: DB 19.31 m: DB 19.36-19.38 m: EW, 10°, RF, IR, SN Fe, 20 mm thick 19.70 m: P, 5°, RF, PR, CN 19.98 m: DB 19.99-20.00 m: CS, RF, PR, XW sandstone, 10 mm thick 20.19-20.20 m: P, 9°, RF, UN, SN Fe, 10 mm spacing
			Is(50) A=0.81 MPa Is(50) D=0.65 MPa	292.0			from 19.75 to 20m, fine to medium grained, pale grey, regular dark brown clasts, up to 20 mm.						
				20.0									
			Is(50) A=0.66 MPa Is(50) D=0.55 MPa	291.0			Terminated at 20.32 m. Target depth.						
				21.0									
				290.0									
				22.0									
				289.0									
				23.0									
				288.0									
				24.0									

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1


ID NO.: PRUP_BH01
PROJECT NO.: 60739890
Sheet 1 of 5



CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1


ID NO. :PRUP_BH01
PROJECT NO. :60739890
Sheet 2 of 5



CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1

ID NO. :PRUP_BH01
PROJECT NO. :60739890
Sheet 3 of 5




AECOM

CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1

ID NO.: PRUP_BH01
PROJECT NO.: 60739890
Sheet 4 of 5




AECOM

CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1

ID NO.: PRUP_BH01
PROJECT NO.: 60739890
Sheet 5 of 5



AECOM

Client: TfNSW

Project: Picton Road Upgrade

Location: Eastern Stockpile west of M1

Project No: 60739890

Logged by: AL

Start Date: 08/12/25

Checked by: PW

End Date: 08/12/25

Location Meth.: DGPS

Driller: Durkin

Drill Rig: Commachio MC 450

Total Depth: 10.33 m

Hole Diameter: 125 mm

Inclination: 90°

Bearing: N/A

Easting: 302972.00

Northing: 6195236.30

Hor. Datum: MGA2020-56

RL: 311 m

Ver. Datum: AHD

Surface: Fill

METHOD	SUPPORT	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
AD/T	U	ES: 0.00-1.00 m		311.0	0.0			FILL - Sandy GRAVEL: fine to coarse grained, angular to sub-angular, dark grey, sandstone and conglomerate; sand, fine to coarse grained .	D		FILL
		SPT: 0.50-0.90 m 6,10,8/100 mm HB N=R D: 0.50-0.90 m									
		ES: 1.00-1.20 m		310.0	1.0			FILL - Gravelly COBBLES: grey, concrete; gravel, fine to coarse grained, sub-angular, sandstone and coal wash.	D		
		ES: 1.20-6.00 m						FILL - Gravelly SAND: fine to coarse grained, dark grey; gravel, fine to coarse grained, sub-rounded, sandstone and coal wash.	D		
		SPT: 1.50-1.95 m 18,19,13 N=32 D: 1.50-1.95 m									
				309.0	2.0			FILL - Sandy GRAVEL: coarse grained, sub-rounded, yellow brown, sandstone; sand, fine to medium grained .	D		
								FILL - GRAVEL: fine to coarse grained, sub-angular to sub-rounded, dark grey to brown, sandstone and coal wash; with sand, fine to coarse grained.			
		SPT: 3.00-3.45 m 6,6,5 N=11 D: 3.00-3.45 m		308.0	3.0				D		
				307.0	4.0						
		SPT: 4.50-4.80 m 2,11,0/0 mm/150 mm HB N=R D: 4.50-4.80 m		306.0	5.0		SP	Gravelly SAND: fine to coarse grained, orange brown mottled grey; gravel, fine to coarse grained, sub-angular to sub-rounded, XW sandstone.	D	VD	EXTREMELY WEATHERED SANDSTONE
				305.0	6.0			SANDSTONE: fine to coarse grained, brown grey mottled red.			BEDROCK
		SPT: 6.00-6.03 m 11/30 mm HB N=R D: 6.00-6.03 m ES: 6.00-6.03 m						Log continued on next page.			
				304.0	7.0						
				303.0	8.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Eastern Stockpile west of M1

Project No: 60739890

Logged by: AL

Start Date: 08/12/25

Checked by: PW

End Date: 08/12/25

Location Meth.: DGPS

Driller: Durkin **Hole Diameter:** 125 mm

Drill Rig: Commachio MC 450

Inclination: 90°

Easting: 302972.00

Northing: 6195236.30

RL: 311 m

Ver. Datum: AHD

Total Depth: 10.33 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Fill

[illegible]

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Eastern Stockpile west of M1

Project No: 60739890
Logged by: AL
Start Date: 08/12/25

Checked by: PW
End Date: 08/12/25
Location Meth.: DGPS

Driller: Durkin	Hole Diameter: 125 mm
Drill Rig: Commachio MC 450	Inclination: 90°
Total Depth: 10.33 m	Bearing: N/A

Easting: 302972.00
Northing: 6195236.30
Hor. Datum: MGA2020-56

RL: 311 m
Ver. Datum: AHD
Surface: Fill


METHOD	CORE RUN	GROUND WATER	SAMPLES & FIELD TESTS	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	MATERIAL DESCRIPTION (colour, grain size, texture and fabric, structure, bedding dip, soil moisture, consistency/density)	WEATHERING	TCR (SCR) (RQD) (%)	INFERRED STRENGTH 20 x Is(50) A: • D: o UCS: □ □ □ 20 30 40 50 60 70 80 90 100	DEFECT SPACING (mm)	VISUAL	ADDITIONAL OBSERVATIONS (Defect Descriptions)
HQ3	3		Is(50) A=0.31 MPa Is(50) D=0.23 MPa Is(50) A=0.21 MPa Is(50) D=0.2 MPa Is(50) A=1.8 MPa Is(50) D=2.5 MPa				SANDSTONE: fine to coarse grained, yellow brown and pale grey, iron stained, bedded at 0 to 20°. SANDSTONE: fine grained, green grey, bedded at 0 to 20°, 5 to 40 mm typical spacing, rare dark brown clasts. SANDSTONE: fine to medium grained, pale orange brown. SANDSTONE: fine grained, green grey, bedded at 0 to 20°, 5 to 40 mm typical spacing, rare dark brown clasts. from 10 to 10.1 m, orange brown.	HW MW					7.53 m: P, 10°, RF, PR, SN Fe 7.59 m: J, 45°, RF, IR, SN Fe, 70 mm persistence 7.73 m: P, 5°, RF, PR, VN Clay 7.86-7.89 m: P, 5°, RF, UN, CT clay , 30 mm spacing 8.12-8.14 m: EW, 5°, RF, IR, XW sandstone , 20 mm thick 8.28-8.30 m: EW, 5°, RF, UN, XW sandstone , 20 mm thick 8.82-8.87 m: CS, 20°, RF, CU, CT clay, 50 mm thick 8.90 m: J, 60°, RF, PR, CN, 40 mm persistence 9.05 m: DB 9.07 m: DB 9.20 m: P, 20°, RF, CU, CN clay 9.26-9.31 m: EW, 20°, RF, UN, XW sandstone , 50 mm thick 9.52 m: DB 9.64 m: DB 9.66 m: DB 9.79 m: DB 9.85 m: DB 10.10 m: P, 5°, RF, PR, CT clay 10.20 m: P, 10°, RF, UN, CT clay
							Terminated at 10.33 m. Target depth.						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1

ID NO. :PRUP_BH02
PROJECT NO. :60739890
Sheet 1 of 2




AECOM

CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1

ID NO. :PRUP_BH02
PROJECT NO. :60739890
Sheet 2 of 2



Client: TfNSW

Project: Picton Road Upgrade

Location: Eastern Stockpile west of M1

Project No: 60739890

Logged by: AL

Start Date: 10/12/25

Checked by: PW

End Date: 11/12/25

Location Meth.: DGPS

Driller: Terratest

Hole Diameter: 125 mm

Easting: 302912.70

RL: 309.4 m

Drill Rig: Commachio MC 450

Inclination: 90°

Northing: 6195264.00

Ver. Datum: AHD

Total Depth: 20.41 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Fill

METHOD	SUPPORT	SAMPLES & FIELD TESTS	GROUND WATER	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATION SYMBOL	MATERIAL DESCRIPTION (plasticity/particle characteristics, colour, secondary and other minor components, structure)	MOISTURE CONDITION	CONSISTENCY / RELATIVE DENSITY	ADDITIONAL OBSERVATIONS (Geological Origin)
AD/T	U	ES: 0.00-0.70 m			0.0			FILL - Clayey Gravelly SAND: fine to coarse grained, dark grey to black; gravel, fine to coarse grained, sub-angular, sandstone and coal wash.	D		FILL
		SPT: 0.50-0.78 m 11, 14/130 mm HB N=R			0.5		SM	Silty SAND: fine to coarse grained, red brown; trace XW sandstone.	D	VD	EXTREMELY WEATHERED SANDSTONE
		D: 0.50-0.78 m ES: 0.70-1.40 m			1.0			SANDSTONE: medium to coarse grained, red brown and pale grey, HW, VL strength.	D	VD	BEDROCK
					308.0			Log continued on next page.			
					2.0						
					307.0						
					3.0						
					306.0						
					4.0						
					305.0						
					5.0						
					304.0						
					6.0						
					303.0						
					7.0						
					302.0						
					8.0						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Eastern Stockpile west of M1

Project No: 60739890

Logged by: AL

Start Date: 10/12/25

Checked by: PW

End Date: 11/12/25

Location Meth.: DGPS

Driller: Terratest

Hole Diameter: 125 mm

Easting: 302912.70

RL: 309.4 m

Drill Rig: Commachio MC 450

Inclination: 90°

Northing: 6195264.00

Ver. Datum: AHD

Total Depth: 20.41 m

Bearing: N/A

Hor. Datum: MGA2020-56

Surface: Fill

METHOD	CORE RUN	GROUND WATER	SAMPLES & FIELD TESTS	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	MATERIAL DESCRIPTION (colour, grain size, texture and fabric, structure, bedding dip, soil moisture, consistency/density)	WEATHERING	TCR (SCR) (ROD) (%)	INFERRED STRENGTH 20 x IS ₍₅₀₎ A: ■ D: ○ UCS: □ σ ₂₀₀	DEFECT SPACING (mm)	VISUAL	ADDITIONAL OBSERVATIONS (Defect Descriptions)
					0.0					SOIL ₀₋₆₅ VL ₇ L ₆ M ₃₀ H ₄₅ VH ₂₀₀ EH			
					-309.0								
					-1.0								
					-308.0		Log continued from previous page.						
HQ3	1		Is(50) A=1.6 MPa Is(50) D=1.3 MPa				SANDSTONE: medium to coarse grained, yellow brown and pale grey, iron stained, massive.	MW	100 (100) [18]				BULGO SANDSTONE 1.49 m: P, 5°, RF, PR, SN Fe
		3.40	Is(50) A=0.04 MPa Is(50) D=0.01 MPa		2.0		CLAYSTONE: red-brown, bedded at 0°, 0-20 mm typical spacing.	HW to MW					1.74 m: DB 1.80 m: P, 5°, RF, PR, CT clay 1.86 m: P, 5°, RF, PR, CT clay 1.96-2.00 m: CS, RF 2.00-2.34 m: P, 5-10°, RF, UN, SN Fe, 20-90 mm spacing, x 5
			Is(50) A=0.12 MPa Is(50) D=0.01 MPa		-307.0								2.71 m: P, 5°, RF, PR, SN Fe
	2		Is(50) A=0.67 MPa Is(50) D=0.38 MPa		3.0								3.02 m: MB, RF 3.10-3.18 m: CS, RF 3.21 m: J, 45°, RF, PR, CN 3.34-3.36 m: EW, RF, IR, 20 mm thick 3.40 m: DB 3.45 m: P, 5°, RF, PR, SN Fe
		6.40	Is(50) A=0.35 MPa Is(50) D=0.06 MPa		-306.0		SANDSTONE: medium grained, yellow brown and pale grey, iron stained.		100 (100) [71]				3.68 m: DB 3.77-3.81 m: CS, RF, PR
			Is(50) A=1.2 MPa Is(50) D=0.76 MPa		4.0								4.00 m: P, 5°, RF, PR, SN Fe 4.10 m: P, 5°, RF, PR, SN Fe 4.13 m: P, 5°, RF, UN, CT clay 4.26 m: DB
			Is(50) A=4.5 MPa Is(50) D=2.4 MPa		-305.0								4.50 m: P, 10°, RF, PR, SN Fe 4.56 m: P, 20°, RF, CU, SN Fe 4.67 m: P, 5°, RF, PR, SN Fe 4.71 m: J, 45°, RF, UN, SN Fe, 20 mm persistence 4.75 m: DB 4.95 m: DB
					5.0			SW					5.47 m: P, 5°, RF, UN, CT clay
					-304.0		from 5.30 to 5.47 m, frequent red brown clasts up to 30 mm. SANDSTONE: fine grained, grey, occasional dark grey laminations and lenses.						6.04 m: P, 5°, RF, IR, CT clay
					6.0								6.40 m: P, 10°, RF, PR, CT clay 6.45 m: DB 6.50 m: DB 6.65 m: DB 6.84 m: DB 6.92 m: J, 80°, RF, UN, SN Fe 6.93 m: P, 5°, RF, PR, CN 7.00 m: P, RF, PR, SN Fe 7.09-7.15 m: CS, RF, IR, 60 mm thick 7.10 m: P, 5°, RF, PR, SN Fe 7.31 m: P, 0°, RF, PR, CN 7.50 m: P, 5°, RF, PR, CT clay 7.52 m: P, 10°, RF, PR, CT clay
					-303.0		from 6.05 to 6.40 m, medium grained, pale grey.		100 (100) [86]				7.81 m: DB 7.85 m: P, 10°, RF, PR, CT clay
					7.0								
					-302.0		SANDSTONE: fine grained, grey to green grey, bedded at 0°, variable spacing, rare red brown clasts.						

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Eastern Stockpile west of M1

Project No: 60739890
Logged by: AL
Start Date: 10/12/25

Checked by: PW
End Date: 11/12/25
Location Meth.: DGPS

Driller: Terratest
Drill Rig: Commachio MC 450
Total Depth: 20.41 m

Hole Diameter: 125 mm
Inclination: 90°
Bearing: N/A

Easting: 302912.70
Northing: 6195264.00
Hor. Datum: MGA2020-56

RL: 309.4 m
Ver. Datum: AHD
Surface: Fill

METHOD	CORE RUN	GROUND WATER	SAMPLES & FIELD TESTS	RL (m AHD)	DEPTH (m)	GRAPHIC LOG	MATERIAL DESCRIPTION (colour, grain size, texture and fabric, structure, bedding dip, soil moisture, consistency/density)	WEATHERING	TCR (SCR) (RQD) (%)	INFERRED STRENGTH 20 x IS ₍₅₀₎ A: • D: ○ UCS: □	DEFECT SPACING (mm)	VISUAL	ADDITIONAL OBSERVATIONS (Defect Descriptions)
HQ3	4	11/12/2025 14:45:00 ▼	C: 8.40-8.70 m UCS=17 MPa Is(50) A=0.28 MPa Is(50) D=0.09 MPa	301.0			SANDSTONE: fine grained, grey to green grey, bedded at 0°, variable spacing, rare red brown clasts.	SW					8.08-8.11 m: CS, RF, PR 8.30 m: P, 20°, RF, CU, CT clay 8.75 m: P, 5°, RF, PR, CT clay 8.97 m: P, 5°, RF, PR, CN 9.11 m: HB 9.35 m: HB 9.48 m: P, 10°, RF, PR, CN 9.58 m: DB 9.66 m: P, 0°, RF, UN, CN 9.86 m: P, 10°, RF, PR, CT clay 9.94 m: DB 10.08 m: DB 10.16 m: J, 60°, RF, PR, CN, 20 mm persistence 10.23 m: P, 0°, RF, PR, CT clay 10.46-10.90 m: P, 0-10°, RF, PR, CT clay, 20-100 mm spacing, x 8
			Is(50) A=0.96 MPa Is(50) D=0.97 MPa	300.0					100 (100) [98]				11.08 m: DB 11.15-11.18 m: CS, RF, PR 11.38 m: P, 10°, RF, CU, SN Fe 11.55 m: HB 11.66 m: DB 11.81 m: DB 11.92 m: DB
	5		Is(50) A=0.56 MPa Is(50) D=0.54 MPa	299.0			SANDSTONE: fine to medium grained, brown grey, bedded at 0 to 10°, 10 to 30 mm typical spacing, occasional dark grey laminations and lenses.						12.32 m: P, 10°, RF, UN, CT clay 12.60 m: DB 13.57 m: P, 5°, RF, PR, SN Fe
HQ3	5	12.60	Is(50) A=2.1 MPa Is(50) D=0.78 MPa	298.0			from 12.32 to 12.36 m, orange brown, iron stained.	SW to FR					14.87 m: P, 15°, RF, PR, CN 15.22 m: P, 10°, RF, PR, CT clay 15.30-15.33 m: CS, RF, IR
			Is(50) A=1.8 MPa Is(50) D=1.4 MPa	297.0			SANDSTONE: medium grained, pale grey, bedded at 0 to 20°, variable spacing.		100 (100) [99]				15.52-15.54 m: CS, RF, PR 15.60 m: DB 15.70 m: P, 5°, RF, PR, CN
	5		Is(50) A=1.6 MPa Is(50) D=1 MPa	296.0									
HQ3	5	15.60	Is(50) A=1.2 MPa Is(50) D=1.1 MPa	295.0									
			Is(50) A=1.6 MPa Is(50) D=1.3 MPa	294.0			SANDSTONE: fine to medium grained, brown grey to green grey, occasional red brown laminations and bands. from 15.74 to 15.84 m, frequent red brown and dark brown clasts up to 20mm.		100 (100) [99]				
	5			294.0									
HQ3	5			293.0									
				292.0									
	5			291.0									

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

Client: TfNSW
Project: Picton Road Upgrade
Location: Eastern Stockpile west of M1

Project No: 60739890

Logged by: AL

Start Date: 10/12/25

Checked by: PW

End Date: 11/12/25

Location Meth.: DGPS

Driller: Terratest
Drill Rig: Commachio MC 450
Total Depth: 20.41 m

Hole Diameter: 125 mm

Inclination: 90°

Bearing: N/A

Easting: 302912.70

Northing: 6195264.00

Hor. Datum: MGA2020-56

RL: 309.4 m

Ver. Datum: AHD

Surface: Fill


[illegible]

Engineering log should be read in conjunction with AECOM soil and rock logging description sheets.

CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1


ID NO.: PRUP_BH03
PROJECT NO.: 60739890
Sheet 1 of 5



CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1


ID NO.: PRUP_BH03
PROJECT NO.: 60739890
Sheet 2 of 5



CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1


ID NO.: PRUP_BH03
PROJECT NO.: 60739890
Sheet 3 of 5



CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1

ID NO. :PRUP_BH03
PROJECT NO. :60739890
Sheet 4 of 5



CORED PHOTO REPORT

PROJECT: 60739890
LOCATION: Eastern Stockpile west of M1

ID NO. :PRUP_BH03
PROJECT NO. :60739890
Sheet 5 of 5

