






Changes since v1.3

- Added K12 2-way power terminal block
- Added IC4 + C7 for on-board 3V3 regulation
- Added D3 for protection in case both FTDI cable and external power are present
- Added JP15 & JP16 to allow use of second UART available in DIP-40 devices
- Deleted JP2 because no longer needed
- PCB silkscreen touched-up

CONFIGURE SOLDER JUMPERS FIRST



**PLATINO**  
Arduino, ISP, FTDI

150555-I

150555-1-Platino-v1.4b

06/11/2015 10:35

CPV

Sheet: 3/3

1.4