




+5V SUPPLY



BAT SUPPLY



MOTOR CONNECTIONS

