




STM32F031K6




who knows why this symbol is misaligned by 1



Current Sense Amplifier




Shunt/Fuse



Mounting Holes



Driver



Ports

