



TROUBLE SHOOTING REPORT

PSMD (SABHAN)

Ref. No:	46/10/23	Date:	01/10/2023	Prnt. Time :	12:44
Substation:	UNIVERSITY-M	Make:	ABB	P.M:	09/02/2023
		Maint:		Comm:	05/22/2007

Equip./Unit Affected : SHKN"M" 33 KV F

Nature of Fault : Polarity chech , stability test and normalize SOLKOR are required for the A/M F .
Requested by CME Mohamed Akber (99471194) . PME has to follow .

Concerned Group & Engr: ... Fawaz aswad . Technicians:- 1-
Section Head : 2-

Action Taken :

Reconnected the pilot wire from marshaling.
Checked polarity from relay to relay. Found ok.
Normalized pilot, dcc informed.

Concerned Group & Engr :

Date: 2 / 10 / 2023

Director :

Section Head :