



## TROUBLE SHOOTING REPORT

PSMD (SABHAN)

|                    |          |               |            |                    |            |
|--------------------|----------|---------------|------------|--------------------|------------|
| <b>Ref. No:</b>    | 40/10/23 | <b>Date:</b>  | 01/10/2023 | <b>Prnt.Time :</b> | 12:19      |
| <b>Substation:</b> | ARDIYA-B | <b>Make:</b>  | TRE - SIE  | <b>P.M:</b>        | 18/12/2018 |
|                    |          | <b>Maint:</b> |            | <b>Comm:</b>       | 09/13/1980 |

**Equip./Unit Affected :** OMAR-AE

**Nature of Fault :** PCF Alarm.PME has to follow.

**Concerned Group & Engr:** Khaled Almutairi

**Technicians:-** 1-

Khalid Farouq

**Section Head :**

2-

**Action Taken :**

The problem was from surge arrester ; we replaced it, Fult is clear in Both S/S

DCC informed

1/10/2023

**Concerned Group & Engr :**

**Date:** / /

**Director :**

**Section Head :**