



PT5, PT6, PT7, PT8, PT9, PT10, PT11, PT12 WILL HAVE TO BE LOOPED BETWEEN THE TWO CONNECTORS.
26 PIN CONNECTOR DOES NOT HAVE ENOUGH PASSTHROUGH LINES

comma.ai
you can copy this!

9

TITLE: Subaru_D_Harness

Design by:

REV:

Date: 4/3/23 4:07 PM

Sheet: 1/1