


PARTS LIST			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	1	PS20021	Z-Assembly Carriage
2	1	PS20028	Z-Axis Rail Assembly
3	1	PS20029	Spindle Carriage Assembly
4	4	25287-02	Flat Washer, M5
5	4	26016-01	M5 insertion nut
6	4	25286-01	M5 x 10mm, BHCS

DRAWN Edward		11/25/2013		<div>Project Shapeoko</div> <div>TITLE</div> <div>Complete Z-Axis Assembly</div>	
<div></div>		SIZE B		DWG NO PS20030	REV
		www.shapeoko.com			SHEET 1 OF 1