



PARTS LIST			
ITEM	QTY	PART NUMBER	DESCRIPTION
1	1	PS20021	Z-Assembly Carriage
2	1	PS20028	Z-Axis Rail Assembly
3	1	PS20029	Spindle Carriage Assembly
4	4	25287-02	Flat Washer, M5
5	4	26016-01	M5 insertion nut
6	4	25286-01	M5 x 10mm, BHCS

DRAWN Edward	11/25/2013	TITLE		
CHECKED				
QA				
MFG				
APPROVED		SIZE B	DWG NO PS20030	REV
		SCALE	SHEET 1 OF 1	