

V4.0 SHIELD / MASK  
WIRING (For VNH5019)

NOTE: Traces and Resistors can be mounted on TOP or BOTTOM of shield (between shield & Arduino MEGA).  
This illustration is showing all connections as viewed from TOP.

