




12V to 5V Buck




5V to 1.8V Buck




5V to 5V Buck




5V to 5V Buck




5V to 5V Buck




5V to 5V Buck




5V to 5V Buck




5V to 5V Buck




5V to 5V Buck








5V to 5V Buck




5V to 5V Buck









Motor 1 - V - A04





Motor 2 - V - A04



Motor 3 - Z - A04





High Power Heaters Control

