


This transistor, when USB is connected, avoid the Sysoff to be asserted and thus avoid the battery disconnection



This transistor is for measuring the battery level. You can enable (assert EN_SENS) and read the Vsens voltage with ADC. The delay must be higher than 10ms for let the capacitor charge.

