

Gold Standard Service Corp.**P.O. BOX 4831****Rancho Cucamonga, CA 91729**

gold-standard@hotmail.com

(877)313-3552 Of...



Invoice

Date: 6/13/2022**Invoice #** 36907**Work Order #** 36907**Bill To**Total Transportation & Distribution
210 East Lambert Road,
Fullerton, CA 92833**Ship To**210 E. Lambert Rd.
Fullerton, CA**P.O. #** LS210-B30-51520**Unit #** B30**Hour Meter:** 12797**Serial #** 32967**Terms:** Due on receipt**Due Date:** 6/13/2022**Ship Date** 6/2/2022 **Tech:** JR**Model:** Toyota8FGCU25

Description	Qty	Rate	Amount
Labor Special Rate Total Trans: Check overheating and check seat. Blow out radiator. Pickup new seat and install. Test OK	3	121.50	364.50
Seat vinyl w/switch	1	725.00	725.00T

Thank you for choosing Gold Standard Service for all your material handling needs.

Remit To: Gold Standard Service Corp.
P. O. Box 4831
Rancho Cucamonga, CA 91729

Subtotal	\$1,089.50
Sales Tax (9.5%)	\$68.88
Total	\$1,158.38
Payments/Credits	\$0.00
	\$1,158.38