




14 2D Laser

14.1 Mounting the 2D Laser

1. Unscrew the following four screws:



2. Mount the 2D Laser in the support:



3. Fix the support to the frame with the 4 screws you unscrewed in step 1:

