



- Bar

- Linear actuator line of action

From this, we see that no matter where on the bar we put the actuator, the angle between the bar and line of action is the same, so we should put actuator at the end of the bar to maximize moment

Use BSX LA since it can provide the highest max force

Use 140 cm to allow for some leeway