



Quotation: PQ202509-E08F4140

Quotation Date: 03/09/2025

Valid Until: 03/10/2025

client 1

0706707144, 121212, Nairobi
Direct Thermal Printers
Email: mburudominic63@gmail.com
Phone: +254706526569

client 1

0706707144
Phone: +254706526569
Email: mburudominic381@gmail.com
Website: http://localhost:5173/register

Project Description

- Entree (18.0m² walls, 8.0m² ceiling):

- One Coat: 17.9m² wall area

- Eetkamer (17.0m² walls, 6.0m² ceiling):

- Priming: 17.3m² wall area

- Woonkamer (51.0m² walls, 48.0m² ceiling):

- Priming: 48.3m² ceiling area

- Slaapkamer 1 (24.0m² walls, 10.0m² ceiling):

- Priming: 10.2m² ceiling area

- Interior Work:

• Doors: Door (Qty: 1)

- Condition: New/Pre-primed
- Unit Price: £75.00

• Preparation Steps:

1. Clean surface (dust and degrease with sugar soap)
2. Light sanding to key the surface
3. Prime if bare wood (skip if factory-primed and in good condition)
4. Apply topcoat

• Stairs: Stair (Qty: 1)

- Unit Price: £25.00

• Turnwindows: Turn Window (Qty: 1)

- Condition: Moderate Wear
- Unit Price: £55.00

• Preparation Steps:

1. Scrape away all loose/flaking paint
2. Sand surface to smooth out rough areas
3. Fill cracks or gouges with appropriate filler
4. Spot prime exposed wood
5. Final sand before painting
6. Apply topcoat

- Exterior Work:

• **Doors:** Door (Qty: 1)

- Condition: New/Pre-primed
- Unit Price: £150.00

• **Preparation Steps:**

1. Clean surface (dust and degrease with sugar soap)
2. Light sanding to key the surface
3. Prime if bare wood (skip if factory-primed and in good condition)
4. Apply topcoat

• **Dormerwindows:** Dormer Window (Qty: 1)

- Condition: Good Condition
- Unit Price: £120.00

• **Preparation Steps:**

1. Clean with sugar soap
2. Light sand to dull surface
3. Fill small dents or imperfections (if needed)
4. Spot prime glossy or bare areas
5. Apply topcoat

• **Rainpipe:** Rain Pipe (Qty: 1)

- Unit Price: £15.00

- Special Jobs & Conditions:

• **Fire/Smoke Damage:** Fire/Smoke Damage (Qty: 1 job)

- Unit Price: £200.00
- Total Cost: £200.00
- Materials included in price

• **Process Steps for Fire/Smoke Damage:**

1. Wash all surfaces with degreaser/sugar soap
2. Remove soot and smoke residue
3. Sand walls if surface is uneven
4. Apply stain- and odour-blocking primer
5. Repaint with high-opacity paint

• **Uneven Wall Surfaces:** Uneven Wall Surfaces (Qty: 1 job)

- Unit Price: £250.00
- Total Cost: £250.00
- Materials included in price

• **Process Steps for Uneven Wall Surfaces:**

1. Assess whether skimming is needed or just filler
2. Fill deep imperfections
3. Sand smooth
4. (Optional) Apply bonding agent
5. If badly uneven, apply full skim coat and allow to dry before painting

Summary Table

Quantity	Description	Amount (excl. VAT)
18.0	Entree - Walls - Painting (1 Coat)	EUR 107.58
17.0	Eetkamer - Walls - Priming	EUR 78.03
48.0	Woonkamer - Ceiling - Priming	EUR 265.59
Total excl. VAT		EUR 1397.31
VAT (20%)		EUR 279.46
Total incl. VAT		EUR 1676.77

Quantity	Description	Amount (excl. VAT)
10.0	Slaapkamer 1 - Ceiling - Priming	EUR 56.10
1.0	Interior - Door	EUR 75.00
1.0	Interior - Stair	EUR 25.00
1.0	Interior - Turn Window	EUR 55.00
1.0	Exterior - Door	EUR 150.00
1.0	Exterior - Dormer Window	EUR 120.00
1.0	Exterior - Rain Pipe	EUR 15.00
1.0	Special Job - Fire/Smoke Damage	EUR 200.00
1.0	Special Job - Uneven Wall Surfaces	EUR 250.00
Total excl. VAT		EUR 1397.31
VAT (20%)		EUR 279.46
Total incl. VAT		EUR 1676.77

The price includes all materials, labor, travel costs, and leaving the site clean.

This quotation is valid until 03/10/2025. Please return a signed copy if you wish to proceed.

Client Acceptance:

By signing below, I accept the terms and conditions of this quotation.

Digital Signature: _____

Date: _____

To sign digitally, please visit:

<http://localhost:5173/register/api/quotes/26/sign>