

Bill To:

Mr Sandesh

DESCRIPTION	QTY	UNIT COST	TOTAL
Wall Putty and Ceiling Repair of 2000 sq.ft Drrawing Room Area	-	35,000	35,000
4 Bathroom Tiles Grouting	-	4000	4000
Window Panel Work	-	12,000	12,000

SUB TOTAL= 51, 000

TAX @ 9%= 4590

TOTAL= 55, 590

It was great doing business with you.