

Test name

Peter Roth

June 25, 2021

**Requirement ids:**

- R123
- R456

**Test id:** 'afeefcc8-7de8-4dd7-94a6-a5571f3b1d17'

**Test\_function\_name:** test\_pulse\_output\_2

**Meter features:**

- pulses
- flow\_simulation

**Date\_changed:** 22.06.2021

**Changed\_by:** Robert Hirschmann

**Description:** This is a fancy description **Specification:**

- Preconditions:
  - Meter must be in production mode
  - Exception recorder must be empty
  - Volume accus must be set to zero
- Test\_steps:

#	Step description	Expected result
1	Set on the error Checksum by the irda command <b>TestCommand</b> with parameter <b>TestParameter</b> . After 60sec read error flag by the command <b>ReadFlag</b>	The error flag should include the error Checksum.
2	Set off the error Checksum by the irda command <b>TestCommand</b> with parameter <b>TestParameter</b> .	The error flag should be 00 00 00.

- **Postconditions:**

- Reset exception recorder
- Reset volume accus