




POWER&USB




MCU




XTAL



MCU




BOOT




排针不


LED




RST



KEY





SWD&UART



```
Switch Download Mode : Tx0 -
ARM Mode: Blue LED on
Risc Mode: Blue LED off
```

ARDUINO



POWER&USB

