

Date:09/01/2022 06:33AM

Post Scan

Vehicle Sysytem Report

Vehicle Information

MAKE Subaru
YEAR 2021
MODEL Outback
ENGINE 2.5L DOHC H4 MFI (U5)
SYSTEM CodeScan
BEN

CODE SCAN RESULTS

Systems Analyzed:24

- ✔ Engine: 0
- ✔ Transmission: 0
- ✔ Antilock Brakes: 0
- ✔ Airbag: 0
- ⚠ Air Conditioning: 1
- ✔ Automatic Headlight Leveling: 0
- ⚠ Back and Side Radar: 1
- ⚠ Back and Side Radar: 1
- ✔ Body Integration Unit: 0
- ✔ Central Gateway: 0
- ⚠ Cockpit Control: 3
- ⚠ Combination Meter: 1
- ✔ Electric Power Steering: 0
- ⚠ EyeSight: 2
- ✔ EyeSight Assist Monitor: 0
- ⚠ Front Relay Control Module: 3
- ⚠ Keyless Access with Push Button Start (Power Supply): 1
- ⚠ Keyless Access with Push Button Start (Collation): 1
- ⚠ Power Rear Gate: 1
- ✔ Power Window: 0
- ✔ Power Window: 0
- ✔ Power Window: 0
- ✔ Telematics: 0
- ⚠ Tire Pressure Monitor: 3
- ✔ OBDII Codes (\$03): 0

Air Conditioning

B14A1 | Sunload Sensor Circuit Open - Current Fault.

Back and Side Radar

B2320 | Rear Radar Low Voltage (less than 9V) - History Fault, History Fault.

Back and Side Radar

B2320 | Rear Radar Low Voltage (less than 9V) - History Fault, History Fault.

Cockpit Control

B2259 | Center Information Display Communication Open - History Fault.
U0128 | Lost Communication with Park Brake Control Module - History Fault.
B2241 | CAN Communication - History Fault.

Combination Meter

B1509 | Flash To Pass Switch Circuit Short To Battery - History Fault.

EyeSight

P2C00 | Refer to OEM repair information for code description
P3100 | Refer to OEM repair information for code description

Front Relay Control Module

B1A00 | Front Relay Control Module Non-Volatile Memory - Current Fault, History Fault.
B1A01 | Front Relay Control Module Battery (Control) Power Supply - History Fault.
B1A02 | Front Relay Control Module Battery (Back Up) Power Supply - History Fault.

Keyless Access with Push Button Start (Power Supply)

B227C | Park Range Signal Performance - History Fault.

Keyless Access with Push Button Start (Collation)

B2793 | Backup Power - History Fault.

Power Rear Gate

B2500 | Power Supply Voltage Malfunction - History Fault.

Tire Pressure Monitor

C2021 | Tire 1 Air Pressure Decrease Normal Mode - History Fault.
C2022 | Tire 2 Air Pressure Decrease Normal Mode - History Fault.
C2023 | Tire 3 Air Pressure Decrease Normal Mode - History Fault.

Readiness Monitors

Tests Complete

- ✔ Misfire
- ✔ Fuel System
- ✔ Comprehensive Component
- ✔ EGR/VVT
- ✔ Catalyst
- ✔ Evaporative System
- ✔ Oxygen Sensor
- ✔ Oxygen Sensor Heater