





1. Table of Contents (This Page)  
Created on Sat Feb 2 14:04:14 2013


- 2. component
- 3. solder
- 4. outline
- 5. plated-drill
- 6. componentmask
- 7. soldermask
- 8. topsilk
- 9. bottomsilk
- 10. toppaste
- 11. topassembly
- 12. bottomassembly
- 13. fab
































There are 7 different drill sizes used in this layout, 112 holes total

| Symbol | Diam. (Inch) | Count | Plated? |   |
|--------|--------------|-------|---------|---|
| γ      | 0.020        | 22    | YES     |   |
| +      | 0.024        | 5     | YES     |   |
| ×      | 0.030        | 6     | YES     |   |
| •      | 0.038        | 61    | YES     | Title: (unknown) - Fabrication Drawing    |
| □      | 0.048        | 12    | YES     | Author: Michael Petersen                  |
| ▽      | 0.128        | 2     | YES     | Date: Sat 02 Feb 2013 09:04:14 PM GMT UTC |
| ⊕      | 0.129        | 4     | YES     |   |



Board outline is the centerline of this path