





1. Table of Contents (This Page)
Created on Wed Mar 30 13:58:56 2016


- 2. component
- 3. solder
- 4. outline
- 5. plated-drill
- 6. componentmask
- 7. soldermask
- 8. topsilk
- 9. bottomsilk
- 10. toppaste
- 11. topassembly
- 12. bottomassembly
- 13. fab

































There are 6 different drill sizes used in this layout, 95 holes total

Symbol	Diam. (Inch)	Count	Plated?
Y	0.020	41	YES
+	0.030	6	YES
x	0.038	32	YES
o	0.048	10	YES
□	0.128	2	YES
▽	0.129	4	YES

Title: (unknown) - Fabrication Drawing
Author: Nathan D. Holmes
Date: Wed 30 Mar 2016 07:58:56 PM GMT UTC



Board outline is the centerline of this path